GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/27 85

Dated: 15 / 10/12

FIRE SAFETY CERTIFICATE

Certified that the Jyoti Mahal Guest House located at 2488-90 & 1507, Nalwa Gali and Ranjit Gali, Pahar Ganj, New Delhi-110055 comprised of basement (storage), ground floor (reception + lobby + office + 04 guest rooms), 1st floor (09 guest rooms), 2nd floor to 3rd floor (10 guest rooms at each floor) and terrace floor (staff canteen sealed by MCD), total 33 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2705 dated 03-09-2009. The premises was re-inspected by the officer concerned of this department on 08-10-2012 in the presence of Sh. Pardeep Singh Sahni (partner) and found the building is comprised of basement (storage), ground floor (reception + lobby + office + 01 hall + 04 guest rooms), 1st floor (11 guest rooms + 01 store), 2nd floor to 3rd floor (12 guest rooms + 01 store) and terrace floor (mumty, generator room, water tank & open terrace), total 39 guest rooms and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi–110049 w.r.t. No.49484-86/Addl.C.P./Lic.(H) New Delhi dated 14-08-12
- 2. M/s Jyoti Mahal Guest House, 2488-90, Nalwa Gali, Pahar Ganj, New Delhi-110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

MIS

	1. Name & address of the building: Ranjit gali, Pahag Ganj, New Dellie-						
	2488-90, & 1507, Nalwa galle and						
	1. Name & address of the building: Ranjit gale, Pahar Ganj, New Dellie-						
	Loageng House						
	3. Type of Case New Case/ Renewal / Addition of Booms 4. Details of previous NOC Letter No. FG/DFS/M-S/GH/2009/2705 5. Fire Safety directives letter No: NIL Only Date of inspection						
	$\begin{array}{cccccccccccccccccccccccccccccccccccc$						
	7. Name of the Inspecting Officers: DROSM vis single yadow (ADO).						
from the building side Series Passer Sinch continued to the side of the side							
-	10. Applicant's letter No.	: 49484	1-86/Adde-c-P/lic	(4) doted new pells	He 14/8/12.		
	S. Minimum Standard	ls on fire	NBC/BBL	Provided at site	Remarks		
IN	No. prevention and fire sa	fety U/R 33	Requirement		MR/NMR		
1	Access to building	Access to building			PSS Area		
	 Road width 		-NA-	06 Mt88	M-R		
	Gate width		- N.A -				
	• Width of internal re	oad	-N.A -				
2	Number, Width, Type &						
	a. Number of staircases						
	 Upper Floors 		Two	Two.	M.R		
	• Basements		one	Two	MR		
	b. Width of staircases						
	 Upper Floors 		O Ca note	Main = 1.25 M	9.8		
	• Basements		0.80 Mts	Altegrate - 1-28 M	to M.R		
	c. Protection of exits		0 .80 MCE	Alterate 0-78M	M.R		
	Fire check door						
	Pressurization		-NA-				
		e. No. of continuous staircases to terrace			- · · · · · · · · · · · · · · · · · · ·		
	*	ases to terrace	one	Two	M.R.		
	g. Width of Corridor	A STATE OF THE STA	-N.A -	02-60Mtss	M.R		
	h. Door Size	4	-N.A	220 CM 8 X 88 CM 8	m.R		

contd:

Tyote makal Greet House. 2488-90, & 1507, Nalwa gali & Ranjit gali, Pakar Grand, New Delli-Compartmentation. 3 - N.A-Fire check door -N.A -Sealing of electrical shafts - N.A -Fire Rating of shaft door -N.A -Water Curtain -N.A -Fire Dampers Smoke Management System. 4 30 a/c per hour vating al ventilation M.R. Basements 12 a/c per hour Upper floors Fire Extinguishers 5 M.R 18 NOS Total numbers M.R Types M.R. ISI marked IS marking First-Aid Hose Reels. 6 M.R TWO TWO Total numbers on each floor Provided. 30 m Length of hose reel hose Provided-5 mm Nozzle diameter Automatic fire detection and alarming system. 7 -N.A -Type of detectors -NA -Location of Main Panel - N.A -Location of Repeater Panel - N.A -Alternate source of power N.A-Hooters' Location M.R Provided yes MR 8 **MOEFA** Provided. Public Address System. 9 Automatic Sprinkler System. 10 M.R Provided Yes Basement

Tyote makal quest pouse, 2488-90, £ 1507, Nolwa gale and All Rangiti gale, Pakas Gant New Delli-11005 -N.A -Upper Floor Sprinkler above false ceiling 11 Internal Hydrants Size of riser/down-comer Number of hydrants per floor -NA -Hose Box - NA -12 Yard Hydrants. Total number of hydrants - NA -- NA -Hose Box 13 Pumping Arrangements. Ground Level -NA-Discharge of main Pump -N.A -Head of Main pump -N.A -Number of main pumps - N.A -Jockey Pump out put - N.A -Jockey pump head - Noff -Standby Pump out put N.A -Standby Pump Head -NA -> Auto Starting/ Manual stopping Pump House Access - N.A -Terrace level 450LPM 450 LPM 30Mtes 30Mtes Discharge of pump Head of the pump Electricity Power Supply Auto Starting of pump Captive Water Storage for fire fighting. 14 N.A -Underground tank capacity N.A. Draw-off connection

conto-

14/8

Tyoti makal quest House, 2488-90 & 150+, Nalwa steed & Ranjit sali Pakar Grans, New ASD-

	10.000		110033	- Da
*_ i	> Fire service inlet	yes	porided	M.R
	Access to tank	yes	Provided	M.R.
	Overhead Tank capacity	5000 liter	8 5000 lites	m·R
15	Exit Signage.	yes:	Provided-	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	-N.A-	- e e	
	Pressurization of Lift lobby	-N.A -		
	Communication In lift Car	-N.A -		
	• Fireman's Grounding Switch	-N.A -		a a
	• Lift Signage	-NA -		
17	Standby power supply	yes	DG Set	M.R.
18				
	> Total Area	-NA-		
	> Location	-N.A -		
19 Fire Control Room				
	Detector System Panel	-N.A -		
	Flow Switch Panel	- N.A -		
	PA System Panel	-NA-		
	Batter backup	- N.A -		
2	Building Floor Plans	-NA-	6 Y	2
20	Special Fire Protection Systems for	-NA-	9.0	
i le	Protection of special Risks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

contdi-

Jyote makal guest 2488-90 & 1507 Ranjit gali, Pakal New Delli-11	valua zall t
Signature of the Inspecting Officer	Signature of the Inspecting Officer
Name	Name Dharm vie singh yadau
Designation	Designation Asth. Divisional
Do (conteal) Submitted plea	se. Officel (centeral)