## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 3822

Dated: 17/16/12

## **FIRE SAFETY CERTIFICATE**

Certified that the Sefali Deluxe Guest House, 2993/2, Chuna Mandi, Street No. 2,Pahar Ganj, New Delhi-110055 comprised of ground floor (Shops and others), 1<sup>st</sup> floor (03 guest rooms + reception), 2<sup>nd</sup> floor to 3<sup>rd</sup> floor (05 guest rooms at each floor), 4<sup>th</sup> floor (rooms sealed by MCD), total 13 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2691 dated 03-09-2009. The premises was re-inspected by the officer concerned of this department on 27-09-2012 in the presence of Sh. Umesh Sharma (manager) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 13 guest rooms with effect from 1.1.2.1.1.2.1.2.2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .1.7./19/12. at New Delhi by.

Chief Fire Officer Delhi Fire Service

## Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony New Delhi–110049 w.r.t. letter No.31965/Addl.C.P./Lic.(H) New Delhi dated 31-05-12
- 2. M/s Sefali Deluxe Guest House, 2993/2, Chuna Mandi, Street No. 2, Pahar Ganj, New Delhi- 110055.

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	a way the state of			
	INSPECTI	UN REPORT	quest House,	2993/2 2, Palas Gang w Dello-1100055.
V .	Name & address of the building Cha:	na mandé,	street No. 2	w sells-110055.
1	S	c house.	1970 A MATERIAL SACRAGE COMMAND ON A ST O	
- 1	7	c/ Renewal		
-1			164/2 Dolovi	03-09-2009.
5.	Fire Safety directives letter No : -	NA -	1 GH/2009 / Dated	64 S0 S0 S S S S S S
Ō.	Flate of Co.	27-09-2012	2	
7.	Name of the Inspecting Officers	Dharm vie si	ist nadau.	
8	Name and designation of officers		Jacan	
		Eli Umesh .	shasma (man	agel)
9.		2001 (stærten		
10	Applicant's letter No.	112 dates	03-09-12	old case
	Minimum Standards on fire	112	Previded at site	0 10
(1).	prevention and fire safety U/R 33	Requirement	4	MRAMIR
	Access to building		Lagran Residence and an array of the same	to a second to a
	<ul> <li>Road width</li> </ul>	-N.A-	04 Mtz offe	e. M.R.
	• Gate width	Administração Constituto Managares de 186 (1966 (1974) de 1975 (1975) de 1975 (19		
	<ul> <li>Width of internal road</li> </ul>	N.A		
		-N.A-		
	Number, Width, Type & Arrangement (	of Exits	The second secon	. 8 
	a. Number of staircases	No.		
	Upper Floors	one	one	ns. R
	• Basements	-N.A -		
	b Width of staircases		es (Victorial Care)	
	* Upper Floors	0.80 mts	G.F. 6 F.F. 80 C FF10 Te88000 1)	M. R
	* Basements	-N.A -	, , , , , , , , , , , , , , , , , , ,	
	c. Protection of exits		10 1000 00 1000 01 1 1 1 1 1 1 1	
	• Fire check door	-N.A -		1
	· Pressurization	- N.A -		
	c. No. of continuous staircases to terrace	one	one	M.R.
	g. Width of Corridor	-N.A-		
	h. Door Size	-N.A		
	The second distribution of the second distribution and the		The state of the s	

contd:-

Sefali Deluxe Guest House, 2993/2, chena mandi, steet No. 2, pakas Grant, New Delhi-

	A CONTRACTOR OF THE CONTRACTOR				,
	* Fire check door	000			
	• Sealing of electrical shafts	-N.A -		· · · · · · · · · · · · · · · · · · ·	
	Fire Rating of shaft door				
- desperation	* Water Curtain	-N.A -		manus malanana salahan salah sal	
. 2010 Mar (1844) - Mil	Fire Dampers	- NA -			
-		- Not -		- Committee of the state of the	1
- 311	10ke Management System.				
Amazina and a	<ul><li>Basements</li><li>Upper floors</li></ul>	30 a/c per hour	- N.A - Natural venti la	fin u.R	
	• Opper Hoors	12 a/c per hour	Natural venue la		
Fi	re Extinguishers			A STATE OF THE PROPERTY OF THE	
	Total numbers	08 NOG.	08 NG.	M·R	
	• Types		ABC Type &	M.R.	
Andrew Comments of Address of	IS marking	ISI marked	ABI Type & pyce Provided.	M.R	
F	irst-Aid Hose Reels.				
	• Total numbers on each floor	one	one	M.R	
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided.	M.R.	
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided.	n.R.	
7 A	Automatic fire detection and alarmin	ig systein.		Les of Anthonorman and Anthony and	s sedi
	• Type of detectors	-MA-			
	• Location of Main Panel	- N.A -			
-	• Location of Repeater Panel	NA -		2	
	Alternate source of power	N.A			
	Hooters' Location				MIN I -
	- Moders Docation	-N.A -			
8	MOERA ?	- N. A -			A 4 A 4 A
9	Public Address System.	Jeg.	provided	M.R	Name of the least
10	Automatic Sprinkler System.				
	• Basement	-NA-		CO	

· Eine			
	- N.A -		THE RESERVE NAMED IN
	- N.A -		The second secon
States, days a resident and a state of the s		2500 lotges	M.R
	Yes	Provided.	M.R
Provision of Lifts.			the age places and produce that the a sector for blackers we
Pressurization of Lift Shaft	- N.A -		Statement Statement Statement
<ul> <li>Pressurization of Lift lobby</li> </ul>	- N.A -		
* Communication In lift Car	- N.A -		
Fireman's Grounding Switch			
* Lift Signage	-N.A -		
Standby power supply	sel.	DG. Set	M.R
Refuge Area.			
> Total Area	- NA -		
> Location	-N.A -		
Fire Control Room			
Detector System Panel	-N.A -		
<ul> <li>Flow Switch Panel</li> </ul>	- N.A -		
<ul> <li>PA System Panel</li> </ul>	-N.A		
<ul> <li>Batter backup</li> </ul>	-N-A -		
Building Floor Plans	-N.A.		A Mariante China and a St. Marian promote Particular and State Adminis
Special Fire:Protection Systems for Protection of special Risks, if any:	NA-		
	Communication In lift Car Fireman's Grounding Switch Lift Signage  Standby power supply  Refuge Area.  Total Area Location  Fire Control Room  Detector System Panel Flow Switch Panel PAI System Panel Batter backup Building Floor Plans  Special Fire Protection Systems for	* Access to tank  • Overhead Tank capacity  Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft  • Pressurization of Lift lobby  • Communication In lift Car  • Fireman's Grounding Switch  • Lift Signage  Standby power supply  Refuge Area.  Total Area  • Location  Fire Control Room  • Detector System Panel  • PAI System Panel  • PAI System Panel  • Building Floor Plans  Special Fire Protection Systems for	Access to tank Overhead Tank capacity  Exit Signage.  Provision of Lifts.  Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage  NA  Standby power supply Refuge Area.  Total Area Location Fire Control Room  Detector System Panel PASystem Panel Batter backup Building Floor Plans  Special Fire Protection Systems for

The fire protection systems provided in the building were test checked and found functional at the time imspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi see Service Rules 2010/ issue shortcomings as noted at serial numbers.

sefale Deliexe Greet Base, 2993/2 Chiens mænde, steet no 2, fallol Gang new Alde-

<ul><li>Upper Floor</li><li>Sprinkler above false ceiling</li></ul>	ту — N.A — — — — — — — — — — — — — — — — — — —		
11 Internal Hydrants	-N.A -		
	NA ASSESSMENT ASSESSMENT ASSESSMENT OF THE PROPERTY OF THE PRO		
• Size of riser/down-comer	- NA -	May be a subsequence of the subs	The state of the s
<ul> <li>Number of hydrants per flo</li> <li>Hose Box</li> </ul>	-N.A -	THE PERSON OF TH	
	-N.A -		
Yard Hydrauts.		AND THE RESIDENCE OF TH	Y .
<ul> <li>Total number of hydrants</li> </ul>	4/0		
* Hose Box	-N.A -		
Pumping Arrangements.	-N.A-	4	
		And the state of t	
Ground Level	-NA-		
Discharge of main Pun	IP -NA-		
Head of Main pump	-NA - -NA -		
Number of main pump	s -N.A		
Jockey Pump out put	-N.A -		
> Jockey pump head	Manager - Million of Malan - Applicant - 1 to 100 and		
> Standby Pump out put	- N.A -		
Standby Pump Head	- N.A -		
> Auto Starting/ Manual	- N.A -		
stopping	- N.A -		
Pump House Access		•	, e ge
• Terra e level	N.A.		
> Lischarge of pump	1801BM	180 L P.M	M.R.
· Head of the pump	30 mtes	30 mtgg	MR MAN
Power Supply	Recticity	Blecticity.	MR
Auto Starting of pump		switch provide	al . D
Captive Water Storage for fire f		at shound flo	E. M.K.
• Underground tank capacity	Statement of annual contract of the statement of the stat	-	
> Draw-off connection			
on connection	- N.A -	THE RESIDENCE OF THE PROPERTY AND THE PROPERTY OF THE PROPERTY	

contd:

sefali polaxe conet pouce, 2993/2, chune mardi, steet 102, Palae Gent New Delli-11055 Signature of the Inspecting Officer Signature of the Inspecting Officer Name Name Drasm vie eingh yadou Designation Accistant Divisional office (certeal) Submitted please.