GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No.F.6/DFS/MS/School/2012/ 3944

Dated: 23/10/12

FIRE SAFETY CERTIFICATE

Certified that the building of Colonel Child Bloom School located at Naveen Palace, Kali Piou, C.R.P.F, Jharoda Road, Najafgarh, New Delhi-110072 comprised of ground floor plus one upper floor, having total 22 rooms (Including Class Rooms, Office, Comp. Room, Sci. Lab, Library, Staff Room & Store etc.) was issued NOC by this department vide letter No.F.6/MS/DFS/2006/1421 dated 29.06.2006. building was re- inspected by the officer concerned of this department on 06.10.2012 in the presence of Smt. Anita Sherawat (Principal) and found that the school management have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Lecuad	on	23	10	12	at Nam Dalla!
Issuea	on		1.		at New Delhi.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

1. The Principal, Colonel Child Bloom School, Naveen Palace, Kali Piou, C.R.P.F, Jharoda Road, Najaf Garh, New Delhi-110072.

2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

		· · · · · · · · · · · · · · · · · · ·	f. 9	
S.	INSPECT	TION REPORT	A	
	1. Name & address of the building:	Colonel Child R	Bloom School, Nave	en Palace Kali Piou Th
		Educational (Rd, Naja + Gam, N.D-7
		: N ew Case /Re		
	4. Details of Previous NOC	: Letter No. F. 6	MS/DFS/2006/14.	<u> 21 Dated 29.06.2</u>
	5. Fire Safety directives letter No:		IA	
	6. Date of inspection	: 06,10.		
	7. Name of Inspecting Officer	: A. D.O P. S.	Dahiya	
	8. Name and designation of office	rs	. 01	
	From the building side	: Sh. Hhit	ta Sehrowat (P	sincipal)
	9. Year of Construction	Before 200		5
C	10. Applicant's letter No.	: Nil dated		
S. No.	Minimum Standards on fire prevention	Dir. Of Edu.	Provided at site	Remarks
140.	and fire safety U/R 33	Circular dt.		MR/NMR
1.	Access to building	01.03.2011		
1.	Road width	Accessible	Obmtr	Da 0
	Gate width	Precession	06 mtr	MR
	Width of internal road	-	-	
2.	Number, Width, Type & Arrangement of	E-:4-		-
4.	a. Number of staircases	EXITS		
	Upper Floors			
	Basements	700	Two	mR
	• basements	-		No Basement
	b. Width of staircases			
	Upper Floor		1 Socms, 10 Scms	MR
	Basements		,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	No Basement
	c. Protection of exits			No Dupement
	Fire check door			
	pressurization	NIA		•
	p. seed. Editor	NIA	-	
	d. No. of continuous staircases to		8 4	10
	terrace	•	One	
	e. Width of Corridor	_		
	f. Door Size			
			-	Old Cape
3.	Compartmentation			× ×
	Fire check door	NIA		
	Sealing of electrical shafts	NIA	,	
	Fire Rating of shaft door			
	Water Curtain	NA		•
	Fire Dampers	N/A		•
4.	Smoke Management System	N/A	8	
	Basements	30 a/c per hour	T	
	4.	Jo are per nour		No Basement
	Upper floors		Natural Ventilation	
				MR

				-
		12 a/c per hour	*	
5.	Fire Extinguishers			
	Total numbersTypesIS marking	O6 Nos ABC, DCP	Provided - do-	MR
6.	First-Aid Hose Reels	ISI marked	151 marked	MR
7.	 Total numbers on each floor Length of hose reel hose Nozzle diameter Automatic fire detection and alarming	N/R 30 m 5 mm	Provided - do do: -	MR
h managari kanamata a salah managari	Type of detectors	NIA		
	 Location of Main Panel Location of Repeater Panel Alternate source of power Hooters' Location 	N/A N/A		
8.	MOEFA		In Staircase	-
9.	Public Address System	MA		-
10.	Automatic Sprinkler System	N/A	Provided	MR
	BasementUpper FloorSprinkler above false ceiling	N/A		No Basement
11.	Internal Hydrants	NIA		
12.	 Size of riser/down-comer Number of hydrants per floor Hose Box Yard Hydrants 	N/A N/A N/A		8
Committee of the Committee of the Arms (Arms) and (Arms)	 Total number of hydrants 	Allo	, j.	
	* Hose Box	NA		
13.	Pumping Arrangements	I IVIT		
	 Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put 	NIA NIA NIA NIA		
	> Standby Pump Head	N/A		-
	Auto Starting/Manual	MIA	-	_
	stopping	NIA		-

Naveen Palace, Kali Paou, C.R.P.F., Tharoda Road, Najaffarh, New Delki-72.

	> Pump House Access	NIA	_	_	
	Terrace levelDischarge of pump	4110	10-10-	h - C	
	Head of the pumpPower Supply	NIA	180 LPM	MR	
		NIA	30 M	MR	
	Auto Starting of pump	-	- 1	-	
14.	Captive Water Storage for fire fighting		3		
+ 3	Underground tank capacity	NIA	8 2	-	
	Draw-off connection	NIA	Tests - to		
	Fire service inlet	NIA	· / , · · · · · · · · · · · · · · · · ·		
	Access to tank	NIA	F		
	 Overhead Tank capacity 	NIA	2500ltr	MR	
15.	Exit Signage.	MA	Provided	mR	
16.	Provision of Lifts.				
	Pressurization of Lift Shaft	•	10	No Cift	
	 Pressurization of Lift lobby 			-do -	
	Communication In lift Car			_do -	
	 Fireman's Grounding Switch 	_	•	-do -	
	 Lift Signage 			-do -	
	,			-110	
17.	Standby power supply	NIA	_		
18.	Refuge Area.				
	Total Area	NIA	8 gr		
	Location	NIA			
19.	Fire Control Room			Y Y	
	Detector System Panel	NIA			
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	NIA			
		NIA			
		NIA			
		MA			
20.	Special Fire Protection System for Protection of special Risks, if any:	NIA			

M

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

The state of the s

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Note: The school building comprised of Ground floor plus One upper floor. The lepper floor is served by two staircases having width 150 cms & 105 cms respectively. There are total 22 Rooms including Class Rooms, Office, Sci Lab, Staff Room, Comp. Room & Store etc. In each class students less than 45.

Signature of Inspecting Officer

Name P.S. Dahiya

Designation ABBH. Divisional Officer

Signature of Inspecting Officer

Name

Designation

AD OCWI