GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI-110001**

No. F6/MS/DFS/GH/2012/ 4163

Dated: 07/11/12

FIRE SAFETY CERTIFICATE

Certified that the India Continental Guest House, 9143/3, Multani Dhanda, Pahar Ganj, New Delhi-110055 comprised of ground floor (03 guest rooms + reception + office + 01 store rooms), mezzanine floor (02 guest rooms), 1st floor to 3rd floor (04 guest rooms at each floor), 4th floor (01 guest room + 01 staff room), total 18 guest rooms, was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2023 dated 08-07-2009. The premises was re-inspected by the officer concerned of this department on 26-10-2012 in the presence of Mr. Sanjeev Kumar (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued . o 6/11./12 at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- by to :
 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony New Delhi-110049 w.r.t. letter No.28308/Addl.C.P./Lic.(H) New Delhi dated 11-05-
- 2. M/s India Continental Guest House, 9143/3, Multani Dhanda, Pahar Ganj, New Delhi- 110055.
- 3. Dy. Commissioner MCD, Sadar Pahar Ganj Zone, Idgah Road, New Delhi with a request to verify the height of the building under intimation to this department.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

India Continental Guest House, 9143/3, Multani Dhanda, Pahar Ganj, New Delhi-110055

INSPECTION REPORT

1. Name & address of the building : India Continental Guest House, 9143/3, Multani Dhanda, Pahar

Ganj, New Delhi-110055

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : Letter No. No.F6/DFS/MS/GH/2009/2023dated 98-07-2009

5. Fire Safety directives Letter No. : N/A

6. Date of inspection : 26-10-2012

7. Name of the Inspecting Officer : Sh. D.S. Yadav (A.D.O.)

8. Name and designation of Officer

from the building side : Mr. Sanjeev Kumar (owner)

9. Year of Construction : 2001 Starting Year

10. Applicant's letter No. : 28308/Addl.C.P./Lic.(H) dated New Delhi the 11-05-2012

CNI	I Minimum to the control of the cont	DDI	D '1 1 . '	D 1 1/	DANAD	
S No	Minimum standards on fire prevention	BBL	Provided at site	Remarks MR/NMR		11.
1	and fire safety U/R 33	Requirements	(PSS Area)	(Old Case	Old Case) PSS Alson	
1.	Access of building	T 37/4				
	Road width	N/A	6 mtrs. Approx.			
	Gate width	N/A	N/A		N/A	
	Width of internal road	N/A	N/A	N/A		
2.	Number, width, Type & Arrangements of	of exits				
	a. Number of staircases			V		
	• Upper floors .	01	01	MR		
	• Basements	N/A	N/A	N/A		
	b. Width of staircases		Annual Control of the			
1	 Upper floors 	80 cms	125 cms to 130 cms.	s. MR		V
	• Basements	N/A	N/A	1	N/A	
	c. Protection of exits					
	Fire check door	N/A	N/A	N/	A	
	 Pressurization 	N/A	N/A	N	/A	
	d. No of continuous staircase to terrace	01	01	MF	?	
	e. Width Of Corridor	N/A	N/A	N/	A	
	f. Door Size	N/A	N/A	N/	A	
3.	Compartmentation					
	 Fire check door 	N/A	N/A	N	/A	
	 Sealing of electrical shafts 	N/A	N/A	N	/A	
	 Fire Rating of shaft door 	N/A	N/A	N	/A	
	Water Curtain	N/A	N/A	N	/A	
	Fire Dampers	N/A	N/A	N	/A	
4.	Smoke managements System					
	Basements	30 a/c per hour	N/A	1	V/A	
	 Upper floors 	12 a/c per hour	Natural ventilation	I	MR	
5.	Fire Extinguishers	3 16				

contel.

older

	ndia Continental Guest House, 9143/3, 1 Total numbers	12	12	MR	
	100.000.0000.0000.0000.0000.0000.0000.0000		Water Co2 &	MR	
	• Types		A.B.C. type.		
	IS marking	ISI marked	Provided	MR	
2	First – Aid Hose Reels				
	Total numbers on each floor	01	01	MR	
	 Length of hose reel hose 	30 M	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
	Automatic fire detection and alarming sy				
	T 0.1	N/A	N/A	N/A	
	CM - D	N/A	N/A	N/A	
	r .: CDD	N/A	N/A	N/A	
	-	N/A	N/A	N/A	
	Alternate source of powerHooters' Location	N/A	N/A	N/A	
		N/A	N/A	N/A	
	MOEFA	Yes	Provided	M/R	
·	Public Address System/Intercom system	1 68	Flovided	141/1	
).	Automatic Sprinkler System	N/A	N/A	N/A	
	Basements	N/A N/A	N/A N/A	N/A	
	• Upper Floor		N/A	N/A	
	Sprinkler above false ceiling	N/A	1N/A	11//1	
1.	Internal Hydrants	21/4	NI/A	NI/A	
	Size of riser/down- comer	N/A	N/A	N/A N/A	
	 Number of hydrants per floor 	N/A	N/A	N/A N/A	
	Hose Box	N/A	N/A	IN/A	
2	Yard Hydrants			27/4	
	 Total number of hydrants 	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
3.	Pumping Arrangements	_			
	Ground Level				15
	 Discharge of main pump 	N/A	N/A	N/A	
	Head of main pump	N/A	N/A	N/A	
	Number of main pumps	N/A	N/A	N/A	
	Jockey pump out put	N/A	N/A	N/A	9-
	Jockey pump head	N/A	N/A	N/A	
	Standby Pump out put	N/A	N/A	N/A	
	> Standby Pump Head	N/A	N/A	N/A	
	auto Staring/Manual stopping	N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	Terrace level				
	Discharge of pump	450 LPM	450 LPM	MR	
	Head of the pump	30 Mtrs.	30 Mtrs.	MR	
	Power supply	Electric	Electric	MR	
	➤ Auto starting of pump		Switch provided at reception	MR	
14.	Captive water Storage for fire fighting				
	Under ground tank capacity	N/A	N/A	N/A	
	Draw of connection	N/A	N/A	N/A	
	Fire service inlet	N/A	N/A	N/A	
	Access to tank	N/A	N/A	N/A	
	 Overhead Tank capacity 	2500 Ltrs.	2500 Ltrs.	MR	V
5	Exit Signage	Yes	Provided	MR	
16.	Provision of Lifts			N/A (
	Pressurization of Lift Shaft	N/A	N/A	N/A	

contd:

India Continental Guest House, 9143/3, Multani Dhanda, Pahar Gani, N

	Programing Clark, 1743/3, Multani Dhanda, Pahar Ganj, New Delhi-110055					
7	riessurization of lift lobby	N/A	N/A	N/A		
	Communication in lift Car	N/A	N/A	N/A		
	Fireman's Grounding Switch	N/A	N/A	N/A		
1.5	➤ Lift Signage	N/A	N/A	N/A		
17.	Standby power supply	YES	D.G. Set			
18. Refuge Area		D.O. 3Cl	MR			
	Total areaLocation	N/A	N/A	N/A		
19.	Fire control room	N/A	N/A	N/A		
 Detector system panel Flow Switch Panel PA System Panel 	Detector system panel	N/A	N/A	N/A		
		N/A	N/A	N/A		
	Batter backup	N/A	N/A	N/A		
	Building Floor Plans	N/A	N/A	N/A		
20.		N/A	N/A	N/A		
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A		

The fire protection systems provided in the building were test checked and found functional at the time of

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name D. S. yadav Designation ADO (C.D)

Submitted please.