## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 4166

Dated: 06/11/12

# FIRE SAFETY CERTIFICATE

Certified that the Monika Guest House, 3427, D.B.G. Road, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 03 guest rooms), 1<sup>st</sup> floor (04 guest rooms), 2<sup>nd</sup> (05 guest rooms + 01 store), total 12 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2455 dated 08-08-2009. The premises was re-inspected by the officer concerned of this department on 19-10-2012 in the presence of Mr. Manohar Lal (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 12 guest rooms with effect from ...o.6/11./....2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 9.6/11/12... at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

### Copy to:-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi–110049 wrt No.28585/Addl.C.P./Lic.(H) New Delhi dated 14-05-12
- 2. M/s Monika Guest House, 3427, D.B.G. Road, Pahar Ganj, New Delhi-110055

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

#### **INSPECTION REPORT**

1. Name & address of the building: Monika Guest House, 3427, D.B. G. Road, Pohor

Ganj, New Delhi - 110055

2. Type of Occupancy : Lo

: Lodging House

3. Type of Case

Renewal

4. Details of previous NOC

Letter No. F6/DFS/MS/GH/2009.../2445.. Dated .08-08-2009

5. Fire Safety directives Letter No.

N/A

6. Date of inspection

/ /2012

7. Name of the Inspecting Officer

Sh. D.S. Yadav

(A.D.O.)

8. Name and designation of Officer

from the building side

Sh. Manohar (al (owner)

9. Year of Construction

: ...19.81..... Starting Year

10. Applicant's letter No.

28585../Addl.C.P./Lic.(H) dated New Delhi the 14-5-12.

contd:

S No	Minimum standards on fire prevention	BBL		Remarks MR/NMR		
	and fire safety U/R 33	Requirements	(PSS Area)	(Old Case) P.S.S. Alex		
1.	Access of building					
	Road width	N/A	Morethen 6 Mts.	MR		
	Gate width	N/A	N/A	N/A		
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A		
2.	Number, width, Type & Arrangements of exits					
	a. Number of staircases					
	<ul> <li>Upper floors</li> </ul>	01	01	MR		
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A		
	b. Width of staircases			> vi , id.,		
	<ul> <li>Upper floors</li> </ul>	80 cms	81 cms to 88 Cm	MR		
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A		
	c. Protection of exits					
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A		
	d. No of continuous staircase to terrace	01	01	MR		
	e. Width Of Corridor	N/A	N/A	N/A		
	f. Door Size	N/A	N/A	N/A		
3.	Compartmentation					
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A		
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A	N/A		
	Water Curtain	N/A	N/A	N/A		
	Fire Dampers	N/A	N/A	N/A		
4.	Smoke managements System					
	Basements	30 a/c per hour		N/A		
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour	Natural ventilation	MR		

Monika Guest House, 3427, D.B.C. Road, Pahar Gany, New Delhi-110055

old case
Des No.

				PSS ASI
	Fire Extinguishers	la.	10	MR
	<ul><li>Total numbers</li><li>Types</li></ul>		Water Co2 &	MR
		101	A.B.C. type.	MR
	IS marking	ISI marked	Provided	IAIIA
	First – Aid Hose Reels	,		MA
	<ul> <li>Total numbers on each floor</li> </ul>	NA	NIA	NA
	<ul> <li>Length of hose reel hose</li> </ul>	30 M	NA	
	Nozzle diameter	5 mm	N/A	NIA
	Automatic fire detection and alarming sy	stem		N/A
	<ul> <li>Type of detectors</li> </ul>	N/A	N/A	N/A N/A
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A N/A
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A N/A
	Alternate source of power	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A
	MOEFA	MA	MA	HA
	Public Address System	Yes	Provided	MR
).	Automatic Sprinkler System			
-	Basements			X 1 / A
	Upper Floor	N/A	N/A	N/A
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A
1.	Internal Hydrants			
	Size of riser/down- comer	N/A	N/A	N/A
	Number of hydrants per floor	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
2.	Yard Hydrants			
4.	Total number of hydrants	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
3.	Pumping Arrangements			
٥.	Ground Level			6
	Discharge of main pump	N/A	N/A	N/A
	➤ Head of main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey pump out put	N/A	N/A	N/A
	> Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	auto Staring/Manual stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace level			. 1.
	Discharge of pump	NA	N/A	NA
	> Head of the pump	MA	NIA	N/A
	Power supply	MA	MA	NIA
	Autoritation of assess	NIA	MA	NA
1.4	Auto starting of pump  Captive water Storage for fire fighting			
14.		N/A	N/A	N/A
		N/A	N/A	N/A
	<ul><li>Draw of connection</li><li>Fire service inlet</li></ul>	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	Overhead Tank capacity	1 1/71	AVAK	
1.7		Yes	Provided	MR
15	Exit Signage	103		
16.	Provision of Lifts			

	Pressurization of lift lobby Communication in lift Car	3427, D.B.	G. Road, Pah	28 Gan, , New Dela	Li-11
	Pressurization of lift lobby	MIA	MA	win of	Lea
		MIA	MA	MA	1550
	Fireman's Grounding Switch	NIA	MA	NA	
	➤ Lift Signage	MA	NIA	MA	
7.	Standby power supply	YES	D.G. Set	MR	
8.	Refuge Area			TVIIC	
	> Total area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19.	Fire control room			11//1	
	Detector system panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
	Batter backup	N/A	N/A	N/A	
`	➤ Building Floor Plans	N/A	N/A	N/A	
).	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name
Designation

Doycoo

Submatiba de bl

Signature of the Inspecting Officer

Name D.S. yadar Designation ADO(CD)