GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2012/ 4164

Dated: 07/11/12

FIRE SAFETY CERTIFICATE

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony New Delhi–110049 w.r.t. letter No.57978/Addl.C.P./Lic.(H) New Delhi dated 03-10-12.
- 2. M/s Topaz Guest House, 9140-41, Multani Dhanda, Pahar Ganj, New Delhi-110055.

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

	INSPECTION	ON REPORT 7	opaz quest he	2180, 9140-41,				
	Gali	NO.3, multa	ni Dhanda,	Palas Gant,				
	Name & address of the building New Delhi-110055.							
1	- Deegenz House							
3.	Type of Case : New Case/ Renewal							
4.	Details of previous NOC: Letter No. F6/MS/DFS/GH/2009/3492 Dated 19-11-09.							
Ĵ.	Fire Safety directives letter No : $-\mathcal{N} \cdot A$							
٥. ح	Date of inspection 26-10-12							
7.	Name of the Inspecting Officers 22	harm vis sing	h yadov.					
8	and addigitation of officers							
0	from the building side She Sanjay vit (ownes)							
9.	9. Year of Construction : Starting year 2009							
T	The Section Spins with the section of the section o	and the state of t	M) dated New Del	and the second s				
S.	Minimum Standards on fire	/	Provided at site	Remarks				
No.	prevention and fire safety U/R 33	Requirement		MR/NMR				
,	Access to building			PSS ARDA				
	• Road width	-NA-	06 mtes app	lear M.R				
	Gate width	-N.A -						
	 Width of internal road 	-NA - -NA -	2					
2	Number, Width, Type & Arrangement of							
	a. Number of staircases							
	 Upper Floors 	one	one	N.R				
1	• Basements	_N.A -						
1	b. Width of staircases	The second second of the second secon						
	• Upper Floors	0.80 M tes	01-25M tax	P M·R				
	• Basements	-N.A-						
	c. Protection of exits			2				
	• Fire check door	-N.A-						
	• Pressurization	-N-A -						
Ť	e. No. of continuous staircases to terrace	one	one	m·R				
	g. Width of Corridor	-N.A-						
	h. Door Size	-N.A -		Jel .				

Topag guest house, 9140-41, multani shanda, Pakas Grand, New Delhi-110055

	Unner Floor			old case
	oppor 11001	-N.A-		
To recognize the lot depression on	oprinkler above false ceiling	- N.A -		
11	Internal Hydrants			
	Size of riser/down-comer	- N.A -		
	 Number of hydrants per floor 	-N.A -		
	* Hose Box	-N.A-		
	Vard Hydrauts.	-N.A-		
	The second secon		A second	
	 Total number of hydrants Hose Box 	-N.A -		
13	Pumping Arrangements.	-N.A -		Carrier Cooke II Carrier III Carrier
	* Ground Level			
		-NA -		
	Discharge of main Pump	-NA -		
	Head of Main pump	-N.A -		
	Number of main pumps	-N.A	111 11 11 11	
	> Jockey Pump out put	- N.A -		
	Jockey pump head	-N-A-		
	Standby Pump out put			
	Standby Pump Head	-N.A -		
	> Auto Starting/ Manual	-N.H		
	stopping	-N.A -		
	> Pump House Access	2 4		
	• Terra e level	- N.A -		
	E ischarge of pump	225 LPM	225 LPM	M.R.
	> Head of the pump	30Mtss	30MER	M. R. Wille
	> Power Supply	<i>Electricity</i>	Beetheity	M.R
of data and a second state of the second	> Auto Starting of pump		Switch Provides	M-R
14	Captive Water Storage for fire fightin	g.	un ground flat	
*	Underground tank capacity	- N.A-		
	> Draw-off connection	N.A -		
	TO AMERICAN CONTRACTOR OF CALCULATION OF CALCULATIO	/ //		ſ

contd:

To pag quest house, 9/40-41, multani Danda, pahar Grand, New Dellie 1/8055.

	1	The state of the s				
	Fire service inlet	- N.A -				
	Access to tank	- N.A -				
	 Overhead Tank capacity 	2500 lites	2500 lites	M.R V		
15	Exit Signage.	yes.	2500 litel	M.R V		
16	Provision of Lifts.					
	* Pressurization of Lift Shaft	- N.A -	The state of the s			
	Pressurization of Lift lobby	- N.A -	The state of the s			
	* Communication In lift Car	428	Denuided -	M·R		
	Fireman's Grounding Switch	The second secon	Provided.			
	Lift Signage	yes		M.R		
	1. 1.	yes	Provided.	M.R		
117	Standby power supply	yes	D.G. SEE	M.R		
18	Refuge Area.		· · · · · · · · · · · · · · · · · · ·			
	> Total Area	-N.A	The second secon			
	> Location	-N.A -				
10	Fire Control Room			and the same of th		
Transport	Detector System Panel	- N.A-	and the second s			
	* Flow Switch Panel	- N.A -	man, and a character appropriate by seek years a section of minimum of the consequence of			
	PAl System Panel	- N.A -	This was the publication of the second of th			
	Batter backup	- N.A -		AND THE PARTY OF T		
	Building Floor Plans	-N.A -				
20	Special Fire Protection Systems for	11-				
	Protection of special Risks, if any:	- N.H	2 1 8			
				7		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi service Rules 2010/ issue shortcomings as noted at serial numbers.

Topaz quest house, 9/40-41, Multani dhanda Pahal Gant New selli-110055

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name Do S. yadov.

Designation A. D. (e.D)

Do (c.D) Submitted Alease