GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No: F.6/DFS/MS/School/2012/ 4475

Dated: 04/12/12

FIRE SAFETY CERTIFICATE

Certified that the building of **M. C. Primary School,** Razapur Khurd No-1 (1st and 2nd Shift), Mohan Garden, New Delhi -110059 comprised of ground floor only, having total 12 rooms (Including Class Rooms & Offices) owned/occupied by MCD was re-inspected by the officer concerned of this department on 24.11.2012 in the presence of Sh. D.P. Mandal (Principal) and found that the M.C.D have complied with the fire prevention and fire safety requirements in accordance with the Circular No-F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to: -

The Principal,
 M. C. Primary School,
 Razapur Khurd No-1 (1st Shift),
 Mohan Garden, New Delhi-59.

The Principal,
 M. C. Primary School,
 Razapur Khurd No-1 (2nd Shift),
 Mohan Garden, New Delhi-59.

3. Director of Education, MCD, Nigam Bhawan (Old Hindu College Bldg.), Kashmire Gate, Delhi – 110006.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	INSPECT	TION REPORT					
	1. Name & dadress of the building:	M.C. Primarys	chool, Kazarpur K	hurd No-1 (I) Mohanga			
	2. Type of Occupancy :	: M.C. Primary School, Rajarpur Khurd No-1 (2) Mohan (and : Educational (School) N.b-59 : New Case/Renewal					
	3. Type of Case :	New Case/Rer	iew al				
		Letter No		Dated			
		NIA					
	6. Date of inspection :	: 24.11.2012					
	7. Name of Inspecting Officer :	: A.D.O P.S. Dahiya					
	8. Name and designation of officers						
	From the building side : Sh. D. P. Mandal (Principal)						
	9. Year of Construction :						
	10. Applicant's letter No. :	: Nil dated 29.08.2012					
S.	Minimum Standards on fire prevention	Dir. Of Edu.	Provided at site	Remarks			
No.	and fire safety U/R 33	Circular dt.		MR/NMR			
		01.03.2011					
1.	Access to building		La constant de la con				
	 Road width 	Accessible	06mtr	MR			
	 Gate width 	-	3. Somtr	MR			
	 Width of internal road 	_	5 50 1111	~ //			
2.	Number, Width, Type & Arrangement of	Exits					
	a. Number of staircases						
	Upper Floors			0 10			
	Basements	-		Ground floor Only			
	Dasements		•	No Basement			
	b. Width of staircases						
	Upper Floor		_	Ground Floor Only			
	Basements			No Basement			
	c. Protection of exits			NO Dupement			
	Fire check door						
	pressurization	MA	(·			
	pressurization	MIA	Name of the last o	<u></u>			
	d. No. of continuous staircases to		. a o				
	terrace	-		Ground Floor On			
	e. Width of Corridor						
	f. Door Size	-	-	- do -			
	1. Door Size	~	92 CMB x 202 CMB	- do - MR, Being Old Bld			
3.	Compartmentation			0			
	Fire check door	NIA	_	_			
	 Sealing of electrical shafts 	MA		_			
	Fire Rating of shaft door Water Countries	KNA					
	Water Curtain	***************************************					
	 Fire Dampers 	AI/A					
4.	Smoke Management System						
	BasementsUpper floors	30 a/c per hour	-	No Bapement			
			-	Ground Moor only			

NIA

NIA

MIA

Standby Pump Head

Auto Starting/Manual

stopping

NIS Razapar Khurd No-1 Mohan Garden, N.D-59

	Pump House Access	NIA		•		
	 Terrace level 					
	Discharge of pump	MIA		~		
	Head of the pump	NIA		-		
	Power Supply	-		~		
	Auto Starting of pump		_			
1.	Captive Water Storage for fire fighting					
	 Underground tank capacity 	NIA	-	-		
	Draw-off connection	NIA	_	_		
	Fire service inlet	NIA		_		
	Access to tank	NIA				
	 Overhead Tank capacity 	NIA	-	-		
).	Exit Signage.		Provided	-		
-).	Provision of Lifts.					
	 Pressurization of Lift Shaft 		-	N/A / :: 61		
	 Pressurization of Lift lobby 			No Lift		
	Communication In lift Car	•				
	• Fireman's Grounding Switch		-	- do -		
	Lift Signage		-	-do -		
	2	_		-do-		
7.	Standby power supply	NIA	•	_		
8.	Refuge Area.	*				
	Total AreaLocation	NIA	•	_		
	1	NIA				
Ω	Fire Control Room					
19.	Detector System Panel					
	Flow Switch Panel	NIA				
	* PA System Panel	NIA		-		
	* Batter backup	NIA				
	 Building Floor Plans 	NIA		-		
	a panania tioot sigus	NIA		-		
0.	Special Fire Protection System for	A 4 5				
	Protection of special Risks, if any:	MIA				

he fire protection systems provided in the building were test checked and found functional at he time of inspection.

mening in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety ertificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Note: The school building is comprised of Ground floor only, having total 12 Rooms including class Rooms, & Offices. The student are less than 45 in each class as stated by Principal's Letter dated 24.11.2012.

Designation ASSH. Divisional Officer

Signature of Inspecting Officer

Name

Designation