GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI - 110001

No. F6/DFS/MS/2011/ School/3626

Dated: 20 12 11

FIRE SAFETY CERTIFICATE

Certified that Dignity International Public School, at G- 526, Sangam Vihar (Near Vishwakarma Mandir), New Delhi-110062 comprised of ground and one upper floor Owned/Occupied by Dignity International Public School, New Delhi has complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 and Rule 33 of the Delhi Fire Service Rules, 2010 and verified by officers concerned of Delhi Fire Service on 09.12.2011 in the presence of Shri Satish Siwas, Manager of the school and that the building / premises is fit for occupancy class-B (Educational) with effect from 20 12 11 for a period of Three years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010

Issued on ____ at New Delhi by

Chief Fire Officer
For Director
Delhi Fire Service

ole

Copy To: -

 Shri Satish Siwas, (Manager) Dignity International Public School, At G-526, Sangam Vihar (Near Vishwakarma Mandir) New Delhi-110062

The Directorate of Education, Govt. of NCTD, Old Secretariat, Dolhi.

Conditions for the validity of fire safety Certificate

- 1. All the means of escape shall be kept free of all type of obstruction all the time.
- All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
- All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
- 4. Any deviation, with regards to construction, electric installation etc. may be got verified from the concerned authorities.
- 5. Basement shall be used as per BBL.
- 6. This NOC may not be treated in any case for regularizations of unauthorized construction, if any.
- The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.

	INS	PECTION REPORT					
1. Name and address of the building: DIGNITY INTERNATIONAL PUBLIC SCHOOL							
	: G. 526, SANGAM VIHAR NEW DELHI. 62 2. Type of Occupancy : Clam - B' (Educational)						
	2. Type of Occupancy	: Clan - 'B'	(Ed Wear	- Vibhnaleanno	Mandin		
	3. Type of Case	: New	Cancaria	(a)			
	4. Details of previous NOC	: NJ.			_		
	-	: N.J.	Det	- 1			
	6 5	: 09-12-2		ea:	_		
	7 N			- /no 1 \			
8. Name of the Inspecting Officers : Rayan Wadehna (Abe/MRd)							
	is the state of th	Mr. Solial	Mr. Salish Siwan (Manapu)				
	9. Year of Construction .	2008-2009	CO	mapa)			
	10 Applicant/ Louis	2008.2009 NIU 12/0	azza e	and one upper t	(hv)		
S.	Minimum	,					
No.	Prevention and Fire Safety U/R 33	Requirement	Provided at site	Remarks			
1	Access to building	quii ement	site	MR/NMR	31-46		
	Road width						
	Gate width	15 m	18.28 m	MR			
		'6 m	7-62 m	MR			
2	Width of internal road	6 m	7.62m	MR			
	Trainber, Width, Type & Arrangement of Exits						
	Number of staircase						
	Upper Floors	PWO	Two	MR			
	Basements	NOT REQUIRE	-N/A-	MIR			
	Width of Staircases						
	Upper Floors	1.5 m	1.5 m	- MIR			
	Basements	NOT, REQUIRED	N/A.	MIR			
Protection of exits							
	Fire check door	Not Required	NIA	AA10			
	Pressurization	Not Required	N/A-	MIR			
	No. of continuous staircases	Two	PWO	m)R			
	to terrace	-	7000	M)R			
	Width of Corridor	1.5m	2.0				
T. C. P. Short	• Door Size	1')M	3.0m -	MIR			

1.0 m

1.25m

MIR

3 Compartmentation N A						
-	Fire check door					
	 Sealing of electrical shafts 		,			
	 Fire rating of shaft door 					
	Water curtain		1			
	Fire Dampers		· ·	6		
4	Šmoke Management System		MA			
	Basements	30 a/c Per hour	N. P.			
	Upper Floors	12 a/c Per hour				
5	Fire Extinguishers					
	Total Number		10 NUS	MIR		
	• Types		613BC	mlR		
	IS marking	ISI mark	462	MID		
6	Firs-Aid Hose Reels		Yes	The state of the s		
0	Total Number on each floor		NIA			
9						
	Length of hose reel hose	30 m				
	Nozzle diameter	5mm		/ _		
7	Automatic Fire detection and alarming system					
	Type of detectors	. ,				
	Location of Main Panel			/ /		
	Location of Repeater Panel		/	/		
	Alternate source of power			/		
	Hooter's Location					
8	MOEFA					
9						
10 Automatic Sprinkler System N 114			HIL			
	Basement					
	Upper FloorSprinkler above false ceiling					
	<u> </u>					
11	Internal Hydrants		NA			
	Size of riser/down comer					
	Number of hydrants per floor					
12	Hose Box	1				
12	12 Yard Hydrants					
William III	 Total Number of hydrants 					
	Hose Box					

	13	Pumping Arrangements		
_		Ground Level		
7. 7		ÿ 11		
	`	Number of main pump		
		Discharge of main pump		
		Head of main pump		
		Jockey pump out put		
		 Jockey pump Head 		
		Standby pump out put		
		Standby Pump Head		
		Auto Starting/Manual		
		Pump House Access		
		Terrace level		
		Discharge of pump	THE TENED	
		Head of the pump		
70		Power Supply		
		Auto starting /manual		
14	4	Captive Water Storage for Fire Fighting		
		Underground tank capacity		
		> Draw-off connection		
		Fire service inletAccess to tank		
		Overhead tank capacity		
15	٠,			
15		Exit Signage Provision of Lifts	Provided MIR	
10	-			
		Pressurization of Lift Shaft Prossurization of Lift Lab.		
		Pressurization of Lift lobbyCommunication in lift Car		
		and the same and a same a same and a same a		
		Fireman's Grounding Switch Lift Signal as		
		Lift Signage	6	
17 18		tandby Power Supply	N M	
10	N	efuge Area • Total Area		
		Location		
19	F	ire Control Room		
	+	Detector System Panel	MH	
		• Flow Switch Panel		
		PA System Panel		
		Battery back up	4	
		Suilding Floor Plans	(
		Cancara Flori Flans		

20 Special Fire Protection System for Protection of special risk, if any N/A N/A N/A

The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules , It is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/issue shortcomings as noted at serial number.

D.(5)

Duilo on El

Signature of Inspecting Officer

Name LA: JAN WADEMA