GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: NEW DELHI – 110001

No. F6/DFS/MS/ school /2012/524

Dated: (6/02/12

FIRE SAFETY CERTIFICATE

Certified that **Great Abhinav St. Thomas Public School, Gali No: 46A, Molar band Extn.,**New Delhi-110044, comprised of ground floor only Owned/Occupied by Great Abhinav St. Thomas Public School, has complied with the fire prevention and fire safety requirements in accordance with Directorate of Education Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01/03/2011 and Rule 33 of the Delhi Fire Service Rules, 2010 and verified by officer concerned of Delhi Fire Service on 02/02/2012 in the presence of Shri Pawan Bansal, Principal of the school and that the building/premises is fit for occupancy class-B "Educational building" with effect from _____/6/o ___//___ for a period of THREE years in accordance with Rule 36 unless renewed under Rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under Rule 38 of the Delhi Fire Service Rule 2010.

Issued on ------at New Delhi by

Chief Fire Officer

Director

Delhi Fire Service

Copy To: -

- 1. The Directorate of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi.
- 2. The Principal, Great Abhinav St. Thomas Public School, Gali No: 46A, Molar band, New Delhi-110044

Conditions for the validity of fire safety Certificate

- 1. All the Fire Safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- Building Sanctioning Authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- 3. The staff shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- 4. The Basement shall be used strictly as per the provisions of Building Bye Laws.
- 5. The owner/occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPE	ECTION REPORT			
Name and address of the building:	Great Abhi	nav ST. Thon	mas Public	
	Molaxband &			
2. Type of Occupancy :	Edeuation	٨		
3. Type of Case :	: New			
4. Details of previous NOC :	NiL			
5. Fire Safety directives letter No :	NIL	Dated	d:	
6. Date of Inspection	of Inspection : 210 In			
7. Name of the Inspecting Officers :	Ratan w	adehag Ar	DOIM-Road	
8. Name and designation of Officers			,	
From the building side :	Stroj Pawan	Bansal (Sinci Pal)	
9. Year of Construction :	Ground Pl	008		
10. Applicant's letter No :_	NIT			
S. Minimum Standards on Fire No. Prevention and Fire Safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR	
1 Access to building			S.	
Road width	15mts.	15 M/rs.	MIR	
Gate width	NA	NA	NA	
 Width of internal road 	NA	NA	NA	
2 Number, Width, Type & Arrangement		A 60	Ψή	
Number of staircase		01 1/1		
Upper Floors				
> Basements				
Width of Staircases	AN			
Upper Floors		7110		
Basements				
 Protection of exits 		AN		
Fire check door		, 110		
 Pressurization 				
 No. of continuous staircases 	-/	NA		
to terrace	/	7	7	
 Width of Corridor 				
Door Size				

3	Compartmentation	on MA			
	Fire check door			h	
	Sealing of electrical shafts				
	Fire rating of shaft door				
	Water curtain	/-			
4	Fire Dampers				
4	Smoke Management System	<i>X</i> -	MA	4	
	Basements	30 a/c Per hour			
	Upper Floors	12 a/c Per hour			
5	Fire Extinguishers				
	 Total Number 	1 EX+300M2	OYNOS.	MIR	
	 Types 	ISI mark	ABC	MIR	
	IS marking		YES	YES	
6	Firs-Aid Hose Reels		NA	1 0	
	 Total Number on each floor 				
	 Length of hose reel hose 	30 m			
	Nozzle diameter	5mm			
7	Automatic, Fire detection and alarming system				
	Type of detectors		/		
	Location of Main Panel				
	 Location of Repeater Panel 		//		
	Alternate source of power				
According to the second	 Hooter's Location 				
8	MOEFA	9	MA		
9	Public Address System		AM		
10	Automatic Sprinkler System		MA		
	Basement		1		
	Upper FloorSprinkler above false ceiling				
				/	
11	Internal Hydrants	2	AM.	9	
	Size of riser/down comer				
	Number of hydrants per floorHose Box				
13			/		
12	Yard Hydrants		NA		
	 Total Number of hydrants 				
	Hose Box				
Marie de Charles de La Constantina de Carlos d		det.			

· .

1	13	Pumping Arrangements	. ^
		Ground Level	MA
		Number of main pump	
		Discharge of main pump	
	MACON Princeton I aggings of		ρ / / / / /
	o complete complete a	Head of main pump	///
	and the same of th	Jockey pump out put	
		Jockey pump Head	
	observed the second sec	Standby pump out put	
	and the second s	Standby Pump Head	
		Auto Starting/Manual	
	a - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -	Pump House Access	
	Total and the state of the stat	Terrace level	
		 Discharge of pump 	MA
		 Head of the pump 	
100		Power Supply	
		Auto starting /manual	
THE RESERVE AND ADDRESS.	14		
-	17	Captive Water Storage for Fire Fighti	ng NA
Anne is justice and displaying		 Underground tank capacity Draw-off connection 	
Bride to an own but to g		> Fire service inlet	
of services of the second		Access to tank	
and an investment of		 Overhead tank capacity 	
	15	Exit Signage	MA
N. Other Control	16	Provision of Lifts	NA
	-	 Pressurization of Lift Shaft 	
		 Pressurization of Lift lobby 	
		Communication in lift Car Fireman's Grounding Switch	
		Fireman's Grounding SwitchLift Signage	
11 12	17		
-		Standby Power Supply Refuge Area	MA M
		• Total Area	NA.
		• Location	
	19	Fire Control Room	NIA
		 Detector System Panel 	T NA
		 Flow Switch Panel 	
		PA System Panel	
		 Battery back up 	
	S. S	Building Floor Plans	
			The state of the s

Special Fire Protection System for Protection of special risk, if any	NA	W A	
The Fire protection			NA

The Fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the second control of the building were test checked and found the building in view the second control of the building were test checked and found the building were test checked and the

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules, It is recommended to grant Fire Safety Certificate under rule of the Delhi Fire Service Rules 2010 / issue shortcomings as noted at serial

Signature of Inspecting Officer

Name : RAJAN WADEHRA
Designation: ASST. DIV. OFFICER

DO (South)

18/7/12

Defo [m]