

No. F6/DFS/MS/Cosmetics/2012/118

Dated : 13/01/12

FIRE SAFETY CERTIFICATE

Certified that the **M/s. NATURAL WANDER COSMETICS** located at **G-13, Badli Industrial Area, Phase-III, Delhi-110 042**, comprised of basement and ground floor and less than 9 meters in height was issued NOC vide this office letter No.F.5/(3)/DFS/2004/05 dated 06.01.2004. The premises was re-inspected by the Officers concerned of this department on 28.12.2011 in the presence of Mr Mahender Kumar Garg, Owner and observed that all the fire safety and fire prevention arrangement as provided in the premises is found in good working condition and there is no additional construction. The premises have therefore deemed complied with requirements under Rule 33 of Delhi Fire Service Rules, 2010 and building/ premises is fit for occupancy class **Industrial Building (G-2) class** with effect from 13/01/12 for a period of **three years** in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on 13/01/12 at New Delhi by



Director

Delhi Fire Service



Shri Mahender Kumar Garg, Owner,
M/s. NATURAL WANDER COSMETICS,
G-13, Badli Industrial Area,
Phase-III, Delhi-110 042.

Copy to :

Shri P.K. Jaggi,
Asstt. Drugs Controller & Licencing Authority,
Govt. of NCT of Delhi, Drugs Control Department,
F-17, Karkar Dooma, Delhi-110032.

Conditions for the validity of fire safety certificate:-

- All the fire safety means of escape facilities shall be maintained in good conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be responsibility of the management.
- Building sanctioning authority may verify any deviation with regard to the construction/ occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- The staff shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.

INSPECTION REPORT

1. Name & address of the building : M/s. Natural Wandur Cosmetics, Bachhi Ind. Area.
2. Type of Occupancy : INDUSTRIES BUILDING G-2
3. Type of Case : New Case/ Renewal
4. Details of previous NOC : Letter No. F.5(C3)/AFS/2004/05 Dated: 06.01.2004
5. Fire Safety directives letter No : _____
6. Date of inspection : 28/12/2011
7. Name of the Inspecting Officers : SHRI R.K. DAHIYA, ADO
8. Name and designation of officers from the building side : N.A.
9. Year of Construction : 2003
10. Applicant's letter No. : NW-61/MFG/Cos/DC/1054 Dated 24.11.11

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	Accessible	Accessible	MR
	• Gate width	— u —	— u —	—
	• Width of internal road	—	—	—
2	Number, Width, Type & Arrangement of Exits			
a.	Number of staircases			
	• Upper Floors	—	—	NOC is already by this Deptt.
	• Basements	—	—	
b.	Width of staircases			
	• Upper Floors	—	—	
	• Basements	—	—	
c.	Protection of exits			
	• Fire check door	—	—	
	• Pressurization	—	—	
e.	No. of continuous staircases to terrace	—	—	
g.	Width of Corridor	—	—	
h.	Door Size	—	—	

3	Compartmentation.			NA	
	• Fire check door	-	-	-	-
	• Sealing of electrical shafts	-	-	-	-
	• Fire Rating of shaft door	-	-	-	-
	• Water Curtain	-	-	-	-
	• Fire Dampers	-	-	-	-
4	Smoke Management System.			NA	
	• Basements	30 a/c per hour	-	-	-
	• Upper floors	12 a/c per hour	-	-	-
5	Fire Extinguishers			Provided	
	• Total numbers		5		MR
	• Types		ABC Type		-
	• IS marking	ISI marked	ISI Marked		-
6	First-Aid Hose Reels.				
	• Total numbers on each floor		Two		MR
	• Length of hose reel hose	30 m	30m		-
	• Nozzle diameter	5 mm	5 mm		-
7	Automatic fire detection and alarming system.			NA	
	• Type of detectors	-	-	-	-
	• Location of Main Panel	-	-	-	-
	• Location of Repeater Panel	-	-	-	-
	• Alternate source of power	-	-	-	-
	• Hooters' Location	-	-	-	-
8	MOEFA			Provided	-
9	Public Address System.			Provided	-
10	Automatic Sprinkler System.				
	• Basement	Required	Provided		MR

	<ul style="list-style-type: none"> • Upper Floor • Sprinkler above false ceiling 	Required	Provided	MR
		-	-	-
11	Internal Hydrants	NA		
	<ul style="list-style-type: none"> • Size of riser/down-comer • Number of hydrants per floor • Hose Box 	-	-	-
		-	-	-
		-	-	-
12	Yard Hydrants.	N.A		
	<ul style="list-style-type: none"> • Total number of hydrants • Hose Box 	-	-	-
		-	-	-
13	Pumping Arrangements.			
	<ul style="list-style-type: none"> • Ground Level <ul style="list-style-type: none"> ➤ Discharge of main Pump ➤ Head of Main pump ➤ Number of main pumps ➤ Jockey Pump out put ➤ Jockey pump head ➤ Standby Pump out put ➤ Standby Pump Head ➤ Auto Starting/ Manual stopping ➤ Pump House Access • Terrace level <ul style="list-style-type: none"> ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	-	-	-
		-	-	-
		-	-	-
		-	-	-
		-	-	-
		-	-	-
		-	-	-
		-	-	-
		900 lpm	Provided	MR
		40 mhs	Provided	MR
		-	-	-
		-	-	-
14	Captive Water Storage for fire fighting.			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection 	-	-	-
		-	-	-

	<ul style="list-style-type: none"> ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	-	-	-
		-	-	-
		10,000 Litres	10,000 Litres	MR
15	Exit Signage.	Repaired	Provided	MR
16	Provision of Lifts.		NA	
	• Pressurization of Lift Shaft	-	-	-
	• Pressurization of Lift lobby	-	-	-
	• Communication In lift Car	-	-	-
	• Fireman's Grounding Switch	-	-	-
	• Lift Signage	-	-	-
17	Standby power supply	-	NA	-
18	Refuge Area.		NA	
	➤ Total Area	-	-	-
	➤ Location	-	-	-
19	Fire Control Room		NA	
	• Detector System Panel	-	-	-
	• Flow Switch Panel	-	-	-
	• PA System Panel	-	-	-
	• Batter backup	-	-	-
	• Building Floor Plans	-	-	-
20	Special Fire Protection Systems for Protection of special Risks, if any:	-	-	-

✓ The fire protection systems provided in the building were test checked and found functional at the time of inspection.

✓ Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

5



Signature of the Inspecting Officer

Name

SHRI R.K. DAHIYA

Designation

ADO

Signature of the Inspecting Officer

Name

Designation

D.O Road Nagpur