GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI**

No: F6/OGS/OS/ GH/2011/3680

Dated: 23/12/11

FIRE SAFETY CERTIFICATE

Certified that the YWCA of India International Guest House located at 10, Sansad Marg, New Delhi comprised of ground floor (Reception, Lobby, Dinner Hall & Staff Kitchen), 1st floor (06 guest rooms), 2nd floor (06 guest rooms), 3rd floor (06 guest rooms), and 4th floor (06 guest rooms) was granted NOC by this department vide letter No. F6/DFS/MS/GH/2008/1246 dated 30-04-2008. The premises was re-inspected by the officer concerned of this department on 14-12-2011 in the presence of Sh. Nanda and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 24 rooms with effect from under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued 23/1.2/1... at New Delhi by.

CHIEF FIRE OFFICER for DIRECTOR DELHI FIRE SERVICE

Copy to :-

- by to :1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi
- 2. Y.W.C.A. of India International Guest House, 10, Sansad Marg, New Delhi-110001
- 3. Chief Architect, NDMC, Palika Kendra, New Delhi-110001 (with the request to get the height of building verified and intimate to this department)

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPEC	TION REPORT.	International	located at			
1. Name & address of the building : 10,	sansad mars	vew delli-11	100%			
INSPECTION REPORT International YWCA of India, Guest House Located at 1. Name & address of the building: 10, Sansad Mars, New Della-110001. 2. Type of Occupancy : Group A-1 Residential 3. Type of Case : New Case/ Renewall						
					1 5	
Details of previous NOC : Letter No. F6/Ms/SFS/G-H/20/2/20 Dated: 0/-02-10 Fire Safety directives letter No : -N-A-						
6. Date of inspection : 14-12-20//						
7. Name of the Inspecting Officers: D.	S. Vadav.	2 2 20				
8. Name and designation of officers	Name and designation of officers					
from the building side ME	· Nanda ·	3. •				
9. Year of Construction : PA	riok to 1982	2				
10. Applicant's letter No.		15				
Minimum Standards on fire	NBC	Provided at site	Remarks			
o. prevention and fire safety U/R 33	Requirement		MR/NMR			
Access to building			Ole			
 Road width 	12 M	12M.	M. R			
Gate width						
 Width of internal road 	N.A.	6 M	M·R			
Number, Width, Type & Arrangement		N. A	m.R.			
a. Number of staircases	DI Exits					
Upper Floors						
• Basements	one.	Two	M.R			
b. Width of staircases	N. A	N.A	M·R			
Upper Floors			r			
• Basements		(2) 1.41 M.				
c. Protection of exits	N. A	N. A	m. P			
Fire check door						
Pressurization	N. A	N. A	M·R			
	N. A	N. A	M.R			
e. No. of continuous staircases to terrace	one	one	M-R			
g. Width of Corridor h. Door Size	1.25	1.3/ M.	m.R			
n. Door Size	1.25	1.25 M	M.R.			

contal:

Yuch of India International Guest Mouse 10, sansad morg, New Delli-110001

\forall	C	1			
+	Compartmentation.		A		
1	• Fire check door	N.			
	 Sealing of electrical shafts 				
	• Fire Rating of shaft door			2	
	Water Curtain				
	 Fire Dampers 				
	Smoke Management System.				
	• Basements	30 a/c per hour	N.A	M.R	
	Upper floors	12 a/c per hour	yes:	m·R.	
	8			n ²	
5	Fire Extinguishers		,		
	Total numbers		12 NOS.	m·R	
	• Types		ABC Type of w. cox Type of	M·R	
	IS marking	ISI marked	w. co 2 Type.	M.R.	
6	First-Aid Hose Reels.				
	Total numbers on each floor	one	one	m-R	
	 Length of hose reel hose 	30 m	yes	m.R	
	Nozzle diameter	5 mm	yes.	M.R	
7	Automatic fire detection and alarming system.				
	Type of detectors	N-A)		
	Location of Main Panel				
	• Location of Repeater Panel				
	Alternate source of power				
	Hooters' Location				
8	MOREA	YES.	yes.	m.R	
	MOEFA		yes.	M·R	
9	Public Address System.	he	a desi		
10	Automatic Sprinkler System.				

contd:-

YWCA of India Integrational Gust House 10 sansad mass, new pelli-/1000/.

	0					
	*	Upper FloorSprinkler above false ceiling	_ N · R)		1
	11	Internal Hydrants				
		Size of riser/down-comer		3 395		
		Number of hydrants per floor	100 mm	100 mm	m.R	
		• Hose Box	one	one	m.A.	-
	12	Yard Hydrants.	he	yes.	M.R.	
					1	-
		Total number of hydrantsHose Box	N. A	N. A	old ca	K
	13	Pumping Arrangements.	N.A	N.A -	-1/ -	
		• Ground Level				
			* * * *			*
		Discharge of main Pump				
		Head of Main pump				
		Number of main pumps				
***		> Jockey Pump out put			×	
		> Jockey pump head	A	D		
		Standby Pump out put		(F)		
		Standby Pump Head				
		➤ Auto Starting/ Manual			. 350	
		stopping		2 - 2	3/	
		Pump House Access				
		 Terrace level 				
		Discharge of pump	450 LAM	570 LPM.	m.R.	
		> Head of the pump		20 M.	M. R.	W
	•	Power Supply	yes	yes	M.A	
F		Auto Starting of pump	yes	ses	m. R	lerî
-	14	Captive Water Storage for fire fighting.				
		 Underground tank capacity 	50,000 Lts	5/000 lite		
		> Draw-off connection	yes.	yes yes		
	le:		<i>\(\)</i>		m.R.	1

contdi-

yweA of India International Guest home.
10, sansad moss, we wo colli-11000/

			1 11		
	> Fire service inlet	yes.	yel-	m.R.	
	Access to tank	yes.	yes	m.R.	
	Overhead Tank capacity		20,000 lites		
15	Exit Signage.	yes	yes.	M.R.	
16	Provision of Lifts.			1	
	• Pressurization of Lift Shaft	N-A.	N-A-	M·R	
	• Pressurization of Lift lobby	N. A	N-A	M·R	
	 Communication In lift Car 	sel	yes.	M. R	
	• Fireman's Grounding Switch	wel.	ys.	M. R	
	• Lift Signage	7		11.02	
		Jes .	yel.	m.R.	
17	Standby power supply		200 KVA	m.R.	
18	Refuge Area.				
	> Total Area	1			
	> Location				
19	Fire Control Room				
	Detector System Panel	N. A.	N.A	M.R.	
	 Flow Switch Panel 	N-A	NA	n.R	
	PA System Panel	yes.	yes.	m.R	
	Batter backup	yes.	W:	me R	
	Building Floor Plans	yes.	2rd .	M-R.	
20	Special Fire Protection Systems for Protection of special Risks, if any:	N-A	p.A	M.R.	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

YN.C.A of India International Guest moves
10, sansad may, New Delli-110001 (5)

Signature of the Inspecting Officer

Name

Name

Designation

Designation

Signature of the Inspecting Officer