GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110001.

No. F6/OFS/MS/GH/2012/12

Dated: 03 | 01 | 2012

FIRE SAFETY CERTIFICATE

Certified that the Guest House **Yug Villa** located at 7A/14, WEA, Channa Market, Karol Bagh, New Delhi-110005 comprised of Basement, Ground floor plus three upper floors using basement as Hall/Storage, ground floor as reception, lobby, office & two guest rooms, first, second & third floor each having five guest rooms respectively (total seventeen guest rooms) and pantry on terrace floor owned/ occupied by Sh.Raman Kapoor S/o Sh. Amir Chand Kapoor have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of fire service on 27.12.2011 in the presence of Sh. Pankaj Mehta (Partner) and that the building / premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 subject to conditions printed overleaf.

CHIEF FIRE OFFICER
For DIRECTOR
DELHI FIRE SERVICE

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.)

 1st floor, P.S., Defence Colony, New Delhi.

 (Ref. No.45143-46/Addl. C.P./Lic.(H), Dated 22.09.2011)
- 2. Sh. Raman Kapoor (Owner) G. H Yug Villa, 7A/14, WEA, Channa Market, Karol Bagh, New Delhi-110005.

	INSPECT	ION REPORT						
	1. Name & address of the building:	tug Villa FALL	14 WEA Change	il to call				
	1. Name & address of the building: Yug Villa, 7A/14 WEA Channa mkt. karol Bagh, N. d. 2. Type of Occupancy: Residential (Guest House)							
	. New Case /Renowal							
	4. Details of Previous NOC	etter No.		Date				
	5. Fire Safety directives letter No :							
	6. Date of inspection : 37.12.2011							
	8. Name and designation of officers From the building side 9. Year of Construction 1. No. H. L. Aneya & A. D. O. P. S. Dahiya 1. Mr. Pantaj Mehta (Partner)							
	10. Applicant's letter No.	45143-46/Add1	. C.P./LIC.(H) date	d 22.09.11				
S.	willing Standards on fire	NBC/BBL	Provided at	Remarks	V			
No.	prevention and fire safety U/R 33	Requirement		MR/NMR				
1.	Access to building			way www.	1			
	Road width	Accessible	12 mtr. Approx	MR				
	Gate width		175cm	mR				
	Width of internal road		4.40 mts	0 0 0	[
2.	Number, Width, Type & Arrangement o	of Exits	1 40 mts	MR				
	a. Number of staircases	One	One					
	• Upper Floors	- do -		mR	111			
	Basements		- do -	MR	* 1.			
	b. Width of staircases	- do -	- do -	MR				
	Upper Floor		100					
	Basements	125cm	126 cm	MR	11			
	c. Protection of exits		117 cm	MR				
	Fire check door)	• • • •			
	pressurization	NIA	-					
	d. No. of continuous staircases to	NIA		-	11			
	terrace							
	e. Width of Corridor		One	m R				
	f. Door Size	•	152 cm	MR				
			79cm x 225cm	mR	;			
3.	Compartmentation		, , , , , as cm	11) K				
	Fire check door Sealing of electrical shafts Fire Rating of shaft door	NIA						
			0		9 F			
		NIA	Sealed					
	Water Curtain	MIA		•				
	Fire Dampers	MIA		E				
4.	Smoke Management System	NIA	-					
	Basements	30 a/c per	Exhaust Fans					
	Upper flcors	hour	are Provided	mR	11;			
		Lancards on the state of	Matural Ventilation	ma	the sales			

		12 a/c per hour		
	Fire Extinguishers		1	
	Total numbers	Two at each floor	0	
	Types	WC02, A.B.C	Provided	mR
1	IS marking	ISI marked	-do-	MR
j.	First-Aid Hose Reels		1SI marked	m R
is a	Total numbers on each floor	One	0	
	Length of hose reel hose	30 m	Provided	m R
Ī	Nozzle diameter	5 mm	- do -	MR
7.	Automatic fire detection and alarming		-de-	MR.
P 2	Type of detectors	NIA		
Î,	Location of Main Panel			1
	Location of Repeater Panel	1 1 1 1 1		
	Alternate source of power			+
	Hooters' Location		DG Setof 82.5 KVA	MR
В.	MOEFA		Staircape	+
). 9.		Required	Provided	MR
10.	Public Address System	Required	Provided	MR
10,	Automatic Sprinkler System • Rasement			
	Dascinette	-	Provided	n R
	Upper Floor Gradelle	NIA		
11.	Sprinkler above false ceiling	NIA	+	4
11.	Internal Hydrants			
	Size of riser/down-comer	MIA		
	Number of hydrants per floor	NIA		
40	Hose Box	MA		
12.	Yard Hydrants		1	
	Total number of hydrants	NIA		+
40	Hose Box	NIA		
13.	Pumping Arrangements	•		
	Ground Level			
	Discharge of main Pump	MIA	- 1	
1	> Head of Main pump	NIA		
	 Number of main pumps Jockey Pump out put 	NIA		
	Jockey Pump out putJockey pump head	NIA	• }	
. 1	Standby Pump out put	NIA		•
	Standby Pump Head	NIA		
	> Auto Starting/Manual	NIA	- 4	-
	stopping	NIA		+
	arohhing	1111		

G.H Yug Villa 7A/14, WEA, Channa Mkt,

	2 Dump Harris					
N COMMUNICATION OF THE PROPERTY OF THE PROPERT	Pump House AccessTerrace level	NIA	-			
	The state of the s					
	Discharge of pumpHead of the pump	450 L.P.M	450 L. P.M	MR		
	Power Supply	30 m	30 M	MR		
	> Auto Starting of pump	Required	Provided	MR		
	Auto Starting of pullip	-	-	_		
14.	Captive Water Storage for fire fighting					
	 Underground tank capacity 	NIA		~		
	 Draw-off connection Fire service inlet Access to tank Overhead Tank capacity 	N/A		<u>~</u>		
		NIA	Provided	MR		
		NIA	-	-		
		Sooo Ltr	6000ltr	MR		
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.	3		The state of the s		
	Pressurization of Lift Shaft	NIA		****		
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 	NIA				
			0			
		NIA	Provided	MR		
		Required	Provided	me		
		-	-	_		
17.	Standby power supply	Required	D.G.Set of 825km	MR		
18.	Refuge Area.					
	> Total Area					
	> Location	MIA		_		
		-	-	-		
19.	Fire Control Room					
	Detector System Panel	NIA	_	· · · · · · · · · · · · · · · · · · ·		
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	NIA				
		NIA	Ground Floor			
		11/1	Provided	me		
		NIA	irovided	mr.		
70	C I.E D.	177				
20.	Special Fire Protection System for Protection of special Risks, if any:	NIA		_		

The fire protection systems provided in the building were test checked and found functional $\overline{\mathbb{R}}$ the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers...

Note: - The width of staircase is 126 cms instead of 180 cms due to building plan sanctioned on 19.07.2007. (Letter with sonction plan placed in File.).

Name H.L. Aneja

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation As Att. Divisional Officer.