GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ 287

Dated: 31/01/12

FIRE SAFETY CERTIFICATE

Certified that the R.S. International Guest House located at 869-870, Gali Chandi Wali, Pahar Ganj, New Delhi comprised of basement (storage), ground floor (reception), 1st floor (05 guest rooms), 2nd floor (05 guest rooms) and 3rd floor (05 guest rooms) total 15 granted NOC by this department vide F6/DFS/MS/GH/2009/1698 dated 09-06-2009. The premises was re-inspected by the officer concerned of this department on 12-01-2012 in the presence of Sh. Harish and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 15 rooms with effect from under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

CHIEF FIRE OFFICER
for DIRECTOR
DELHI FIRE SERVICE

ofe men

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. Shri Gurvinder Singh Sachdeva, M/s R.S. International, 869-870, Gali Chandi Wali, Pahar Ganj, New Delhi 110055

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

oldar

INSPECTION REPORT

| 1. | Name & address of the building : R. S. | nternational | , 869-870 Galia | handi lebli Phas G | | |
|-----|--|--|-------------------|--------------------|--|--|
| 2. | | | | N. | | |
| 3. | Type of Case : New Case/ Renewal | | | | | |
| 4. | Details of previous NOC : Letter No | . F6/DFS/MS/G | 4/2009/1698 Dated | : 09-06-2009 | | |
| 5. | Fire Safety directives letter No : | | | | | |
| 6. | Date of inspection : | 101/2012 | | | | |
| 7. | Name of the Inspecting Officers: | . S. Yadar | A. D. O. | | | |
| 8. | Name and designation of officers | | | | | |
| | from the building side : | 8. Harish | (Manager) | | | |
| 9. | Year of Construction : | let Known | | | | |
| 10 | Applicant's letter No. : \$1024 | -28/ Addl. C.P/Lic | (H) dated New | Dellithe 28-10-11 | | |
| S. | Minimum Standards on fire | NBC | Provided at site | Remarks | | |
| No. | prevention and fire safety U/R 33 | Requirement | e v | MR/NMR | | |
| 1 | Access to building | | | old case | | |
| | Road width | N.A | 04-metres | M.R | | |
| | Gate width | N. A | - N.A- | M.R. | | |
| | Width of internal road | - N.A- | - N.A - | -N.A- | | |
| 2 | Number, Width, Type & Arrangement of Exits | | | | | |
| | a. Number of staircases | | a a | | | |
| | Upper Floors | one | one. | M.R | | |
| | Basements | one | one | m. R | | |
| | b. Width of staircases | Case : New Case/ Renewal f previous NOC : Letter No. FL/DFS/ms GH/2009/1698 Dated: Q try directives letter No: | | | | |
| | Upper Floors | | M·R | | | |
| | • Basements | 1.25 mtzs | 1.25 Mts | M.R. | | |
| | c. Protection of exits | | | | | |
| | Fire check door | N-A | N. A | M.R | | |
| | Pressurization | | N. A | M·R. | | |
| | e. No. of continuous staircases to terrace | one | one | M.R. | | |
| | g. Width of Corridor | -N.A = | -N.A - | M-R | | |
| | h. Door Size | -N.A- | -N-A- | M-R | | |
| | | | | conti - | | |

R.S. International, 869-870 Grali Chardinale Palol Gand, "Delli-110055

| | Comment | | | 9 | | |
|----|---|-----------------|--------------|--------------|--|--|
| | Compartmentation. | N.A- | | | | |
| | • Fire check door | | | | | |
| | • Sealing of electrical shafts | v g | | | | |
| | • Fire Rating of shaft door | | | | | |
| | • Water Curtain | | | | | |
| | Fire Dampers | | | | | |
| | Smoke Management System. | | | | | |
| | Basements | 30 a/c per hour | yes | M.R | | |
| | Upper floors | 12 a/c per hour | yes | M.R. M.R. | | |
| - | | | | | | |
| | Fire Extinguishers | | | | | |
| | Total numbers | 10 | 10 | M-R | | |
| | Types | 200 | CO2 Type = 5 | M-R M·R | | |
| | IS marking | ISI marked | yes | M-R | | |
|) | First-Aid Hose Reels. | | | | | |
| | Total numbers on each floor | one | one | M. R | | |
| | Length of hose reel hose | 30 m | yes | M-R | | |
| | Nozzle diameter | 5 mm | yes | M.R. | | |
| 7 | Automatic fire detection and alarming system. | | | | | |
| | Type of detectors | - N. F | 7 | | | |
| | Location of Main Panel | | | | | |
| | • Location of Repeater Panel | | | | | |
| | Alternate source of power | | | | | |
| | Hooters' Location | | | | | |
| | | | | P P | | |
| 8 | MOEFA | Yes | yes | M.R | | |
| 9 | Public Address System. | - N. A - | N.A- | -N.A- | | |
| 10 | Automatic Sprinkler System. | | | | | |
| | Basement | Not sequil | ed Provided | M.R | | |

contd:

R.S. International Gali Chandiwali, 869-870, Pakak Gand, N. Delli: 110055

Upper Floor Sprinkler above false ceiling 11 Internal Hydrants Size of riser/down-comer Number of hydrants per floor Hose Box Yard Hydrants. 12 Total number of hydrants Hose Box 13 Pumping Arrangements. Ground Level Discharge of main Pump > Head of Main pump Number of main pumps > Jockey Pump out put > Jockey pump head > Standby Pump out put > Standby Pump Head > Auto Starting/ Manual stopping > Pump House Access Terrace level 225 LPM Discharge of pump Head of the pump 30 Metres 30 melses > Power Supply yes yes. > Auto Starting of pump Ves Captive Water Storage for fire fighting. 14 Underground tank capacity > Draw-off connection N.A-

contd.

R.S. Intelnational Gali chandier. 869-870, Palas Gang, N. Delli-110055

| | yes | yes | m.R. |
|--|--|--|--|
| 10 12 | yes. | yes | m.d. m.R |
| Overhead Tank capacity | 4000 Lites | | M.R. |
| Exit Signage. | | | M.R. |
| Provision of Lifts. | 11 0 == | , — | .,, |
| • Pressurization of Lift Shaft | 10. 41 | | |
| • Pressurization of Lift lobby | | | |
| Communication In lift Car | | | |
| • Fireman's Grounding Switch | 1 h | | |
| • Lift Signage | | | |
| | | | |
| | yes | D.G. Set | m.R. |
| Refuge Area. | - M.A - | | |
| > Total Area | | | |
| > Location | | | |
| Fire Control Room | N.A | | |
| Detector System Panel | | | |
| Flow Switch Panel | | | |
| PAl System Panel | | | |
| Batter backup | | | |
| Building Floor Plans | | | |
| Special Fire Protection Systems for Protection of special Risks, if any: | - N.A - | | |
| | Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans Special Fire Protection Systems for | > Access to tank Overhead Tank capacity Exit Signage. Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel PAI System Panel PAI System Panel Batter backup Building Floor Plans Special Fire Protection Systems for | Access to tank Overhead Tank capacity Provision of Lifts. Pressurization of Lift Shaft Pressurization of Lift Car Fireman's Grounding Switch Lift Signage Standby power supply Refuge Area. Total Area Location Fire Control Room Detector System Panel Flow Switch Panel Batter backup Building Floor Plans Special Fire Protection Systems for |

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

R.S. International, Galiceandiwali 869-870 Paral Gans N. Dolli-11055

Signature of the Inspecting Officer

Name

Designation

909 23-01-12

Signature of the Inspecting Officer

Name D. S. yadav

Designation A. Do (central)

Do (central) 11/25/1/12