## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ 732

Dated: 0//03//2

## FIRE SAFETY CERTIFICATE

Certified that the Sunny Lodge located at 100-T, 327/XV, General Market, Pahar Ganj, New Delhi comprised of basement (other's property, Shops with separate door), ground floor (reception + lobby), 1<sup>st</sup> floor (04 guest rooms), 2<sup>nd</sup> floor (03 guest rooms) 3<sup>rd</sup> floor and 4<sup>th</sup> floor (owner residence) total 07 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/27 dated 05-01-2009. The premises was reinspected by the officer concerned of this department on 22-02-2012 in the presence of Sh. Gurucharan Singh and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 07 guest rooms with effect from .o.l. .o.l. .o. 2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .o.l./.o.3/12... at New Delhi by.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

## Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. Shri Gurucharan Singh M/s Sunny Lodge located at 100-T, 327/XV, General Market, Pahar Ganj, New Delh

## Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

-	INSPECTI	ON REPORT	, 100-7, 327	XV		
1.	Name & address of the building : Gene	eral market	, 100-T, 327, F, Pakas Gant	N. Delli:		
		esidential	72.8			
	Type of Case : New Case/ Renewal					
4.						
5.						
6.	Date of inspection : 22-02-2012					
7.	Name of the Inspecting Officers: Dhalm vil singh yadav.					
8.	Name and designation of officers					
		izuclaran s	ingh	ur e cual sec connectificacione i dissa iuna scolomorphise bueno iun en con con con cid a co		
9	and the same of th	10E to 1995				
10	Applicant's letter No. : 520	11/Addl.c.f/	lie (M) dt new De	lhi the 03-11-1		
S.	Minimum Standards on fire	NBC	Provided at site	Remarks		
No.	prevention and fire safety U/R 33	Requirement		MR/NMR		
	Access to building			PSS AERA		
	<ul> <li>Road width</li> </ul>		02-Mths	m.k		
	<ul><li>Gate width</li></ul>	- N.A.	-N.A-	MR		
and the second s	<ul> <li>Width of internal road</li> </ul>	- N.A.	- N.A-	-N.A-		
2.	Number, Width, Type & Arrangement	of Exits		y i ne many ann disputation administrative continuents and district of the service of a manufacture for		
	a. Number of staircases					
	<ul><li>Upper Floors</li></ul>	and the second s	one	m·R		
	<ul><li>Basements</li></ul>		one	m·R		
	b. Width of staircases					
	<ul> <li>Upper Floors</li> </ul>		90 cms	M· R		
	Basements			m·R		
	c. Protection of exits			and a second final day of high person day, it to the national price we have at 12, 12, 1700, 1		
	Fire check door	- M. A.	- N.A -	- N.A-		
	• Pressurization	- N.A -	- N.A one - N.A -	- N.A -		
	e. No. of continuous staircases to terrace	-N.A -	one	m.R		
	g. Width of Corridor	- N.A -	-N.A-	-N.A-		
	h. Door Size					
		the control of the state of the control of the cont	anneador confraencia e a a su circo con de crispe un sale de arte antespesar compresso que manera em establicar	cont		

Sunny lodge 100-T, 327/XN General masket, pagas como, New Ocla.

3 Compartmentation. Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers 4 Smoke Management System. yes M. R. Natural ventilation m. R. 30 a/c per hour Basements 12 a/c per hour Upper floors 5 Fire Extinguishers M.R 06 NOS Total numbers M.R Types MR ISI marked IS marking 6 First-Aid Hose Reels. one one Total numbers on each floor M.R 30 m Length of hose reel hose M.R 5 m.m. (yes) 5 mm Nozzle diameter 7 Automatic fire detection and alarming system. - N. A Type of detectors Location of Main Panel Location of Repeater Panel . Alternate source of power Hooters' Location 8 MOEFA 9 Public Address System. 10 Automatic Sprinkler System. Basement

contd:

	Suny	alodge, 10	6-1, 327/2	old case
4		faller Gang	New Delle	PSS AL
9	<ul><li>Upper Floor</li><li>Sprinkler above false ceiling</li></ul>	- N.A.	M.A -	-N.A -
11	Internal Hydrants	-N.A-	- N.A -	- N.A -
	<ul> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	N. 1	7	
2	Yard Hydrauts.	and the second s		
	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	N. F	7 -	, X
3	Pumping Arrangements.	The state of the s	The second secon	
	<ul> <li>Ground Level</li> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/ Manual stopping</li> <li>Pump House Access</li> <li>Terrace level</li> </ul>	N. A		
A constraint and a cons	Discharge of pump  Head of the pump		220 LPM	M·R
The state of the s	Power Supply		30 M	M·R
-	> Auto Starting of pump	- N. A -	-N.A-	-N.A-
-	Captive Water Storage for fire fighting.	The second secon		
The second secon	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	- N. A		
and opening manager	A TALLY VILLE			

old care

	of the state of th			
	> Fire service inlet	-N.A-	_N.A-	-N.A-
	> Access to tank		yes	m.R.
	Overhead Tank capacity	2500 litte	2500 lites	M.R
15	Exit Signage.	yes	yes	W.K
16	Provision of Lifts.	. 3		
and the second s	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N.A		
	• Pressurization of Lift lobby	H		
	<ul> <li>Communication In lift Car</li> </ul>			1
	<ul> <li>Fireman's Grounding Switch</li> </ul>			application and assembly to a characteristic and to a 12 description logic in success
ż	<ul> <li>Lift Signage</li> </ul>			
17	Standby power supply		-	
18	Refuge Area.	7.1		und reflected control offerendelle and plantage and a series of the control of th
	> Total Area	N.A -		
los terminas replas escuapas	> Location			was not and emblood and advantage between the common angles and an emblood
19	Fire Control Room	\$ 900 mm		вом в <sub>то</sub> м интенциального под пред достойнений в под
	Detector System Panel	N.A		
	· Flow Switch Panel			
	PAl System Panel			The same and the s
	Batter backup	: /		2 2
	Building Floor Plans			
20	Special Fire Protection Systems for	N-A		
	Protection of special Risks, if any:	1	4 * ******	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name Daarn vie single yadow

Designation Acristant givisional (control)