GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, **NEW DELHI-110001**

No. F6/MS/DFS/GH/2012/ 9 0 2

Dated: 13/03/12

FIRE SAFETY CERTIFICATE

Certified that the Flora Guest House located at 4179-4181, 1st & 2nd floor, Urdu Bazar, Jama Masjid, Delhi comprised of ground floor (Commercial use), 1st floor (3 guest rooms + one dormitory for 8 beds) and 2nd floor (04 rooms used as residence) was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2374 dated 31-07-2009. The premises was re-inspected by the officer concerned of this department on 05-03-2012 in the presence of Sh. Mohd. Zubair and found that the party has converted the residence rooms in to guest rooms and guest rooms at second floor are 04 guest rooms. Total guest rooms in the guest house 7 guest rooms + one dormitory for 8 beds. The said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of (total 07 guest rooms + one dormitory for 8 beds) with effect from .1.3.1.0.3.1....2012 for period of three years in accordance with rule 36 junless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

CHIEF FIRE OFFICER FOR DIRECTOR DELHI, FIRE SERVICE

Copy to :-

The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New 1. Delhi – 110049

M/s Flora Guest House, 4179-4181, 1st & 2nd floor, Urdu Bazar, Jama Masjid, 2. Delhi - 110006

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

Flora Grest House, 4/79-4/8/, urda Bazak

Jama maszid, Delki-1/0206 1. Name & address of the building: : Great A-1, Residential. 2. Type of Occupancy : New Case/ Renewal/ Addition V 3. Type of Case : Letter No. F6/ms/DFS/GH/09/23+Dated: 31-07-09 4. Details of previous NOC 5. Fire Safety directives letter No : -N.A -: 05-03-2012 6. Date of inspection 7. Name of the Inspecting Officers: DRasm vie singh yadar. A. Do (certed) 8. Name and designation of officers owner: Mohd Zubais. from the building side 9. Year of Construction : 1980 : 62617-19/Addl. C.P./lic. (H) dated 21-12-2011 10. Applicant's letter No. ciscular G. posses Provided at site 5. Minimum Standards on fire Remarks MRINDLE Requirement NO. prevention and fire safety U/R 33 PSS ARCA. Access to building of mtes 09 MIES Mik Road width - N.A -MR · N.A -Gate width Width of internal road N.A -N.A -N.A. Number, Width, Type & Arrangement of Exits M.R one one a. Number of staircases m.R one one Upper Floors NIL NIL NIL Basements b. Width of staircases 90-115 cmg M.R. 90 cmg Upper Floors NIL 11/2 NIL Basements c. Protection of exits - N.A - Fire check door - N.A -• Pressurization e. No. of continuous staircases to terrace g. Width of Corridor - N.A h. Door Size

Flora Guest House, 4/19-4/8/ Usdel Bazar Jama mas Jid, Delhi-110006.

Compartmentation. Fire check door Sealing of electrical shafts Fire Rating of shaft door Water Curtain Fire Dampers Smoke Management System. 30 a/c per hour Basements Natural ventilation m. R 12 a/c per hour Upper floors 5 Fire Extinguishers M.R. Total numbers M-R Types ISI marked MR. IS marking First-Aid Hose Reels. 6 Total numbers on each floor Length of hose reel hose 30 m 30 MZeg 5 mm Nozzle diameter ves. 7 Automatic fire detection and alarming system. N. F. Type of detectors Location of Main Pane! Location of Repeater Panel . Alternate source of power Hooters' Location 8 MOEFA 9 Public Address System. 10 Automatic Sprinkler System. Basement

anta:

Flora Guest House, 4/79-4/8/ Weder Bazak Jamamaszid, Delhi-11006.

	 Upper Floor 	1	^	oldcase
The state of the s	 Sprinkler above false ceiling 	A	A	PSS AR
11	Internal Hydrants			and a fight harmon the confidence and a second seco
	 Size of riser/down-comer Number of hydrants per floor Hose Box 		A	
12	Yard Hydrauts.			
	Total number of hydrantsHose Box	No	A	
3	Pumping Arrangements.			The state of the s
	 Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jeckey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/ Manual stopping 	MA		
	 Pump House Access Terrace level Discharge of pump Head of the pump Power Supply Auto Starting of pump 	180 LAM 30 M top Glectricity	180 LPM 30 MES Electricity	M.R. M.R.
	Captive Water Storage for fire fighting.			The same of the sa
Α,	 Underground tank capacity Draw-off connection 	N.A		

contil:

Flora Guest 1902se 4/79-4/8/ Wedn Bagas Jama margid, Delhi-1/100%

	> Fire service inlet	- N.A -		PSS A	
	> Access to tank			THE WARRANCE AND REPORT OF THE PROPERTY OF THE	
	Overhead Tank capacity	,			
15	Exit Signage.	Required	Provided	M.R	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N.A			
	Pressurization of Lift lobby	4			
	Communication In lift Car				
	Fireman's Grounding Switch		14 B 7		
	• Lift Signage	. 7		and agraphical field of high distribution and a state fluid gustaurine is a see	
17	Standby power supply	N.A-			
18	Refuge Area.				
	> Total Area	N. A	7-		
-	> Location				
10	Fire Control Room				
	Detector System Panel	N.A	W. 1		
	 Flow Switch Panel 				
	PAl System Panel		/		
	Batter backup				
-	Building Floor Plans				
20	Special Fire Protection Systems for Protection of special Risks, if any:	·N. F	4		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Flora Guest House 4179-4/81 Wedu Bazar Jama mas Jid, Delli-1/0006

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name DHARM VIR SINGH YADAW

Designation Assistant Divisional