GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/1102

Dated: 27/03/12

FIRE SAFETY CERTIFICATE

Certified that the Richmond Inn Guest House, located at 9597-9603, Desh Raj Bhatia Marg, Multani Dhanda, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 01 offices), 1st floor (09 guest rooms), 2nd floor (10 guest rooms), 3rd floor (10 guest rooms) and 4th floor (staff kitchen + DG set) Total 29 guest rooms was granted NOC by this department vide letter No. F6/DFS/MS/GH/2009/2104 dated 15-07-2009. The premises was re-inspected by the officer concerned of this department on 15-03-2012 in the presence of Sh. Nipun Gulati and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 29 guest rooms with effect from A. 2. 1.0.3.1...2012 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .27./.٥.٤/.٤.. at New Delhi by.

CHIEF FIRE OFFICER
FOR DIRECTOR
DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049
- 2. Mrs. Maninder Kaur M/s Richmond Inn, 9597 & 9603, Sadar Thana Road, Motia Khan, Paharganj, New Delhi

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

INSPECTION REPORT

1. Name & address of the building: Rickn	nond Inn, 9.	597-9603, Desh K	Bhatia, 10 las					
	lential (Gue		New New York					
	se/ Renewal							
	otter No. F6/DFs/MS/6H/2009/2104 Dated: 15-07-209							
	Fire Safety directives letter No: - N-A -							
	· ·							
n.management in a minimum or of the	Name of the Inspecting Officers: Dharm Vir Singh Yadav (A.D.O)							
8. Name and designation of officers								
from the building side . Sh	i Nipun G	ulati , Manage	2					
9. Year of Construction : 2	007 Starting	s year)						
10. Applicant's letter No.	NIL	distribution of Consensation Service and constitution and consensation and	Old Case					
. Minimum Standards on fire	Create	Provided at site	Remarks					
vo. prevention and fire safety U/R 33	Requirement		PSS Asea					
Access to building	133 Mesc		and the same of th					
Road width	Accessible	09 Mtss	M.R					
• Gate width	-N.A-	_ N, A -	-N. A-					
 Width of internal road 	- N-A -	- N.A-	- N. A -					
Number, Wic'th, Type & Arrangement of	Access a liver and the contract of the contrac	and I account attempted control and another territories and another control and another and another and another and another and another and another another and another another and another an						
a. Number of staircases	The second secon							
Upper Floors		one.	M.L					
Basements	-N.A-	- N.A-	-N.A.					
b. Width of staircase:								
Upper Floors	Administration Plants Associated by Michael (Michael (Mic	122 cms to 127 cms. M.R. -N.A - N.A.						
Basements	-N.A-	-N.A-	-NA-					
c. Protection of exits			againing a later of the spoke one process to the state of the second of					
Fire check door	- N.A							
• Pressurization	- N.A	and the state of t	anticologic mention for the anticologic described factor of electric described and entered as a second class con-					
e. No. of continuous staircases to terrace		One	M.R.					
g. Width of Corridor	N-A-	_ N.A	_N.A.					
h. Door Size	- N. A -	- N. A -	-N.A					

Richmond Jan: 9597-9603

Richmond Jan: 9597-9603

Desh Raj Bhatia malg, maltani Dhandu,

Pahah Gang, New Delhi-110055.

Cor	upartmentation.	State of commission of the State of the Stat				
COI	Fire check door			- Market and registrate in the consequent (MARKET) (1) (2) (2) (3) (2) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4		
	• Sealing of electrical shafts	N. A.		e de ann include an hann an t-aug aibh ainm da agus na dhe a dhe ann a 1907 ann a mar a mhair		
	• Fire Rating of shaft door					
	Water Curtain					
	• Fire Dampers					
4 Sn	noke Management System.					
	Basements	30 a/c per hour	- N.A Natural Ventilation	-X-H-		
	• Upper floors	12 a/c per hour	Natural Ventilation	p).K,		
and the second second second second						
5 Fi	re Extinguishers	1		m D		
	 Total numbers 		Con Type and A.B.C. Type	M.R.		
~ ~	• Types		A.B.C. Type			
	 IS marking 	ISI marked	Yes	M, R,		
6 F	irst-Aid Hose Peels.					
	 Total numbers on each floor 	one	one	M.R.		
	 Length of hose reel hose 	30 m	408	M.R.		
	Nozzle diameter	5 mm	Yes.	M.R.		
7 A	Automatic fire detection and alarming system.					
	• Type of detectors	_ N.A				
	 Location of Main Panel 					
	• Location of Repeater Panel					
	Alternate source of power					
	• Hooters' Location	/		and the second s		
8	MOERA	Required	Provided	m.R.		
9	Public Address System.			_ 4 _		
10	Automatic Sprinkler System.					
	Basement	- N. 1	9 .	Con		

Richmond Inn, 9547 9603, Wesh ng) bromer. Multani Dhanda, Pahar Ganj, New Delhi-110066 Upper Floor Sprinkler above false ceiling 11 Internal Hydrants N. A. Size of riser/down-comer Number of hydrants per floor Hose Box Yard Hydrants. 12 Total number of hydrants Hose Box Pumping Arrangements. 13 N.A Ground Level > Discharge of main Pump > Head of Main pump > Number of main pumps > Jockey Pump out put > Jockey pump head > Standby Pump out put Standby Pump Head > Auto Starting/ Manual stopping > Pump House Access 450 L. P.M. Terrace level 450 LPM > Discharge of pump 30 Mtrs 30 Mtrs. > Head of the pump Flectric Electric > Power Supply - N-A--N.A. > Auto Starting of pump Captive Water Storage for fire fighting.

-N.A.

14

Underground tank capacity

> Draw-off connection

(ontd:

Richmond Gruest House,

9597-9603 Delh Raj Bhatia mars,

Multani Bhandha Pahas Grand Old Case

New Delh: - PSS Area

	> Fire service inlet	-	Provided	m.R.				
	> Access to tank	.	Provided	M.R.				
	 Overhead Tank capacity 	2500 litres	2500 Litnes	m.R.				
15	Exit Signage.	Required	Provided	M.R.				
16	6 Provision of Lifts.							
	Pressurization of Lift Shaft	- N.A-						
8	 Pressurization of Lift lobby 	-N.A -		-				
	* Communication In lift Car	and the control and the design area and another and an incident and an inciden	yes	m·R				
	Fireman's Grounding Switch		yes	M.R				
	• Lift Signage	1	yes	M.R				
17	Standby power supply		D.G. Set; 2.5 KVA	M.R.				
18	Refuge Area.							
	> Total Area	- N. A						
	> Location	/		weren dan Andreas Gregoriaanse van deur den deur anderen van de engleochste van de engleo				
19	Fire Control Room							
	Detector System Panel	- N.A.		5				
	 Flow Switch Panel 		/	and the Park to the Sampanda annual and a second and a second and a second annual and a second annual annual a				
	PA System Panel							
	Batter backup		38					
No.	Building Floor Plans							
20	Special Fire Protection Systems for	N.A		1				
	Protection of special Risks, if any:							

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Confd:

Richmond Inn Guest House, -9597-9603 Desh laj Bhatia Marg, Multoni Dhanda, Pahas Ganj, New Delling

Signature of the Inspecting Officer

Name

Designation

01 - 11 0 1 11 11

Signature of the Inspecting Officer

Name Dhalm Vir Singh Yadav

Designation Assistant Divisional
Officer (Central)