## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No. F6/MS/DFS/GH/2012/ //67

Dated: 29/03/12

### FIRE SAFETY CERTIFICATE

Issued 25/.0.3./.... at New Delhi by.

CHIEF FIRE OFFICER
FOR DIRECTOR
DELHI FIRE SERVICE

Copy to:-

1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi – 110049

2. Shri Harish Kumar M/s Sparkk Dx. Guest House, 9360-67/8, Multani Dhanda, Pahar Ganj, New Delhi

#### Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

# INSPECTION REPORT

1.	Name & address of the building : Sparkk	Dx. Guest Hous	e,9360-678, Mu	ltani Ohanda, P.G.	
2.		dential (Gy		New Del	
3.	Type of Case : New Case	se/Renewal			
4.	Details of previous NOC : Letter No. f6/DFs/ms/GH/2009/391 Dated: 09-02-209				
5.					
6.	Date of inspection	6-03-2012			
7.	Name of the Inspecting Officers :	arm Vir Singe	Yadan (A.D.	0)	
8.	8. Name and designation of officers				
			us (owner)		
9.	9. Year of Construction : 2007 - 2008 (Starting year)				
10	Applicant's letter No. : 6203	1/AZZL. C.P./Lich	D dated New Debi)	the 16/10/4	
5.	Minimum Standards on fire	Cirala&BG. H.	Provided at site	Remarks Old	
No.	prevention and fire safety U/R 33	Requirement Areg.		MR/NMR PSO ARRA	
1	Access to building	·			
	<ul> <li>Road width</li> </ul>	Accessible	06 M ts.	M·R	
	• Gate width	-NA-	N.A -	- NA-	
	<ul> <li>Width of internal road</li> </ul>	N.A.	- MA-	-N.A-	
2	Number, Width, Type & Arrangement of	of Exits			
	a. Number of staircases		The	mR	
	Upper Floors	And the second s	One.	MR	
	* Basements	-N.A	-N.A-	_N.A-	
	b. Width of staircases				
	Upper Floors		123 cms to 125 cm	s - M2-	
	Basements	-N.A-		- N.A-	
	c. Protection of exits	per lateral regions and real-section of the section			
	Fire check door	- N+A-			
	Pressurization		Additional distance in a public control of the second control of t	:	
	e. No. of continuous staircases to terrace	and contact and references to the contact the contact to the conta	One	_m.R	
	g. Width of Corridor	- KA-	- NA -	-NA-	
	h. Door Size	-N.A-	- N.A-	- N.A -	

# Sparkk Dx. Gruest House, 9360-67/8 Mulfani Dhanda, PaharGan, New Delhi-110055

		The second description and the second		1
• Se	nentation.  e check door  aling of electrical shafts  re Rating of shaft door  ater Curtain  are Dampers	_ N-A_		
• 1	Management System.  Basements  Upper floors	30 a/c per hour 12 a/c per hour	_ N.A Natural Ventilation	mR- -MR-
and the state of the same of t	Total numbers Types IS marking	ISI marked	Ten Cortype & water Cortype & A.B.C  Yes	mR. M.K M.K.
	Aid Hose Reels.  Total numbers on each floor  Length of hose reel hose  Nozzle diameter	00e 30 m 5 mm	One Yes	m.R. — m.R
	matic fire detection and alarmin  Type of detectors  Location of Main Panel  Location of Repeater Panel  Alternate source of power  Hooters' Location	ig system.	V A	
9 Pu	OEFA ablic Address System.	Yes Yes	1 Provided Provided	M.R.
10 A	utomatic Sprinkler System.  Basement	_N. A		Contd.

Sparkk Dx. Gruest House, 9360-67/8, Multeni Dhanda,

	<ul> <li>Upper Floor</li> </ul>	N <sub>5</sub> A		
	Sprinkler above false ceiling	- N. A		
11	Internal Hydrants	10.14	6	
	<ul> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> </ul>	- M-A	1	
	Hose Box			
12	Yard Hydrauts.	and desired a second or the second or the second of the se		
12	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	- N. F	7	
13	Pumping Arrangements.	The state of the s		
	<ul> <li>Ground Level</li> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Auto Starting/ Manual</li> <li>stopping</li> </ul>	- W - A		
	<ul><li>Pump House Access</li><li>Terrace level</li></ul>			
	Discharge of pump	450 LPM	450 LPM	m.R.
	Head of the pump	30 Mirs	30 Mtrs.	-MR
ς	Power Supply	Electric	Electric	mk 1
	> Auto Starting of pump	- NA-	~ N. A -	- N. A
14	Captive Water Storage for fire fighting.		The first terminate and the contraction of the contraction of the contraction of	
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	- N. A		

Contd.

# Sparkk Dx. Gruest House 9360-67/8 Multani Drandar, Parton Grain, New Delly-110055



	> Fire service inlet		Provided	-MR-
,	> Access to tank		Yes	-MR.
	Overhead Tank capacity	and the first facilities and the second seco	2500 Uters	mR.
15	Exit Signage.	Required	Provided	M.R.
16	Provision of Lifts.			miglade des amen un sector de proprio constant de sego aspectos constantes de sector de se
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	-N-A		•
	<ul> <li>Pressurization of Lift lobby</li> </ul>	- MA	The state of the s	
	<ul> <li>Communication In lift Car</li> </ul>		Provided	m.K.
Programme of the Control of the Cont	Fireman's Grounding Switch		Provided Provided	M.R.
	<ul> <li>Lift Signage</li> </ul>		Provided	mR.
17	Standby power supply		D.G. Set 82.5 KNY	M.R.
18	Refuge Area.			
And the second second second second	> Total Area	- MA-	/	THE PARTY OF THE P
	> Location			may may take the distributed the control of the control described and described and described and an extension of the control
19	Fire Control Room	2		and a superfining against the second second production who can decrease one one
	Detector System Panel	N-A		
	<ul> <li>Flow Switch Panel</li> </ul>			THE THE THE STATE OF THE STATE
	PAl System Panel			
	Batter backup		1	
No.	Building Floor Plans			
50	Special Fire Protection Systems for	N.A-		
	Protection of special Pisks, if any:			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Deihi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

Spark R. Dr. - 9360-67/8,
Multani Danda, Pahar Gang, Delly-110055

Signature of the Inspecting Officer

Name

Designation

Signature of the Inspecting Officer

Name Dhaen Vir Singh Yadan

Designation Assistant Divisional
Offices (central)

,