#### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI

No: F.6/DFS/MS/GH/2012/ 113 8

Dated: 28/03//2

### FIRE SAFETY CERTIFICATE

Issued .28./.0.3./.!... at New Delhi by.

CHIEF FIRE OFFICER
FOR DIRECTOR
DELHI FIRE SERVICE

Copy to :-

- The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi - 110049
- 2. Shri Parveen Kumar Chabbra M/s. Surya Plaza Guest House, 2471, Nalwa Gali, Pahar Ganj, New Delhi

#### Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

## (1)

# INSPECTION REPORT

1.	Name & address of the building : Susya	Plaza Guest	House, 2471, Nal	wa Gali, Pahas G			
	Type of Occupancy : Reside	ential (Gruest	House)	700			
3.	Type of Case : New Cas	e/Renewal					
4.	Details of previous NOC : Letter No. F6/As/OFS/GH/2008/3550 Dated: 24-12-2008						
5.	Fire Safety directives letter No :						
6.	Date of inspection 15-03-2012						
7.	Name of the Inspecting Officers: Dhalm Vir Singh Yadav (A.D.O.)						
	Name and designation of officers						
	from the building side : Mr. Parkash Panday (Manager)						
9.	Year of Construction : 2	008 (starting	year)	ingenier werden der der einem einem gehalte der Stadt von der			
10	Applicant's letter No. : N			Old Case			
3.	Minimum Standards on fire	Circules Gr. H.	Provided at site	Remarks			
No.	prevention and fire safety U/R 33	Requirement		MR PSS ASE			
	Access to building	and the second s	de a commune a como como como como como como como co				
	Road width	Accessible	06 Miss	m.R.			
	× ×	-N.A-		-N.A.			
	• Gate width	_ N-A -	-N.A-	- N.A.			
as sylveste strander	Width of internal road	_ /V-H =					
2	Number, Width, Type & Arrangement of Exits						
	a. Number of staircases			M.R.			
	<ul> <li>Upper Floors</li> </ul>		One.	-N.A-			
	• Basements	-N.A-	_ M. A-	-10.00			
	b. Width of staircases						
	Upper Floors		1.25 MArs	m·R,			
	Basements	N. A	- N.A -	- N-A -			
	c. Protection of exits	- existence del filmando - reporte describir con describir del production de la constitución de la constituc					
The state of the s	Fire check door	- N.A	the second secon				
	Pressurization						
	e. No. of continuous staircases to terrace		One	m.R.			
	n	_N.A_	-N.A-	_N.A_			
	g. Width of Corridor	_ N. A -	-N.A -	-N-A-			
	h. Door Size		And the second s	Contd;			

Surya Plaza Guest House, 2471 Natura Gali-Pakar Gang, new Delti-1/02/5

	<ul><li>Upper Floor</li><li>Sprinkler above false ceiling</li></ul>	- N.A -		
11	Internal Hydrants	Annual Annual September 14 particular and a september 14 annual se	The state of the s	The second secon
	<ul> <li>Size of riser/down-comer</li> <li>Number of hydrants per floor</li> <li>Hose Box</li> </ul>	N.A.		
12	Yard Hydrants.	The second secon		
The state of the s	<ul><li>Total number of hydrants</li><li>Hose Box</li></ul>	- N.A -		
13	Pumping Arrangements.	The state of the s		
	<ul> <li>Ground Level</li> <li>Discharge of main Pump</li> <li>Head of Main pump</li> <li>Number of main pumps</li> <li>Jockey Pump out put</li> <li>Jockey pump head</li> <li>Standby Pump out put</li> <li>Standby Pump Head</li> <li>Anto Starting/ Manual stopping</li> <li>Pump House Access</li> </ul>	N. A		
	<ul><li>Terrace level</li><li>Discharge of pump</li></ul>	450 LPM	450 LPM	M.R.
The state of the s	> Head of the pump	. 30 MARS	30 Mtss	M-Rossia
	Power Supply	Electric,	Electric	MX
14	Auto Starting of pump  Captive Water Storage for fire fighting.	- N.A.	-N-A -	-N.A -
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> </ul>	W.A +		

conta

surya plaza Guest house, 2471 Walwa Goli, Pakar Gang, wen soldi

	and the second contraction of the properties of the second contraction				
	> Fire service inlet		P-Earided.	M.R.	
	Access to tank		yes.	m.R	
and the second s	Overhead Tank capacity		5000 lites	m·R	
15	Exit Signage.	lequised.	Peridad	m-R	
16	Provision of Lifts.				
	Pressurization of Lift Shaft	N. A		and a first and employed a rest and a supply and a standard and an employed at 1 a 2 a 2 a 2 a 2 a 2 a 2 a 2 a	
	Pressurization of Lift lobby			ett de Bandacian en	
	<ul> <li>Communication In lift Car</li> </ul>			The state of the s	
(4.			was a see and a see an analysis and a see		
	Theman's Grounding Switch				
	<ul> <li>Lift Signage</li> </ul>			distribution of the state of th	
17	Standby power supply		D.G. set 12.5 KVA	m.R	
10	Refuge Area.		123 200	and district the context to the context of the cont	
	> Total Area	N.A			
	> Location			we se stationaries paid nonlinearies and another and an experiment in the	
19	Fire Control Room				
	Detector System Panel	N.A.			
	<ul> <li>Flow Switch Panel</li> </ul>			odis Ele Trip E' de Ministeres alla sincia de conserva	
	PAi System Panel			where the time the for electric streams, the same agreed special contains a se-	
	Batter backup				
**	Building Floor Plans			Analysis and the Management of the stage of	
20	Special Fire Protection Systems for	N.A			
	Protection of special Risks, if any:	5, 1	30.7 XI		
at Confederação do Rigido - com			2 2		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.

surge plaga Guest house 2471, Nalva Gali, Pakos Gang (5) New Delle: -110045. Signature of the Inspecting Officer Signature of the Inspecting Officer Name Dhakm vie single yadar Name Designation Assistant Divisional offices (central). Designation