GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

NO. F6/OFS/MS/ GH/2012/1197 DATED: 02/04/12

FIRE SAFETY CERTIFICATE

Certified that the M/s Parkland Hospitality Ltd, E-19, Defence Colony New Delhi110024 comprised of basement, ground plus three upper floors was granted NOC by
this department vide letter no. F6/MS/DFS/GH/2008/3126 Dated 12.11.2008. The
premises re-inspected by the officers concerned of Fire Service on 29.2.2012 in the
presence of Mr. Pintu (Manager), of the guest house and that the building is fit for
occupancy class A "Residential & Lodging building" (ground floor reception and 6
guest room, first floors 9 guest rooms, second floors 11 guest rooms and 3rd floor 11
guest rooms) with effect from.

Chief Fire Officer
For Director
Delhi Fire Service

Copy To:-

- 1. The DHO(South Zone), Office of Deputy Health Officer, M.C.D. Health Department South Zone, Green Park, New Delhi.
- 2. The Director, M/s Parkland Hospitality Ltd, E-19, Defence Colony New Delhi-110024.

Conditions for the validity of fire safety certificate

- 1. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- 2. Building Sanctioning authority may verify any deviation with regard to the construction/occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- 3. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- 4. The basement shall be used strictly as per the provisions of Building Bye laws.
- 5. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules-2010. The form is available on www.dfs.delhigovt.nic.in

		INSPECT	TION REPO)RT			
1	Name & address of the building	INSPECTION REPORT M/s Parkland Hospitality Ltd, E-19, Defence Colony New Delhi-110024					
2	Type of Occupancy	Residentia	al & Lodging ".	A"			
3	Type of case	Renewal					
4	Details of previous NOC	F6/MS/DFS/GH/2008/3126 Dated 12.11.2008					
5	Fire safety directives letter No						
6	Date of inspection						
7	Name of the inspecting Officers :	D.O. (South) D.P. Bhardwaj,					
,	Name and designation of officers	Mr.Pintu (I		iwaj,			
8	from the building side						
9	Year of construction	Rooms Detail (ground floor reception and 6 gues room, 1st floor 12 guest rooms, 2nd floor 13 guest rooms and 3rd floor 13 guest rooms)					
			-	(Basement, upper floors		Ground+Three	
10 S. N		Nil		Nil			
5. N	and fire safety U/R 33	NBC R	equirement	Prov	rided at site	Remarks MR / NMR	
1	Access to building				0		
	1) Road width	15 mtrs	· ·	Provided		MR	
	2) Gate width	N/A		N/A		N/A	
	3) Width of internal road	N/A		N/A		N/A	
2	Number, width Type & arrangement of	exits				-	
	a. Number of staircases						
	1 Upper fleers	0.11					
	Upper floors basements	2 Nos.		Provided		MR	
	b. Width of staircase	2 Nos		Provided		MR	
	1. Upper floors	1.25 Mtr		125 cm &	1.30 Provided	MR	
	2. basements	1.25 Mtr		(125 cm 8		MR	
	c. Protection of exits					1000	
	1. Fire check door	N/A		N/A		N/A	
	2. Pressurization	N/A		N/A		N/A	
	d. No. of continuous staircase to terrace	Requied		1 Nos. Sta	irs Provided	MR	
	e. Width of corridor	N/A	N/A			N/A	
	f. Door size	1 Mtr		Provided		MR	
3	Compartmentation.						
	1. Fire check door	N/A		N/A Provided		N/A	
	2. Sealing of electrical shafts	Required				MR	
	3. Fire Rating of shaft door	N/A		N/A		N/A	
	4. water curtain	N/A		N/A		N/A	
4	5. Fire dampers Smoke Management system.	N/A		N/A		N/A	
	basement	30 a/c per hour 12 a/c per hour		Exhust Fans Provided		MR	
		-		Noticella	ntilation	ا	
5	upper floors			Natural Ve	nillatiON	MR	
5	Fire Extinguishers total numbers			12 Nos		MR	
	Types	1		ABC, Co2		MR	
	ISI marking	ISI		Yes		MR	
6	First-Aid Hose Reels.	101		1100		livii t	
	total numbers on each floor	One		Provided		MR	
	Length of Hose reel hose	30 m		Provided		MR	
	Nozzle Diameter	5 mm		Provided	ja	MR	

7	Automatic fire detection and alarming	g system	E		
	Type of detectors	Required	Provided	MR	
	location of Main Panel	Required	Ground Provided	MR	
	location of Repeater panel	N/A	N/A	N/A	
	Alternate source of power	Required	Battery Backup Provided	MR	
	hooter's location	N/A	N/A	N/A	
8	MOEFA	Required	Provided	MR	
9	Public Address System.	Required	Provided	MR	
10	Automatic Sprinkler System.				
	basement	Required	Provided	MR	
	upper floors	N/A	N/A	N/A	
	sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants			1. 7	
	Size of riser/down-corner	100 mm	Provided	MR	
	Number of Hydrants per floor	One	Provided	MR	
	hose Box	One	Provided	MR	
12	Yard Hydrants.		į. reviada	TWO C	
	total number of hydrants	N/A	N/A	N/A	
	hose box	N/A	N/A	N/A	
13	Pumping arrangements	1.4	11.3/1.3	114/71	
	1. Ground level			1	
	a. Discharge of main Pump	N/A	N/A	N/A	
	b.Head of main pump	N/A	N/A	N/A	
	c.Number of main pumps	N/A	N/A	N/A	
	d.jockey pump out put	N/A	N/A	N/A	
	e.jockey pump head	N/A	N/A	N/A	
	f. Standby Pump output	N/A	N/A	N/A	
	g.Stanby Pump head	N/A	N/A	N/A	
	h.Auto Starting/Manual stopping	N/A	N/A	N/A	
	pump house access	N/A	N/A	N/A	
	2.Terrace level	IN/A	IN/A	IN/A	
	2.1011406 16461	900 LPM	900 LPM Provided	IMR	
	a. Discharge of pump		ood El William	1	
	b. head of the pump	40 mtr	Provided	MR	
	c. Power supply	Required	Provided	MR	
	d. Auto starting of pump	Required	Provided	MR	
			p. rovided	1,4,1,4	
14	Captive water storage for fire fighting				
	Underground tank capacity	Required	20,000 Ltr Provided	MR	
	a. Draw-off connection	N/A	N/A	N/A	
	b. fire service inlet	N/A	N/A	N/A	
	c.Access to tank	N/A	N/A	N/A	
	Over head tank Capacity	Required	10000 Ltr Provided	MR	
15	Exit Signage.	Required	Provided	MR	
16	Provision of lifts.		2		
	a. Pressurization of lift shaft	N/A	N/A	N/A	
	b. pressurization of lift lobby	N/A	N/A	N/A	
	c. communication in lift car	Required	Provided	MR	
	d. Fireman's grounding switch	Required	Provided	MR	
	e. Lift signage	N/A	N/A	N/A	
17	Standby power supply	Required	Provided	MR	
18	Refuge Area.	Not Required			
	total area				
	location				

19	Fire control room					
	a. detector system Panel	N/A	N/A	N/A		
	b. Flow switch Panel	N/A	N/A	N/A		
	c. PA system Panel	Required	Provided	MR		
	d. Batter backup	Required	Provided	MR		
	e. Building floor plans	N/A	N/A	N/A		
20	Special Fire Protection systems for protection of special risks, if any:					
		•				

The fire protection systems provided in the building were checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the

Accordingly DFA is put up for your approval and signature please

Signature of the inspecting officer

Name D. P. Bhardwaj

Designation : Divisional Officer (South)