## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

NO.F6/DFS/MS/EH/2012// / 3 \( \)

Dated: 08/01/20/7

## **FIRE SAFETY CERTIFICATE**

Certified that Hotel Sarvana Bhavan, (Restaurant) run by M/s. Thanigai Murugan Restaurants (P) Ltd., located at P-13/90 Connaught Circus, New Delhi-110001 comprised of ground, Mezzanine + one upper floor, Restaurant is on Ground + Mezzanine Floor owned / occupied by Sarvana Bhavan (Thanigai Murugan Restaurants P Ltd.) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service rules, 2010 and verified by the officers concerned of Delhi fire service on 24.12.2012 in presence of Shri R. Sami Singh, Senior Manager of the guest house and that the building/premises is fit for occupancy class D Assembly Building Sub Division D-3 with effect from 8/1/13 for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued on  $\frac{8}{1/\sqrt{3}}$  at New Delhi by.

**Chief Fire Officer** Delhi Fire Service

Copy to: -

1. M/s. Hotel Sarvana Bhavan, P-13/90 Connaught Circus, New Delhi-110001.

## Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss to life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

## **INSPECTION REPORT**

1. Name & address of the building :Hotel Sarvana Bhawan (restaurant), (Prop: Thanigai Murugan Restaurants (P) ltd, P-13/90, Connaught Circus, New Delhi

2. Type of Occupancy

: Eating House

3. Type of Case

: New case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No : N/A

6. Date of inspection

: 24-12-2012

7. Name of the Inspecting Officers: Dr. Than Singh Sharma, DCFO(NDZ), Dharamvir Singh Yadav, DO(CD) and M.K.Chattopadhyay, ADO(CC)

8. Name and designation of officers

from the building side

: R.Swami Singh, Sr. Manager

9. Year of Construction

:1937

10. Applicant's letter No.

: HSB/DELF/011 dated 20-12-2012

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	<ul><li>Road width</li><li>Gate width</li></ul>	06 mts	More than 06 mts  Directly accessible	MR MR		
	Width of internal road	N/A	from the road N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases	_	_ ''	-		
	• Upper Floors	02	02	MR		
	• Basements	N/A	N/A	N/A		
	b. Width of staircases		·			
	• Upper Floors	1.50 mts	1.65mts, 1.15 mts	MR		
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A		
	c. Protection of exits	-	_	_		
	<ul><li>Fire check door</li><li>Pressurization</li></ul>	N/A	N/A	Mark Care Sales Care Care Care Care Care Care Care Care		
		N/A	N/A			
	e. No. of continuous staircases to terrace	01	01(back side)	MR		
	g. Width of Corridor	N/A	N/A			
	h. Door Size	1.5 mts	Main gate-1.85 mts  Back side gate-1,5 mts	MR		

3	Compartmentation.		-		
	Fire check door	N/A	N/A	100 MI AND	
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A		
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A		
	<ul> <li>Water Curtain</li> </ul>	N/A	N/A	NO NO DE	
	• Fire Dampers	N/A	N/A		
4	Smoke Management System.				
	• Basements	30 a/c per hour	N/A	N/A	
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour			
			Provided	MR	
5	Fire Extinguishers				
	<ul> <li>Total numbers</li> </ul>	05	Provided	MR	
	• Types	ABC, CO2, W.CO2	Provided	MR	
	IS marking	ISI marked	Provided	MR	
6	First-Aid Hose Reels.				
	<ul> <li>Total numbers on each floor</li> </ul>	01	Provided	MR	
	• Length of hose reel hose	30 m	Provided	MR	
	Nozzle diameter	5 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	• Type of detectors	N/A	N/A		
	• Location of Main Panel	N/A	N/A		
	• Location of Repeater Panel	N/A	N/A		
	• Alternate source of power	N/A	N/A		
	Hooters' Location	N/A	N/A		
8	MOEFA	Required	Provided	MR	
9	Public Address System.	N/A	N/A	N/A	
10	Automatic Sprinkler System.				
	• Basement	N/A	N/A	N/A	
	• Upper Floor	Required	Provided	MR	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11 Internal Hydrants					
	Size of riser/down-comer	N/A	N/A	N/A	

	Number of hydrants per floor	N/A	N/A	N/A	
	• Hose Box	N/A	N/A	N/A	
12	Yard Hydrants.			- 1// 1	
	<ul> <li>Total number of hydrants</li> </ul>	N/A	N/A	,	
10	Hose Box	N/A	N/A		
13	Pumping Arrangements.				
	<ul> <li>Ground Level</li> </ul>	N/A	N/A		
	<ul> <li>Discharge of main Pump</li> </ul>	N/A	N/A		
	<ul> <li>Head of Main pump</li> </ul>	N/A	N/A		
	Number of main pumps	N/A	N/A		
	<ul> <li>Jockey Pump out put</li> </ul>	N/A	N/A		
	Jockey pump head	N/A	N/A		
	Standby Pump out put	N/A	N/A		
	Standby Pump Head	N/A	N/A		
	Auto Starting/ Manual	N/A	N/A		
	stopping	N/A	N/A		
	<ul><li>Pump House Access</li><li>Terrace level</li></ul>	N/A			
	<ul> <li>Discharge of pump</li> </ul>		N/A		
	Head of the pump	450 LPM	450, 180 LPM	MR	
	Power Supply	40 mts	Provided	MR	
	<ul> <li>Auto Starting of pump</li> </ul>	Required	provided	MR	
4	Captive Water Storage for fire fighting	Required	Provided	MR	
	Underground tank capacity				
	<ul> <li>Draw-off connection</li> </ul>	N/A	N/A		
	Fire service inlet	N/A	N/A		
	Access to tank	N/A	N/A		
	Overhead Tank capacity	N/A	N/A		
		10,000 Its	Provided	MR	
	Exit Signage.	Required	Provided	MR	
6 P	Provision of Lifts.				
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	N/A	N/A	N/A	
	<ul> <li>Pressurization of Lift lobby</li> </ul>	N/A	N/A	N/A	
	The state of the s				

	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A	N/A	N/A
	Lift Signage	N/A	N/A	N/A
17	Standby power supply	Required	Provided	MR
18	Refuge Area.			
	Total Area	N/A	N/A	Mar No. 600 No. 500 No. 500 No. 500 No. 500 No.
	Location	N/A	N/A	
19 Fire Control Room				
	Detector System Panel	N/A	N/A	THE NEW YORK HAS AND HOW MAD NOW AND AND
	<ul> <li>Flow Switch Panel</li> </ul>	N/A	N/A	THE RES AND AND AND AND AND AND AND AND
	PA System Panel	N/A	N/A	49 90 00 00 100 100 100 100 100 100 100
	Batter backup	N/A	N/A	NOT THE THE THE THE THE THE THE THE THE TH
	Building Floor Plans	N/A	N/A	
20	Special Fire Protection Systems for	Required	One ABC type	MR
	Protection of special Risks, if any:		fire extinguisher	
			found Provided	
			near elect. panel	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Dr. Than Singh Sharma DCFO(NDZ)

Dharamvir Singh Yadav DO(CD) M.K.CHATTORADHYAY Asstt. Div. Officer(CC)