## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DELHI-110001**

NO.F6/DFS/MS/school/2013/178

Branch Medical 

Dated: 9/1/2013

## **FIRE SAFETY CERTIFICATE**

Certified that Bengali Sr. Secondary School, 22A, Shyam Nath Marg, New Delhi-110054 comprised of two blocks. Block-1 is comprised of ground floor plus one upper floor and block-2 is comprised of ground floor only was inspected by the officer concerned of this department on 03.12.2012 in presence of Mr. A.K. Sinha (Chairman) & Mrs. Roma Mazumdar, Principal of the school and found that the School management have complied with the fire prevention and fire safety requirements in accordance with the Circular No-F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01-03-2011 issued by the Directorate of Education dated 01-03-2011 and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on 9/1/2013 at New Delhi by.

**Chief Fire Officer** Delhi Fire Service

Copy to: -

1. The Director of Education, Govt. of NCT of Delhi, Old Secretariat, Delhi

2. The Principal, Bengali Sr. Sec. School, 22A, Shyam Nath Marg, New Delhi-110054

## Conditions for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning
- 5. The certificate may not be treated in any case for regularization of unauthorized
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available www.dfs.delhigovt.nic.in

## **INSPECTION REPORT**

1.	Name & address of the building: Benderal Street Str	gali Sr. Seco	ndary school,	22 A, Shamnet	
2	. Type of Occupancy : :	cational	marg,	civil lines, Dell	
3	. Type of Case : New Ca	ase/ Renewal		-	
4	d:				
5	. Fire Safety directives letter No :	<b>—</b>			
6	. Date of inspection : 28	112/2012		1	
7	. Name of the Inspecting Officers: Share	·m. K. Chatte	opadhyay, A	00 (HO)	
8					
	from the building side :	i A.K. Sinha,	, Chairman, Smt	Kama Mayumla	
9	. Year of Construction :	1968		principal	
1(	O. Applicant's letter No. : 65	20/3 delis.	22/8/2012	×	
S.	Minimum Standards on fire	NBC/circulo	Provided at site	Remarks	
No.	prevention and fire safety U/R 33	Requirement	- 1 V	MR/NMR	
1	Access to building				
	Road width	06mt	OFmt	mR	
	• Gate width	4.5mt	6 ont	mp	
	Width of internal road	66m+.	More than 06mi	me	
2	Number, Width, Type & Arrangement	of Exits			
	a. Number of staircases	-	9 H A	-	
	Upper Floors	03 NB	03 MB	MR	
	Basements	MA	MA	MA	
	b. Width of staircases		- 1 3	-	
	Upper Floors	1.5m+	1.4	MR	
	• Basements	MA	MA	MA	
	c. Protection of exits	N/A	N/A	N/A	
	Fire check door	N/A	N/A	N/A	
	Pressurization	N/A	N/A	N/A	
	e. No. of continuous staircases to terrace	02	02	m R	
	g. Width of Corridor	1.5m+	2.001	me me	
	h. Door Size	N/A	N/A	N/A	
		N/A	N/A	N/A	
3	Compartmentation.	Not required		1	

The state of the s

		Vol.			
	Fire check door	N/A	N/A	N/A	
	Sealing of electrical shafts	N/A	N/A	N/A	
	• Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
	• Fire Dampers	N/A	N/A	N/A	
	Smoke Management System.	Low-rise bldg, 1	Not required		
	• Basements	30 a/c per hour	N/A	N/A	
	• Upper floors	12 a/c per hour			
			N/A	N/A	
	Fire Extinguishers	A pick	1		
	• Total numbers (5 No.	1823	provided	MR	
	· Types ABC lyke	530 403	provider	MR	
:	IS marking	ISI marked	provides	MR	
	First-Aid Hose Reels.	Not required			
	Total numbers on each floor	02	provided	mr	
	• Length of hose reel hose	30 m		M P.	
	Nozzle diameter	5 mm	provided	MZ	
Α	Automatic fire detection and alarming system. Not required				
	• Type of detectors	N/A	N/A	N/A	
	Location of Main Panel	N/A	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	N/A	
	Alternate source of power	N/A	N/A	N/A	
	Hooters' Location	N/A	N/A	N/A	
3	MOEFA	N/D	MA	MA	
)	Public Address System.	MA	MA	MA	
10	Automatic Sprinkler System				
	Basement	N/A	N/A	N/A	
	Upper Floor	N/A	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	N/A	
11	Internal Hydrants Not required				
	Size of riser/down-comer	El loomon	provider	NA MR	

	<ul><li>Number of hydrants per floor</li><li>Hose Box</li></ul>	01	poorde	MR	
		1.A 01	1 poorda	Me Me	
2	Yard Hydrants.				
	Total number of hydrants	N/A	N/A	N/A	
	Hose Box	N/A	N/A	N/A	
13	Pumping Arrangements				
	Ground Level	Mas	no	70	
	<ul><li>Discharge of main Pump</li></ul>	mo	m m	MA	
	> Head of Main pump	MA	MA	MA	
	Number of main pumps	N/A	N/A	N/A	
	Jockey Pump out put	N/A	N/A	N/A	
	Jockey pump head	N/A	N/A	N/A	
	> Standby Pump out put	N/A	N/A	N/A	
	Standby Pump Head	N/A	N/A	N/A	
	➤ Auto Starting/ Manual		. **		
	stopping	N/A	N/A	N/A	
	Pump House Access	N/A	N/A	N/A	
	Terrace level	N/A	450 LPM	MR	
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>		40 mt	MR	
	> Power Supply	N/A	70 311		
	Auto Starting of pump	N/A	Provided at GF	Me	
14	Captive Water Storage for fire fighting				
	Underground tank capacity	N/A	MA	MA	
	> Draw-off connection	MA	MA	79	
	Fire service inlet	Mo	MA	no	
	> Access to tank	MA	MA	75	
	Overhead Tank capacity	20,000 lh.	provided	MR	
15	Exit Signage.	Required	provided	MR	
16	Provision of Lifts. Not Applicable				
CONTRACTOR OF STREET	Pressurization of Lift Shaft	N/A	N/A	N/A	
	Pressurization of Lift lobby	N/A	N/A	N/A	



	Communication In lift Car	N/A	N/A	N/A	
	• Fireman's Grounding Switch	N/A	N/A	N/A	
	• Lift Signage	N/A	N/A	N/A	
17	Standby power supply	MA	MA	MA	
18	Refuge Area.				
	> Total Area	N/A	N/A	N/A	
	> Location	N/A	N/A	N/A	
19	Fire Control Room				
	Detector System Panel	N/A	N/A	N/A	
	Flow Switch Panel	N/A	N/A	N/A	
	PA System Panel	N/A	N/A	N/A	
TO THE PROPERTY OF THE PROPERT	Batter backup	N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	01 ABC life fri exterpushu pomole freau Elect-panel	MR	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules as per the directives of Education Department vide Circular No. F.16/Estate/CC/Fire Safety/2011/3298-3398 dated 01-03-2011 it is recommended to grant fire safety certificate under rule 35 of the Delhi Fire Service rules 2010 /issue shortcomings as noted at serial numbers.

Note:-The school building is comprised of Im blocks-Block-1 is Comprised of

Ground Lone upper floor and Block-2 is Comprised of Ground floor only

having total 47 rooms . The student are less than 45 in each class as

stated by the Principal vide letter dated 28/12/2012.

Do Ceo on poons

Signature of the Inspecting Officer Name (M.K. CHATTOPADHYAY) Designation:- Assistant Divisional Officer