

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI  
HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE  
NEW DELHI- 110 001


No. F6/DFS/MS/EH/2013/205

Dated 11/01/12

**FIRE SAFETY CERTIFICATE**

Certified that the Pind Balluchi Restaurant Located at 410, Karkardooma Village, Vikash Marg, Delhi-96, comprised of basement ground plus two upper floors was granted NOC by this department vide letter No.F.6/DFS/MS/EH/09/1866 dated 25.06.09. The premises was re-inspected by the officer concerned of this department on 22.12.12 in the presence of Mr. Devender Thapa (Manager), and found that the Assembly Building have deemed complied with the fire prevention and fire safety requirements in accordance with the earlier directives and that the building is fit for occupancy Group D "(Eating House)" with effect from ...11/01/12... renewed for a period of three years, subject to conditions printed overleaf.

Issued on..... 11/01/12 ..... at New Delhi by



Chief Fire Officer  
Delhi Fire Service

OC  
RSD  
9.1.13

Copy to-

1. The Deputy Health Officer,  
Shahdara (South) Zone, EDMC,  
Health Department, Shahdara South Zone,  
Karkardooma, Delhi
2. Mr. Devender Thapa  
Pind Balluchi Reataurant,  
410, Karkardooma Village, Delhi 96.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.
2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.
3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.
4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
5. This NOC may not be treated in any case for regularizations of unauthorized construction unauthorized use of land if any.
6. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on [www.dfs.delhigovt.nic.in](http://www.dfs.delhigovt.nic.in)
7. Basement shall be used as per BBL 1983.

1 RN-4

**INSPECTION REPORT**

1. Name & address of the building : Pind Balluchi Restaurant, 410, Karkardooma Village, Vikash Marg, Delhi-96
2. Building is comprised of : Basement, G+2
3. Type of Occupancy : Assembly
4. Type of Case : Renewal
5. Details of Previous NOC : F6/DFS/MS/EH/09/1866 Dated 25.06.09
6. Fire Safety directives No : Old Circular
7. Date of Inspection : 22.12.12
8. Name of the Inspecting Officer : ADO Suresh Singh
9. Name of the designation of Officer  
From the building side : Mr. Devender Thapa (Manager)
10. Year of Construction : 2000
11. Applicant's letter No : Nil

S.No	Minimum Standards on fire prevention and fire safety U/R33	Requirement	Provided at Site	Remarks MR/NMR
1.	Access to building			
	Road width	6 m	24 m	MR
	Gate width	.....	.....	.....
	Width of internal road	.....	.....	.....
2.	Number, Width, Type and Arrangement of Exits			
	a. Number of Staircases	2 no.	2 no.	MR
	Upper Floor	.....	1 no.	MR
	Basement	1 no.	1 no.	Old Accepted
	B. Width of Staircases	.....	1.1 & 1.2 m	Old Accepted
	Upper Floor	.....	.....	.....
	Basement	.....	1 m	Old Accepted
	c. Protection of exits	.....	.....	.....
	Fire check door	.....	.....	.....
	Pressurization	.....	.....	.....
	e. No. of continuous staircases to terrace	.....	.....	.....
	g. Width of Corridor	.....	.....	.....
	h. Door Size	1 m	1 m & 1.5 m	Old Accepted
3.	Compartmentation.	Required	Provided	
	Fire check door	.....	.....	.....
	Sealing of electrical shafts	.....	.....	.....
	Fire rating of shaft door	.....	.....	.....
	Water curtain	.....	.....	.....
	Fire Dampers	.....	.....	.....
4.	Smoke Management System.		Provided	
	Basement	.....	Provided	Old Accepted
	Upper for	.....	provided	Old Accepted
5.	Fire Extinguisher			
	Total numbers	10 no.	10 no.	MR
	T types	ABC & Co2	ABC & Co2	MR
	IS marking	ISI marked	ISI marked	MR

6	First-aid-Hose Reels.			
	Total numbers of each floor	1no.	Provided	MR
	Length of hose reel hose	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarming system.			
	Type of detectors	Heat	Provided	MR
	Location of main panel	.....	.....	.....
	Location of repeater panel	.....	.....	.....
	Alternate source of power		Provided	.....
	Hooters's location	.....	.....	.....
8	MOEFA	Required	Provided	MR
9	Public address System.	.....	.....	.....
10	Automatic Sprinkler System.			
	basement	Required	Provided	MR
	upper floor	Required	Provided	MR
	sprinkler above false ceiling	Required	Provided	MR
11	Internal Hydrants			
	size of riser/down-comer	100 mm	100 mm	MR
	Number of hydrants per floor	1 no.	1 no.	MR
	Hose Box	1 no.	1 no.	MR
12	Yard Hydrants			
		N/A		
	Total number of hydrants	.....	.....	.....
	Hose Box	.....	.....	.....
13	Pumping Arrangements.			
	Ground Level	.....	.....	.....
	Discharge of main Pump	.....	.....	.....
	Head of Main Pump	.....	.....	.....
	Number of main pumps	.....	.....	.....
	Jockey pump out put	180 LPM	180 LPM	Old Accepted
	Jockey pump head	.....	.....	.....
	Standby pump out put	.....	.....	.....
	Standby pump Head	.....	.....	.....
	Auto Starting /Manual stopping	.....	.....	.....
	Pump House Access	.....	.....	.....
	Terrace Level			
	Discharge of pump	450 LPM	450 LPM	Old Accepted
	Head of the Pump	40 m	40 m	Old Accepted
	Power supply	.....	.....	.....
	Auto Starting of pump	.....	.....	.....

IRN-6

Pind Balluchi Restaurant, 410, Karkardooma Village, Vikash Marg,

14	Captive Water Storage for Fire Fighting.			
	Underground tank capacity	.....	.....	.....
	Draw-off connection	.....	.....	.....
	Fire service inlet	.....	.....	.....
	Access to tank	.....	.....	.....
	Overhead Tank capacity	5,000 Liters	5,000 Liters	Old Accepted
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	Pressurization of Lift Shaft	-----	-----	-----
	Pressurization of Lift lobby	-----	-----	-----
	Communication in lift car	-----	-----	-----
	Firemen's grounding switch	-----	-----	-----
	Lift Signage	-----	-----	-----
17	Standby power supply	.....	Provided	.....
18	Refuge Area	N/A		
	Total area	-----	-----	-----
	Location	-----	-----	-----
19	Fire Control Room	N/A		
	Detector system panel	.....	.....	.....
	Flow switch panel	.....	.....	.....
	PA system panel	.....	.....	.....
	Batter backup	.....	.....	.....
	Building Floor Plans	.....	.....	.....
20	Special Fire Protection systems for protection of special Risks, if any:	-----	-----	-----

The fire protection systems provided in the building were tested checked and found functional at the time of inspection. Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Singh  
24.12.12

Signature of the Inspecting Officer

Name Suresh Singh

Designation ADO

DO (East) Mugh  
26/12/12