GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2013/ 299

3

Dated: 18/01/13

FIRE SAFETY CERTIFICATE

Issued 12/.01/.12. at New Delhi.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi—110049 w.r.t. No 6161516/Addl.C.P./Lic.(H) New Delhi dated 19-10-2012
- 2. M/s Saina international Guest House located at 2324 & 2471, Chuna Mandi, Phar Ganj, New Delhi-110055.
- 3. Dy. Commissioner, MCD, Sadar Pahar Ganj Zone, Idgah Road, Delhi with a request to get height of the building measured and send intimation to Delhi Fire Service.

Condition for the validity of fire safety certificate

- 1 All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2 Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3 The trained fire fighting staff should be available round the clock.
- 4 Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5 This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Saina international Guest House, 2324 & 2471, Chuna Mandi Pahar Ganj, New Delhi-110055

INSPECTION REPORT

1. Name & address of the building : Saina international Guest House located at 2324 & 2471, Chuna

Mandi Pahar Ganj, New Delhi-110055

2. Type of Occupancy : Lodging House

3. Type of Case : Renewal

4. Details of previous NOC : Letter No. F6/DFS/MS/GH/2009/2454 Dated 08-08-2009

5. Fire Safety directives Letter No. : N/A

6. Date of inspection : 08-01-2013

7. Name of the Inspecting Officer : Sh. D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side : Smt. Shukla Kumari (owner)

9. Year of Construction : 2001 Starting Year

10. Applicant's letter No. : 65615-16/Addl.C.P./Lic.(H) dated New Delhi the 19-10-2012

S No	Minimum standards on fire prevention	BBL	Provided at site	Remarks MR/NMR			
	and fire safety U/R 33	Requirements	(PSS Area)	(Old Case)			
1.	Access of building						
	 Road width 	N/A	6 mtrs. Approx	x. MR			
	 Gate width 	N/A	N/A	N/A			
	 Width of internal road 	N/A	N/A	N/A			
2.	Number, width, Type & Arrangements of exits						
	a. Number of staircases	,					
	Upper floors	01	02	MR			
	• Basements	N/A	N/A	N/A			
	b. Width of staircases	1071					
	• Upper floors	80 cms	(1)109 cms. to 121 c (2) 107 cms.	ems. MR			
	• Basements	N/A	N/A	N/A			
	c. Protection of exits			14/11			
	Fire check door	N/A	N/A	N/A			
	 Pressurization 	N/A	N/A	N/A			
	d. No of continuous staircase to terrace	01	01	MR			
	e. Width Of Corridor	N/A	N/A	N/A			
	f. Door Size	N/A	N/A	N/A			
3.	Compartmentation			13/12			
	Fire check door	N/A	N/A	N/A			
	 Sealing of electrical shafts 	N/A	N/A	N/A			
	 Fire Rating of shaft door 	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	Fire Dampers	N/A	N/A	N/A			
4.	Smoke managements System						
	• Basements	30 a/c per hour	Exhaust fan	MR			
	Upper floors	12 a/c per hour	Natural ventilation	MR			

Saina international Guest House, 2324 & 2471, Chuna Mandi Pahar Ganj, New Delhi-110055

5.	Fire Extinguishers	+/1, Chuna Mand	ranar Ganj, New Deini	1-110055		
٥.	Fire Extinguishers	10	10	Z- \		
	• Total numbers	10	10 Water Co2 &	MR		
	• Types		A.B.C. type.	MR		
	IS marking	ISI marked	Provided	MR		
6.	First – Aid Hose Reels					
	Total numbers on each floor	01	01	MR		
	 Length of hose reel hose 	30 M	Provided	MR		
	Nozzle diameter	5 mm	Provided	MR		
7.	Automatic fire detection and alarming system					
	Type of detectors	N/A	N/A	N/A		
	 Location of Main Panel 	N/A	N/A	N/A		
	 Location of Repeater Panel 	N/A	N/A	N/A		
	Alternate source of power	N/A	N/A	N/A		
	Hooters' Location	N/A	N/A	N/A		
3.	MOEFA	Yes	Provided	M/R		
).).	Public Address System	Yes	Provided	M/R		
0.	Automatic Sprinkler System	1 68	riovided	IVI/ K		
J.	Basements	N/A	N/A	NI/A		
	BasementsUpper Floor	N/A N/A	N/A N/A	N/A N/A		
		N/A				
1.	Sprinkler above false ceiling	IN/A	N/A	N/A		
1.	Internal Hydrants	77/4	NT/A	2711		
	Size of riser/down- comer	N/A	N/A	N/A		
	Number of hydrants per floor	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
2.	Yard Hydrants	1	-			
	 Total number of hydrants 	N/A	N/A	N/A		
	Hose Box	N/A	N/A	N/A		
3.	Pumping Arrangements					
	Ground Level					
	 Discharge of main pump 	N/A	N/A	N/A		
	Head of main pump	N/A	N/A	N/A		
	Number of main pumps	N/A	N/A	N/A		
	Jockey pump out put	N/A	N/A	N/A		
	Jockey pump head	N/A	N/A	N/A		
	Standby Pump out put	N/A	N/A	N/A		
	Standby Pump Head	N/A	N/A	N/A		
	auto Staring/Manual stopping	N/A	N/A	N/A		
	Pump House Access	N/A	N/A	N/A		
	Terrace level					
	Discharge of pump	225 LPM	225 LPM	MR		
	Head of the pump	30 Mtrs.	30 Mtrs.	MR		
	Power supply	Electric	Electric	MR		
	➤ Auto starting of pump		Switch provided at G.F	MR		
4.	Captive water Storage for fire fighting	1	1	**************************************		
	Under ground tank capacity	N/A	N/A	N/A		
	> Draw of connection	N/A	N/A	N/A		
	Fire service inlet	N/A	N/A			
	Access to tank	N/A N/A	N/A N/A	N/A		
	Overhead Tank capacity			N/A		
5	Exit Signage	2500 Ltrs. Yes	2500 Ltrs. Provided	MR		
	T DAIL MEHAPE	YPC	Provided	MR		

Saina international Guest House, 2324 & 2471, Chuna Mandi Pahar Ganj, New Delhi-110055 Pressurization of Lift Shaft N/A N/A N/A Pressurization of lift lobby N/A N/A N/A Communication in lift Car N/A N/A N/A Fireman's Grounding Switch N/A N/A N/A Lift Signage N/A N/A N/A YES D.G. Set MR 17. Standby power supply 18. Refuge Area Total area N/A N/A N/A Location N/A N/A N/A 19. Fire control room

N/A

N/A

N/A

N/A

N/A

N/A

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name Designation

20.

Deto on leave.

Detector system panel

Building Floor Plans

Special Fire Protection Systems for

Protection of special Risks, if any;

Flow Switch Panel

PA System Panel

Batter backup

Signature of the Inspecting Officer

N/A

N/A

N/A

N/A

N/A

N/A

Name That vil singh yadow Designation Jo./cD)

N/A

N/A

N/A

N/A

N/A

N/A