## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No. F.6/DFS/MS/GH/2013/ 566

Dated: /2/2//3

## FIRE SAFETY CERTIFICATE

Certified that the Anila Hotels (a unit of Le-passage to India Tours & Travels Pvt. Ltd.) located at A-15, Naraina Vihar, New Delhi-110028 comprised of Basement, stilt floor, ground floor plus three upper floors, using basement as Hall/Storage, stilt floor as a parking, ground floor having nine guest rooms, office and reception, first, second and third floor each having nine guest rooms and one store respectively (Total Thirty Six guest rooms), A pantry for staff in a tin shed on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/2941 dated 13.10.2010 in the name of Mughal Heritage. Now this department has no objection in changing the name from Mughal Heritage to Anila Hotels (a unit of Le-passage to India Tours & Travels Pvt. Ltd.). The guest house building was re inspected by the officers concerned of this department on 29.01.2013 in the presence of Smt. Sunita Thukral (G.M), Sh. Anthony Cruz (A.G.M) and found that the management have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 12/2/13 at New Delhi.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

1. The Addl. Commissioner of Police (Lic.) 1<sup>st</sup> floor, P.S., Defence Colony, New Delhi. (Re. No.69791/Addl. C.P./Lic.(H), Dated 10.12.2012)

2. Sh. Manish Goel (Owner)
Anila Hotels (a unit of Le-passage to India Tours & Travels Pvt. Ltd.).
A-15, Naraina Vihar, New Delhi-110028.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	INSPE	ECTION REPORT	unit of Le-bassage	to India Tours &			
	and the building	Anila Hotel,	A-15, Naraina	Vihar New Noll - 28			
	<ol> <li>Type of Occupancy</li> <li>Type of Case</li> </ol>	Mesidential	(Guest House)				
	4. Details of Previous NOC	: New Case/Rene					
	5. Fire Safety directives letter No	: Letter No. F. 6/1	FS/MS/GH/2010/20	141 Date 13 · 10 · 20/0			
	6. Date of inspection		MA	The state of the s			
	7. Name of Inspecting Officer	29,	29.01.2013				
	8. Name and designation of office	D.O H.L. Ane	ja & A.D.O	P.S. Dahiya			
	From the building side		Thuballe				
	<ol><li>Year of Construction</li></ol>	Before	2016	Anthony Cruz CAGM			
	10. Applicant's letter No.	697911Add1.	C.P. 1111 (11)	lated 10.12.2012			
ς,	Minimum Standards on fire	NBC BBL	Provided at	Remarks			
No.	prevention and fire safety U/R 33	Requirement					
1.	Access to building	- Jan ement	Jite	MR/NMR			
	<ul> <li>Road width</li> </ul>	Accessible	18mtr	Da.0			
	<ul> <li>Gate width</li> </ul>	11-00351012	122 cms, 350 cms	MR			
	<ul> <li>Width of internal road</li> </ul>	-	122 cmp, 330 cmp	MR			
2.	Number, Width, Type & Arrangemen	nt of Evito		Manager to the control of the contro			
2.	a Number of staircases	THE OF EXILS		The state of the s			
	• Upper Floors						
	* Basements	One	One	MR			
	b. Width of staircases	7600	7600	MR			
	Upper Floor						
	* Basements		132 cms	MR, Being Old Cape			
	c Protection of exits	more and a second with a second secon	150 cms, 115 cms	MR, Being old Case MR			
	Fire check door						
	* pressurization	MA					
	d. No. of continuous staircases to	MIA	Common Co				
	terrace		The second state of the se				
	e. Width of Corridor		One	-			
	f. Door Size		147 cms, 180 cms	4***			
3.			88 cms x 220 cm	<b>b</b>			
).	Compartmentation	A Shadow Market (100 and market) and a shadow real					
	<ul> <li>Fire check door</li> </ul>	NIA					
	<ul> <li>Sealing of electrical shafts</li> </ul>	14/1	0				
	<ul> <li>Fire Rating of shaft door</li> </ul>	Assert Control of the section of the	Sealed				
	Water Curtain	NIA					
	<ul> <li>Fire Dampers</li> </ul>	NIA					
4.	Smoke Management System	MA		-			
	Basements						
	• Upper floors	30 a/c per	Exhaust Fans	N 0 0			
	aphai ucotz	hour	are Provided	MR			
		Commence of the second	Mataral Ventila	hioh MR			

	M	K		100 10		
	4.1	12 a/c per				
		hour				
	Fire Extinguishers			1		
	• Total numbers	20 Nes				
	• Types	Coz, ABC, WCoz	Provided	MR		
	<ul> <li>IS marking</li> </ul>	ISI marked	-do-	IMR		
	First-Aid Hose Reels	Dimarked	151 Marked	MR		
	<ul> <li>Total numbers on each floor</li> </ul>	Ohe				
	<ul> <li>Length of hose reel hose</li> </ul>	30 m	Provided	MR		
	Nozzle diameter	5 mm	-do-	MR		
7.	Automatic fire detection and alarming		-do-	MR		
	• Type of detectors	MA				
	<ul> <li>Location of Main Panel</li> </ul>	NIA	-	7		
	Location of Repeater Panel	NIA				
	<ul> <li>Alternate source of power</li> </ul>					
	<ul> <li>Hooters' Location</li> </ul>		D.G. Set of 140 KV	7 - 1		
8.	MOEFA	Partit	0 -			
9.	Public Address System	Required - do-	Provided	MR		
10.	Automatic Sprinkler System - do - do - MR					
	<ul> <li>Basement</li> </ul>	Required	Provided	6.0		
	<ul> <li>Upper Floor</li> </ul>	NIA	1 sovided	MR		
	<ul> <li>Sprinkler above false ceiling</li> </ul>	NIA	1	Ž.		
11.	Internal Hydrants	14(11		1		
	<ul> <li>Size of riser/down-comer</li> </ul>	574	100 M.M	MR		
	<ul> <li>Number of hydrants per floor</li> </ul>		One	1		
	<ul> <li>Hose Box</li> </ul>		-do-	MR		
12.	Yard Hydrants					
	<ul> <li>Total number of hydrants</li> </ul>		One	MR		
	<ul> <li>Hose Box</li> </ul>		-do-	MR		
13.	Pumping Arrangements					
	Ground Level			N		
	Discharge of main Pump	NIA				
	Head of Main pump	NIA		Manager 1		
	Number of main pumps	NIA				
	Jockey Pump out put	NIA				
	<ul><li>Jockey pump head</li><li>Standby Pump out put</li></ul>	NIA				
	> Standby Pump Head	NIA		\$ \$400.00 Mark \$100.00 Mark \$10		
	> Auto Starting/Manuai	NIA	i			
	stopping	NA	1			
	1 C = 0	7 1				

## N/7 A-15, Naraina Vikar, New Delli-110028.

0	<ul><li>Pump House Access</li><li>Terrace level</li></ul>	NIA					
	<ul><li>Discharge of pump</li><li>Head of the pump</li></ul>	450 LPM E	hr. 10. m				
	Power Supply	30 M Eac		h MR LOS Pur			
	Auto Starting	Required	h 38 M Each Provided	MR			
	Auto Starting of pump		Both	MR			
14.	Captive Water Stone		13014	-			
7	Captive Water Storage for fire fighting						
	• Underground tank capacity	NIA					
	or dw-on connection	NIA		_			
	the service inlet		D	_			
	Access to tank	MIA	Provided	MR			
	Overhead Tank capacity	15000 Ltr	10	-			
15.	F. 'l or		15000 Ur	MR			
13,	Exit Signage.	Required	Provided	MR			
16.	Provision of Lifts.						
	<ul> <li>Pressurization of Lift Shaft</li> </ul>	Alla					
	<ul> <li>Pressurization of Lift lobby</li> </ul>	NIA					
	<ul> <li>Communication In lift Car</li> </ul>	MIA	_	_			
	<ul><li>Fireman's Grounding Switch</li></ul>	-	Provided	MR			
	Lift Signage	Required	-do -	MR			
		- do -	-do-	MR			
17.	Standby power supply	Required - do -	Provided	MR			
18.	Refuge Area.						
	Total Area						
	Location	IVIA					
		NIA					
19.	Fire Control Room						
	Detector System Panel						
	• Flow Switch Panel	NIA					
	• PA System Panel	MA					
	Batter backup	MA					
	Building Floor Plans	Required	Provided	n 10			
		NIA	- SOVINER	MR			
0.	Special Fire Protection System for Protection of special Risks, if any:	NIA	-	~			

The fire protection systems provided in the building were test checked and found functional at  $\chi$  the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers

Note: - The above Guest House was issued Noc by this department viole letter No. F.6/DFS/MS/GH/2010/2941 dated 13.10.2010 in the name of Mughal Heritage Now this department has no objection for changing the name from Mughal Heritage to Anila Hotel (Auxit of Le-passage to India Tours & Travels Pvt. Ltd.)

Signature of Inspecting Officer

Name H.L. Aneja

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Sahiya

Designation Asst. Divisional Officer