GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

No: F.6/DFS/MS/School/2013/ 845

Dated: 28/02/13

FIRE SAFETY CERTIFICATE

Certified that the building of **M. C. Primary School,** Sarang Pur, New Delhi - 110073 comprised of ground floor only, having total 02 rooms (Including Class Room & Office) owned/occupied by MCD was inspected by the officer concerned of this department on 15.02.2013 in the presence of Sh. Bhupender Kumar (Incharge) and found that the M.C.D have complied with the fire prevention and fire safety requirements in accordance with the Circular No- F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on $\frac{28}{02}$ $\frac{13}{13}$ at New Delhi

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to: -

- The Principal,
 M. C. Primary School,
 Sarang Pur, New Delhi-73.
- Director of Education, South Delhi Municipal Corporation 15th floor, Dr. S.P.M Civic Centre, Minto Road, New Delhi-110002.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non- functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	CION REPORT				
1. Name & address of the building:	M. C. Primary S	chool, Sarang M	ur, New Delli-73		
	: Educational (School)				
3. Type of Case	: New Case/R enewa l : Letter No. N/A Dated				
4. Details of Previous NOC	: Letter No	Dated			
 Fire Safety directives letter No 		The second state of the se			
 Date of inspection 	15.02	and the second s			
1. Name of Inspecting Officer	: A.D.O P.S.	Bahiya	0.00		
8. Name and designation of office	ers	i D	10 0		
From the building side	Sh. Bhubender Kumar (Incharge)				
Year of Construction	Betore	· · · · · · · · · · · · · · · · · · ·			
10. Applicant's letter No.		ed 15.02.2013	NAMES OF THE OWNERS OF THE PARTY OF THE PART		
Minimum Standards on fire prevention and fire safety U/R 33	Dir. 0f Edu. Circular dt. 01.03.2011	Provided at site	Remarks MR/NMR		
Access to building		J			
 Poad width 	Accessible	06 mts	MR		
 Gate width 		290 cms	MR		
 Width of internal road 	Parameter 1		_		
Number, Width, Type & Arrangement of	Exits	Annen and a second seco			
Number of staircases					
• Deper Floors			Cooking Ch.		
 Bosements 			Ground Floor on		
	¥***		No Basement		
Width of staircases					
 Upper Floor 		-	Ground Floor Only		
 Basements 		P	No Basement		
Protection of exits			n e		
 Fire check door 		_			
 pressurization 			The second section of the sect		
Ne. of continuous staircases to					
terrace					
e Width of Corridor : Door Size		200 cms			
	-	100 cm x 20 Scms	-		
Compartmentation					
 Fire check door 			The second secon		
 Sealing of electrical shafts 		A CONTRACTOR OF THE CONTRACTOR			
 Fire Rating of shaft door 					
 Water Curtain 			-		
 Fire Dampers 		<u>-</u>			
	+		-		
Smoke Management System					
 Basements 	30 a/c per hour				
Ground		-	No Basement		
· Hoor			- 1		
		Natural Ventilation	, +		

Sarang Pur, New Delli-110073.

	Pump House Access	C				
	 Terrace level 					
	Discharge of pump					
	Head of the pump	(<u></u>				
	Power Supply	_	-			
	Auto Starting of pump					
4.	Captive Water Storage for fire fighting					
	 Underground tank capacity 	-				
	Draw-off connection	-		-		
	Fire service inlet			Andreas of the second s		
	Access to tank		<u></u>			
	 Overhead Tank capacity 					
15.	Exit Signage.	-	Provided	-		
16.	Provision of Lifts.					
LD.	Pressurization of Lift Shaft			Nolift		
	 Pressurization of Lift lobby 		N. A. C. Pick.	-do-		
	• Communication In lift Car			- do -		
	• Fireman's Grounding Switch					
				- do -		
	 Lift Signage 			- do -		
17.	Standby power supply					
18.	Refuge Area.					
	> Total Area	•	The second secon	_		
	> Location					
19.	Fire Control Room					
	 Detector System Panel 					
	 Flow Switch Panel 					
	 PA System Panel 					
	 Batter backup 	Name of the latest and the latest an		_		
	 Building Floor Plans 		_	8-		
30	Special Fire Protection System for			3. 11		
20.	Protection of special Risks, if any:			-		

The fire protection systems provided in the building were test checked and found functional at " the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers

Note: The school building comprised of Ground Floor only and having total of Rooms. In each class students less than 45.

Name P.S. Dahiya
Designation ASSH- Divisional Officer

Signature of Inspecting Officer

Name

Designation