## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE, NEW DELHI-110001

No. F6/MS/DFS/GH/2013/ 07

Dated: 05/03/2013

## FIRE SAFETY CERTIFICATE

Certified that the Everest Palace Guest House, 8244-A, Gali No.-6, Multani Dhanda, Pahar Ganj, New Delhi-110055 comprised of ground floor (reception + 01 guest room) and 1<sup>st</sup> floor to 4<sup>th</sup> floor (02 guest rooms at each floor) total 09 guest rooms, was granted NOC by this department vide letter No. F6/MS/DFS/GH/2009/3123 dated 29-10-2009. The premises was re-inspected by the officer concerned of this department on 26-02-2013 in the presence of Smt. Sunita Katyal (owner) and found that the said guest house building have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises is fit for occupancy of 09 guest rooms with effect from \$5./03./.2013 for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued .0.5/63/13... at New Delhi by.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Copy to :-

- 1. The Addl. Commissioner of Police (Lic.), First Floor, P.S. Defence Colony, New Delhi 110049.wrt. No.47813/Addl.C.P./Lic.(H) New Delhi dated 31-7-12
- 2. M/s Everest Palace Guest House, 8244-A, Gali No.-6, Multani Dhanda, Pahar Ganj, New Delhi-110055
- 3. Dy. Commissioner, MCD, Sadar Pahar Ganj Zone, Idgah Road, Delhi with a request to get height of the building measured and send intimation to Delhi Fire Service

Condition for the validity of fire safety certificate

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Everest Palace Guest House, 8244-A, Gali No.-6, Multani Dhanda, Pahar Ganj, New Delhi-110055

INSPECTION REPORT

1. Name & address of the building : Everest Palace Guest House, 8244-A, Gali No.-6, Multani

Dhanda, Pahar Ganj, New Delhi-110055

2. Type of Occupancy

Lodging House

3. Type of Case

Renewal

4. Details of previous NOC

Letter No. F6/DFS/MS/GH/2009/3123 dated 29-10-2009

5. Fire Safety directives Letter No.

N/A

6. Date of inspection

: 26-02-2013

7. Name of the Inspecting Officer

Sh. D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side

Smt. Sunita Katyal (owner)

9. Year of Construction

: 2002 Starting Year

10. Applicant's letter No.

47813/Addl.C.P./Lic.(H) dated New Delhi the 31-07-2012

S No	Minimum standards on fire prevention and fire safety U/R 33	BBL Requirements	Provided at site (PSS Area)	Remarks MR/NMR (Old Case)			
	Access of building						
	<ul> <li>Road width</li> </ul>	N/A	6 mtrs. Approx.	MR			
	<ul> <li>Gate width</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Width of internal road</li> </ul>	N/A	N/A	N/A			
2.	Number, width, Type & Arrangements of	of exits					
	a. Number of staircases						
	<ul> <li>Upper floors</li> </ul>	01	01	MR			
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A			
	b. Width of staircases		The higher discount disabilities and the second	- 0.5			
	<ul> <li>Upper floors</li> </ul>	80 cms	100 cms. to 102 cms	. MR			
	<ul> <li>Basements</li> </ul>	N/A	N/A	N/A			
	c. Protection of exits						
	<ul> <li>Fire check door</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Pressurization</li> </ul>	N/A	N/A	N/A			
	d. No of continuous staircase to terrace	01	01	MR			
	e. Width Of Corridor	N/A	N/A	N/A			
	f. Door Size	N/A	N/A	N/A			
3.	Compartmentation						
	Fire check door	N/A	N/A	N/A			
	<ul> <li>Sealing of electrical shafts</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Fire Rating of shaft door</li> </ul>	N/A	N/A	N/A			
	Water Curtain	N/A	N/A	N/A			
	<ul> <li>Fire Dampers</li> </ul>	N/A	N/A	N/A			
4.	Smoke managements System						
	Basements	30 a/c per hour	N/A	N/A			
	<ul> <li>Upper floors</li> </ul>	12 a/c per hour		MR			
5.	Fire Extinguishers		The second secon				

Everest Palace Guest House, 8244-A, Gali No.-6, Multani Dhanda, Pahar Ganj, New Delhi-110055

L	Everest Palace Guest House, 8244-A, G						
	<ul> <li>Total numbers</li> </ul>	10	10	MR			
	• Types		Water Co2 &	MR			
		ICI mankad	A.B.C. type.	MR			
	IS marking	ISI marked	Provided	IVIK			
6.	First – Aid Hose Reels						
	<ul> <li>Total numbers on each floor</li> </ul>	01	01	MR			
	<ul> <li>Length of hose reel hose</li> </ul>	30 M	Provided	MR			
	<ul> <li>Nozzle diameter</li> </ul>	5 mm	Provided	MR			
	Automatic fire detection and alarming system						
	<ul> <li>Type of detectors</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Location of Main Panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Location of Repeater Panel</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Alternate source of power</li> </ul>	N/A	N/A	N/A			
	<ul> <li>Hooters' Location</li> </ul>	N/A	N/A	N/A			
	MOEFA	N/A	N/A	N/A			
	Public Address System/Intercom	Yes	Provided	MR			
) .	Automatic Sprinkler System	yet and the second seco					
	Basements	N/A	N/A	N/A			
	Upper Floor	N/A	N/A	N/A			
	<ul> <li>Sprinkler above false ceiling</li> </ul>	N/A	N/A	N/A			
	Internal Hydrants						
	Size of riser/down- comer	N/A	N/A	N/A			
	<ul> <li>Number of hydrants per floor</li> </ul>	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
)	Yard Hydrants						
12.	Total number of hydrants	N/A	N/A	N/A			
	Hose Box	N/A	N/A	N/A			
3	Pumping Arrangements	1 1/1 2					
13.							
		N/A	N/A	N/A			
	<ul><li>Discharge of main pump</li><li>Head of main pump</li></ul>	N/A	N/A	N/A			
	Number of main pumps	N/A	N/A	N/A			
	Jockey pump out put	N/A	N/A	N/A			
	<ul><li>Jockey pump head</li></ul>	N/A	N/A	N/A			
	Standby Pump out put	N/A	N/A N/A	N/A			
	Standby Pump Head	N/A	N/A N/A	N/A			
	auto Staring/Manual stopping	N/A	N/A	N/A			
	<ul><li>Pump House Access</li></ul>	N/A N/A	N/A N/A	N/A N/A			
	Terrace level	1 N/ /A	] 1 V/ /\[ \]	1 1/ / 1			
	Discharge of pump	225 LPM	225 LPM	MR			
	Head of the pump	30 Mtrs.	30 Mtrs.	MR			
	Power supply	Electric	Electric	MR			
	Auto starting of pump		Switch provided at	MR			
			reception	IVIX			
4.	Captive water Storage for fire fighting						
	<ul> <li>Under ground tank capacity</li> </ul>	N/A	N/A	N/A			
	Draw of connection	N/A	N/A	N/A			
	Fire service inlet	N/A	N/A	N/A			
162	Access to tank	N/A	N/A	N/A			
	<ul> <li>Overhead Tank capacity</li> </ul>	N/A	N/A	N/A			
5	Exit Signage	Yes	Provided	MR			
16.	Provision of Lifts						
	Pressurization of Lift Shaft	N/A	N/A	N/A			
	Pressurization of lift lobby	N/A	N/A	N/A			

M

L	Everest Palace Guest House, 8244-A, Ga Communication in lift Car Fireman's Grounding Switch Lift Signage	N/A	N/A	1 N/ 2 X	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
7	Standby power supply	YES	D.G. Set	MR	
7.	Refuge Area				
8.	> Total area > Location	N/A	N/A	N/A	
		N/A	N/A	N/A	
1.0	Cine control room				
19.	Detector system panel Flow Switch Panel PA System Panel Batter backup	N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
		N/A	N/A	N/A	
	Building Floor Plans	N/A	N/A	N/A	
20.	Special Fire Protection Systems for Protection of special Risks, if any;	N/A	N/A	N/A	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Designation pero on leave.

Signature of the Inspecting Officer

Name Dhafm vie singh yadov Designation Divisional offices (contral)