## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No.F.6/DFS/MS/School/2013/ 62

Dated: 14/03/13

## FIRE SAFETY CERTIFICATE

Certified that the **Presidium School (Middle School) Dwarka** located at Sec-16B, Phase-II, Half Pocket-A, Dwarka, New Delhi-110075 comprised of basement, stilt floor plus five upper floors, having total 40 class rooms was issued NOC by this department vide letter No.F.6/DFS/MS/2009/491 dated 17.02.2009. The school building was re inspected by the officer concerned of this department on 28.02.2013 in the presence of Sh. Karan Singh (Manager) and found that the Florence Nightingale Educational Society have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class educational w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

CHIEF FIRE OFFICER
DELHI FIRE SERVICE

of L

Copy to:-

- 1. Sh. Akash Gupta (Treasurer), Florence Nightingale Educational Society, Sec-16B, Ph-II, Half Pocket-A, Dwarka, N.D-75.
- 2. Director of Education, Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110 054

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in



	Name & address file (INSP	ECTION REPORT				
	<ol> <li>Name &amp; address of the buildin</li> <li>Type of Occupancy</li> </ol>	8: Presidium Sch	pol (Middle Colon)	Near to a land		
	3 Type of Case	Educational (	School >	1917 Pocket - A, N. B - 75		
	The or case	New Case/Rand	lewe	7/11/8-43		
	- Octans of MENIORS NOC	Letter No Fig.	1DFS/MS/09/49/	Date 17.02.2009		
	and safety unectives letter No.	F. G/DFS/MS/	3P/2008/1088 de			
	- oars or mahermon	1,131313	28,02,2013			
	7 Name of Inspecting Officer 8. Name and decimally 5	0 4 4 0				
	and designation of office	ers	S. Banga	Propher angener the second part of the second secon		
	From the building side	Sh. Kaza	in Singh (Mana			
	9. Year of Construction	2008	risingh Criana	768)		
S	10. Applicant's letter No.		Nil dated 29:01:2013			
	Minimum Standards on fire	NBC/BBL	Provided at			
No.	prevention and fire safety U/R 33	Requirement		Remarks		
1.	Access to building	- Terrement	Site	MR/NMR		
	<ul> <li>Road width</li> </ul>	18mtr	18mtr			
	<ul> <li>Gate width</li> </ul>			MR		
	<ul> <li>Width of internal road</li> </ul>	•	05mtz	MR, Being Old Ca,		
2.	Number, Width, Type & Arrangeme		06 mts	MR		
	a. Number of staircases	nt of Exits	to a second complete the comple			
	• Upper Floors					
	Basements	1000	Two	MR		
	b. Width of staircases	025. Case Oilor	no 025. Case 01 Ram	b MR		
	• Upper Floor		VINUM			
		-	142 cm + Foot	No.0 0		
	Basements	<b>&gt;</b>	119 Ou a Cool	MR, Being a old a		
	c. Protection of exits	the second section of the second section of the second section of the second	142 cms Each	- do -		
	<ul> <li>Fire check door</li> </ul>	Received	0 , 1 1	The second section of the second section (as a second section of the second section se		
	• pressurization	Required	Provided	MR		
	d. No. of continuous staircases to			Company Compan		
	terrace	and the same of the first of the same of t				
	e. Width of Corridor		Two			
	f. Door Size		215cms, 165cms	-		
		<u>.</u>	109cms x 205cms	According to the production of the second discovery for the second of the second of the second discovery for the second d		
	Compartmentation		TO THIS X SOS CMB			
	• Fire check door	Δ				
	<ul> <li>Sealing of electrical shafts</li> </ul>	Required	Provided	MR		
	• Fire Rating of shaft door	1	Sealed			
	• Water Curtain					
	the Dampers			W-7		
١.	Smoke Management System					
	* Basements	70 /	Ew At at Com			
	<ul> <li>Upper flcors</li> </ul>	30 a/c per	Exhaust fans	Me		
	,	hour	are Provided	MR		
			Natural Ventilahi	in MR		

	12 a/c per hour		-	
Fire Extinguishers				
<ul> <li>Total numbers</li> </ul>	25 Nos	P	Al-a	
<ul><li>Types</li></ul>	Co2, WCo2, ABC	Provided	MR	
<ul> <li>IS marking</li> </ul>	ISI marked	-do=	MR	
First-Aid Hose Reels		131 Marked	MR	
<ul> <li>Total numbers on each floor</li> </ul>	7000	D	4 6	
<ul> <li>Length of hose reel hose</li> </ul>	30 m	Poovided	MR	
<ul> <li>Nozzle diameter</li> </ul>	5 mm	-do-	MR	
Automatic fire detection and alarmir		- do:-	MR	
Type of detectors	NIA			
<ul> <li>Location of Main Panel</li> </ul>				
<ul> <li>Location of Repeater Panel</li> </ul>		Near Reception	MR	
<ul> <li>Alternate source of power</li> </ul>		202	<u>.</u> +	
<ul> <li>Hooters' Location</li> </ul>		02 B.G. Set of 125 KVA	& MR	
MOEFA	0	Near S. Case	MR	
Public Address System	Required	Provided	MR	
Automatic Sprinkler System	-do-	- do -	MR	
Basement	0 ,		-  -	
Upper Floor	Required	Provided	MR	
<ul> <li>Sprinkler above false ceiling</li> </ul>	NA			
Internal Hydrants	MA	-	-	
Size of riser/down-comer	1			
	100 M.M	100M·M	MR	
- Ranmer of flydrams per 1100r	One	One	MR	
TOSC DOX	- do -	-do-	MIR	
Yard Hydrants		,		
<ul> <li>Total number of hydrants</li> <li>Hose Box</li> </ul>	One	One	MR	
TIOSC DOX	- do -	- do -	MR	
Pumping Arrangements				
Ground Level				
Discharge of main Pump	MIA	Cons.	-	
Head of Main pump	NIA	-		
Number of main pumps	NA		_	
<ul> <li>Jockey Pump out put</li> <li>Jockey pump head</li> </ul>	MA			
Standby Pump out put	NIA		-	
<ul> <li>Standby Pump dut put</li> <li>Standby Pump Head</li> </ul>	NIA	pan-y		
Auto Starting/Manual	MA	_		
stopping	NIA		-	
200phing	10171	The state of the s		

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Designation ASSH. Divisional Officer

Signature of Inspecting Officer

Name

Designation