GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No.F6/MS/DFS/EH/2013/ / 67

Dated: $\frac{10}{09}/3$

FIRE SAFETY CERTIFICATE

Certified that the **Big Banana Restaurant,15-16 1st Floor,J Block Market,Saket,New Delhi-110017**.comprised of **Ground + 2 Upper Floor and the Restaurant is running on 1**st **floor only** was granted NOC by this department vide letter No.F6/MS/DFS/EH/2010/366 dated 05/02/10 The premises was re-inspected by the officer concerned of this department on 18/03/13 in the presence of **Mr. Lalit Gupta** and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class **Group – D Assembly Building** with effect from-12/22/-/------for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued -- 10/04/13 -- at New Delhi by.

Chief Fire Officer Delhi Fire Service

- Copy to:- (1) D.E.O. RESTT.,
 Govt. of NCT of Delhi, Office of The Commissioner of Excise
 Entt. & Tax Deptt. L & J Block, I.P. Estate, Vikas Bhawan, New Delhi110002.
 - (2) Big Banana Restaurant, 15-16, 1st Floor, J Block Market, Saket, New Delhi-110017.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1.Name & address of the building:- Big Banana Restaurant, 15-16, 1st Floor, J Block Market, Saket, New Delhi-110017.
- 2. Type of occupancy:- Group D Assembly Building
- 3. Type of case:- Renewal
- 4. Details of previous NOC:-No. F6/MS/DFS/EH/2010/366 dated 05/02/10
- 5. Fire safety directives No.- No
- 6. Date of inspection: 18/03/13
- 7. Name of the inspecting officer:-A.D.O. S.S. Kaushik
- 8. Name & designation of officer From the building side:- Mr. Lalit Gupta
- 9. Year of construction:- Not Known
- 10.Applicant's letter No:-Nil dated 01/03/13 Ground + 2 Upper Floor and the Restaurant is on 1st floor only

| | | | | Old Case |
|------------|---|---|---------------------|-------------------|
| S.No. | Minimum Standards on fire Prevention and fire safety U/R 33 | Requirement NBC/BBL | Provided at site | Remarks MR/NMR |
| 1. | Access to Building | 200 100 100 100 100 100 100 100 100 100 | 3 | |
| | 1) Road width | Required 12 mtr. | Provided | MR |
| | 2) Gate width | N/A | N/A | N/A |
| | 3)Width of internal road | N/A | N/A | N/A |
| 2. | Number, Width Type & Arrange | ment of Exits | | |
| | A. Number of staircases | | | |
| | 1. Upper floors | Required | 1 Nos. | MR |
| | 2. Basements | N/A | N/A | N/A |
| | B. Width of staircase | | | 1 |
| | 1. Upper floors | Required | 1.25 mtr. | MR |
| | 2. Basements | N/A | N/A | N/A |
| | C. Protection of exits | 1 | | |
| | 1. Fire check door | N/A | N/A | N/A |
| ٠ | 2. Pressurization | N/A | N/A | N/A |
| | D. No. of continuous staircase to terrace | N/A | N/A | N/A |
| CONTRACTOR | E. Width of corridor | N/A | N/A | N/A |
| | F. Door size | Required two Nos. exit | 2 mtr. | MR |
| • | Compartmentation | | | |
| | 1) Fire check door | N/A | N/A | N/A |
| | 2) Sealing of electrical shafts | N/A | N/A | N/A |
| | 3) Fire rating of shaft door | N/A | N/A | N/A |
| Management | 4) Water curtain | N/A | N/A | N/A |
| 11 | 5) Fire Dampers | N/A | N/A | N/A |
| | Smoke Management System | | | |
| | 1) Basements | 30 a/c per hour | N/A | N/A |
| 1 2 | 2) Upper floors | 12 a/c per hour | Exhaust fan | MR |
| | Fire Extinguishers | - Landard Control of the Control of | | |
| | 1) Total numbers | 1 | 08 Nos. | MR |
| | 2) Types | ISI Marked | ABC, Co2 & W.Co2 | MR |

I outles

| 6. | 3) ISI marking First-Aid Hose Reel 1) Total number of each floor | One at each floor | Yes | MR |
|----------|--|-------------------|-------------------|------------|
| 6. | | One at each floor | , | |
| | 1) Total number of each floor | One at each floor | | |
| | | * 1 | One at each floor | MR |
| | 2) Length of hose reel hose | 30 m | Yes | MR |
| | 3) Nozzle diameter | 5 mm | Yes | MR |
| 7. | Automatic Fire Detection & Alarming | g System | | • |
| | 1) Type of detectors N/A | | N/A | N/A |
| | 2) Location of main panel | N/A | N/A | N/A |
| | 3) Location of repeater panel | N/A | N/A | N/A |
| | 4) Alternate source of power | N/A | N/A | N/A |
| | 5) Hooter's Location | N/A | N/A | N/A |
| 8. | MOEFA | Yes | Provided | MR |
| 9. | Public Address System | N/A | N/A | N/A |
| 10. | Automatic Sprinkler System | 1 | | |
| | 1) Basement | N/A | N/A | N/A |
| | 2) Upper floors | Yes | Restaurant | MR |
| | ^ | | area | |
| | 3) Sprinkler above false ceiling | N/A | N/A | N/A |
| 11. | Internal Hydrants | 7 | | |
| | 1) Size of riser/down-comer | Yes | 100 mm | MR |
| | 2) Number of hydrants per floor | One | One | MR |
| | 3) Hose box | One | One | |
| 12. | Yard Hydrants | One | One | MR |
| | 1) Total number of hydrants | N/A | NT/A | DT/A |
| | 2) Hose box | N/A | N/A N/A | N/A |
| | =) 11000 00K | IN/A | IN/A | N/A |
| 13. | Pumping Arrangement | | | |
| | 1) Ground level | * | 1 | |
| | a) Discharge of main pump | N/A | N/A | N/A |
| | b) Head of main pump | N/A | N/A | N/A N/A |
| | c) Number of main pump | N/A | N/A | N/A |
| | d) Jockey pump out put | N/A | N/A | N/A N/A |
| | e) Jockey pump head | N/A | N/A | N/A |
| | f) Stand by pump output | N/A | N/A | |
| | g) Stand by pump head | N/A | | N/A |
| | h) Auto starting/Manual stopping | N/A | N/A | N/A |
| | 2) Terrace level | IN/A | N/A | N/A |
| | a) Discharge of pump | 450 I DM | 450 I D) 5 |) (D |
| | b) Head of pump | 450 LPM | 450 LPM | MR |
| | | 38 mtr. | 38 mtr. | MR |
| | c) Power supply | Yes | Provided | MR |
| 4. | d) Auto starting of pump | Yes | Provided | MR |
| 7. | Captive Water Storage for Fire Fightin | | | |
| | 1) Under ground tank capacity | N/A | N/A | N/A |
| | a) Draw-off connection | N/A | N/A | N/A |
| | b) Fire service inlet | Yes | Provided | MR |
| | c) Access to tank | N/A | N/A | N/A |
| _ | d) Over head tank capacity | 5,000 Ltrs. | 5,000 Ltrs. | MR |
| | Exit Signage. | Yes | Provided | MR |
| | | | | 1 |
| 5. 6. | Provision of Lifts. | - | | |



| b) Pressurization of lift lobby | N/A 1// 6 | N/A | N/A |
|---------------------------------|-----------|-----|-----|
| c) Communication in lift car | N/A | N/A | N/A |
| d) Fireman's switch | N/A | N/A | N/A |

| | e) Lift signage | N/A | N/A | N/A |
|-----|------------------------------------|--------------------|--------------------|-----|
| 17. | Stand by Power Supply | Yes | Provided | MR |
| 18. | Refuge Area | N/A | N/A | N/A |
| | Total area location | N/A | N/A | N/A |
| 19. | Fire Control Room | N/A | N/A | N/A |
| | a) Detector system panel | N/A | N/A | N/A |
| | b) Flow switch panel | N/A | N/A | N/A |
| | c) PA system panel | N/A | N/A | N/A |
| | d) Battery backup | N/A | N/A | N/A |
| | e) Building floor plan | N/A | N/A | N/A |
| 20. | Special Fire Protection System for | Protection of spec | cial Risk, if any: | N/A |

The shortcomings communicated vide letter dated 13/02/13 found complied.

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/------

Accordingly DFA is put up please.

Signature of the inspecting officer

Signature of the inspecting officer

Name: Dharampal Bharadwaj

Designation: - Divisional Officer

Name: - S.S. Kaushik.

Designation: - Assistant Divisional Officer.