GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CANNAUGHT PLACE NEW DELHI- 110 001

Fax: 23412593, E-mail:cfohq.dlfire@nic.in

No. F6 DFS MS 2013 186

Dated: 18.04.2013

FIRE SAFETY CERTIFICATE

Certified that the Delhi State Cancer Institute at G.T.B. Hospital Complex, Dilshad Garden, Delhi -95, comprised of basement, ground plus three upper floors, owned/occupied by Govt. of NCT of Delhi have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and verified by the officers concerned of Fire Service on 29.01.2013 in the presence of Sh.Harjeet Singh(CE-E) and that the building is fit for occupancy group C -1 "Institutional Building" with effect from Normal State Cancer Cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010, printed overleaf.

(Dr.G.C.Misra) Chief Fire Officer Delhi Fire Service Ph.23414333

To,

The Director Delhi State Cancer Institute G.T.B. Hospital Complex, Dilshad Garden, Delhi -95

Copy to:-

The Chief Engineer (E),
Delhi State Cancer Institute
G.T.B. Hospital Complex, Dilshad Garden,
Delhi -95

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be responsible.

- 4. Any deviation, with regards to construction, ventilation, occupancy, electric installation etc. may be got verified from the concerned authorities.
- 5. Internal access road of 6 mtrs wide all around building blocks must be kept clear all the time for free movement of fire engines in case of fire.
- **6.** Basement shall be used as per BBL.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in.
- 8. This Fire Safety Certificate may not be treated in any case for regularizations of unauthorized construction/ unauthorized use of land if any.

INSPECTION REPORT

1. Name & address of the building : Delhi State Cancer Institute at G.T.B. Hospital Complex,

Dilshad Garden, Delhi.

2.Building Comprised of

2. Type of Occupancy

:B+Ground plus three upper floos : Institutional (Hospital Building)

3. Type of Case

: New Case

4. Details of Previous NOC

: Nil

5. Fire Safety directives No

: Nil

6. Date of Inspection

: 29.01.2013

7. Name of the Inspecting Officer

: DO Virendra Singh

8. Name of the designation of Officer

: Sh. Harjeet Singh (CE-E) with other supported staff.

From the building side 9. Year of Construction

10. Ap	plicant's letter No. : F.7(129	/DSCI/CE/2011-12/671 dated 05/02/13					
S.NO.	Minimum Standards on fire prevention	As per	Provided at Site	Remarks			
	and fire safety U/R33	requirement					
1	Access to building						
	Road width	12 Mtrs.	26 Mtrs.	MR			
	Gate width	4.5 Mtrs.	6 Mtrs.	MR			
	Width of internal road	6 Mtrs.	6 Mtrs.	MR			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	Upper Floor	05 Nos.	O5 Nos.	MR			
	Basement	05 nos.	05 Nos.	MR			
	b. Width of Staircases						
	Upper Floor	2.0 Mtrs.	Provided	MR			
	Basement	2.0 Mtrs.	Provided	MR			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	 Pressurization 	Required	Provided	MR			
	e. No. of continuous staircases to terrace	3 nos.	5 nos.	MR			
	g. Width of Corridor	2 .0 M	2.40 M	MR			
	h. Door Size	2.0 M	2.0 M & 1.30 M	MR			
3	Compartmentation.	Required	Provided				
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Sealed	MR			
	Fire rating of shaft door	1 hrs.	1 hrs.	MR			
	Water curtain						
	Fire Dampers						
4	Smoke Management System						
	Basement	N/A	Provided	Acceptable			
	 Upper floor 	12 a/c per hour	Provided	MR			

Delhi State Cancer Institute, G.T.B. Hospital Complex, Dilshad Garden, Delhi.

5.	Fire Extinguisher Total numbers	50 Nos.	150 Nos.	MR
	The second state states and the second secon	Water	Provided	MR
	• types	Type,ABC &Co2	South September 100 mar south control	
	IS marking	ISI marked	Provided	MR
6	First-aid-Hose Reels.			
		04 nos.	Provided	MR
	Total numbers of each floor	30 m	Provided	MR
	Length of hose reel hose	20 mm	Provided	MR
	Nozzle diameter		11011464	
7	Automatic fire detection and alarming syst	Heat & smoke	Provided	MR
	Type of detectors	Ground floor	Provided	MR
	Location of main panel	Ground floor	Provided	MR
	 Location of repeater panel 		Provided	MR
		Battery & DG	Frovided	IVIIX
	 Alternate source of power 	Set		
			,	
	Hooters's location	Near Staircase	Provided	MR
0	MOEFA	Required	Provided	MR
8	Public address System.	Required	Provided	MR
9	·	Required	Provided	MR
10	Automatic Sprinkler System.	Required	Provided	MR
	• basement	Required	Trovided	
	upper floor		Provided	Acceptable
	sprinkler above false ceiling		Provided	Acceptable
11	Internal Hydrants			
	size of riser/down-comer	150 mm	Provided	MR
	Number of hydrants per floor	04 Nos.	Provided	MR
	Hose Box	04 Nos	Provided	MR
12	Yard Hydrants.	24		
	Total number of hydrants	06 Nos.	15 Nos.	MR
	Hose Box	06 Nos.	15 Nos.	MR
13	Pumping Arrangements.			
13	Ground Level	2280 LPM	2280 LPM	MR
	> Discharge of main Pump	2280LPM	Provided	MR
	> Head of Main Pump	70 Mtrs.	Provided	MR
	> Number of main pumps	01 No.	Provided	MR
	> Jockey pump out put	180 LPM	Two 180 LPM	MR
	> Jockey pump head	70 Mtrs.	Provided	MR
	> Standby pump out put	2280LPM	2280 LPM	MR
	> Standby pump Head	70 Mtrs	Provided	MR
	> Auto Starting /Manual stopping	Auto	Provided	MR
	> Pump House Access	Required	Provided	MR
	Terrace Level	- Hoganica		
	Discharge of pump	220 lpm	Provided	MR
	Delhi State Cancer Institute G T B	<u> </u>		

Delhi State Cancer Institute, G.T.B. Hospital Complex, Dilshad Garden, Delhi.

	Head of the Pump	70 mtrs,	Provided	MR
	> Power supply	Required	Provided	MR
	> Auto Starting of pump	Required	Provided	MR
14	Captive Water Storage for Fire Fighting.			
	 Underground tank capacity 	1,50,000 Ltrs.	1,50,000 Ltrs.	MR
	Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	10,000 Ltrs.	20,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	 Pressurization of Lift Shaft 	Required	Provided	MR
	 Pressurization of Lift lobby 	Required	Provided	MR
	 Communication in lift car 	Required	Provided	MR
	 Firemen's grounding switch 	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	320 KVA	MR
18	Refuge Area.			
	Total area			
	• Location			
19	Fire Control Room			
	 Detector system panel 	Required	Provided	MR
	Flow switch panel	Required	Provided	MR
	PA system panel	Required	Provided	MR
	Battery backup	Required	Provided	MR
	Building Floor Plans	Required	Provided	MR
20	Special Fire Protection systems for	Required for	Provided	MR
	protection of special Risks, if any:	HT/LT panels		
			<u> </u>	

The fire protection systems provided in the building were tested checked and found functional at the time of inspection.

Keeping in view the compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Wingle