GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No. F.6/DFS/MS/GH/2013/ / 6 9

Dated: 68/04/13

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Citi International** located at 8/21, WEA, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus three upper floors, using basement as Hall/Storage, ground floor as reception, hall and one store room, first, second & third floor each having six guest rooms respectively (Total Eighteen guest rooms) was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/1484 dated 20.05.2010 owned/occupied by Sh. Parveen Kumar Anand. The guest house building was re inspected by the officers concerned of this department on 25.03.2013 in the presence of Sh. Parveen Kumar Anand (Owner) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

e/c

Men

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.12295/Addl. C.P./Lic.(H), Dated 12.03.2013)
- Sh. Parveen Kumar Anand (Owner), Hotel Citi International, 8/21, WEA, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT Name & address of the building: Hotel Citi International, 8/21, WEA, Karol Bogh, Type of Occupancy Residential (Guest House) Type of Case : New Case/Renewal 4. Details of Previous NOC : Letter No. F. 6/DFS/MS/GH/2010/1484 Date 20.05.2010 5. Fire Safety directives letter No 6. Date of inspection 25.03.2013 Name of Inspecting Officer D.O H.L. Aneja & A.D.O P.S. Dahiya 8. Name and designation of officers From the building side Sh. Parveen Kumar Anand 9. Year of Construction Before 2010 10. Applicant's letter No. 12295/ Addl. C.P. /LIC. (H) dated 12.03.2013 Minimum Standards on fire NBC/BBL Provided at Remarks prevention and fire safety U/R 33 No Requirement | site MR/NMR Access to building Road width Accessible 09mtr MR Gate width 173 cms MR Width of internal road Number, Width, Type & Arrangement of Exits 2. a. Number of staircases Upper Floors One One MR, Being a old case Basements - do --dob. Width of staircases Upper Floor 125cms MR, Being a Old Case Basements 125cms c. Protection of exits Fire check door pressurization d. No. of continuous staircases to terrace Ohe e. Width of Corridor f. Door Size 250 cms, 160 cms Socmax 205cms 3. Compartmentation Fire check door Sealing of electrical shafts Sealed Fire Rating of shaft door Water Curtain Fire Dampers Smoke Management System Basements Exhalist fans 30 a/c per Upper floors are Provided MR hour Matural Ventilation

MR

N/7. 8/21, WEA, Karol Bagh, New Delli-110005.

	Pump House Access	Ç.	-	
	Terrace level			
	Discharge of pump	450 LPM	456 LPM	MR
	Head of the pumpPower Supply	30M		MR
	· · · · · · · · · · · · · · · · · · ·	Required	30M Provided	MR
	Auto Starting of pump		Veneza,	
14.	Captive Water Storage for fire fighting			
	 Underground tank capacity 			
	Draw-off connection	•	~	-
	Fire service inlet			
	Access to tank			
	 Overhead Tank capacity 	-	Smalter	Mo Rain and
	T T T T T T T T T T T T T T T T T T T	0	Sooo Ur	MR, Being a old
15.	Exit Signage.	Requerred	Provided	MR
16.	Provision of Lifts.			
	Pressurization of Lift Shaft			
	 Pressurization of Lift lobby Communication In lift Car Fireman's Grounding Switch Lift Signage 			-
			N	-
			Provided	MR
		Required	- do -	MR
	2.11 51511450	-do-	-do-	MR
17.	Standby power supply	Required -do- Required	Provided	me
18.	Refuge Area.		2	
	> Total Area			
	> Location	•	-	
***************************************		_		
19.	Fire Control Room			
	Detector System Panel	•	_	-
	 Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	-	-	
				-
		Required	Provided	me
		-	-	/ //
20.	Special Fire Protection System for Protection of special Risks, if any:			
20.			140	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant-Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Name H. L. Aneja

Designation Divisional Officer

Signature of Inspecting Officer