GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No. F.6/DFS/MS/GH/2013/ 177

Dated: 11/04/13

FIRE SAFETY CERTIFICATE

Certified that the **Hotel Kashish Plaza** located at 12A/8, WEA, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus four upper floors, using basement as Hall/Storage, ground floor as reception, office and five guest rooms, first, second & third floor each having eight guest rooms respectively (Total Twenty Nine guest rooms), A pantry for staff on forth floor was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2009/2913 dated 30.09.2009 owned/occupied by Smt. Sangeeta Manchanda. The guest house building was re inspected by the officers concerned of this department on 03.04.2013 in the presence of Sh. Narender Singh (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overlean.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

The Addl. Commissioner of Police (Lic.)
 1st floor, P.S., Defence Colony, New Delhi.
 (Re. No.52978-79/Addl. C.P./Lic.(H), Dated 10.09.2012)

2. Smt. Sangeeta Manchanda (Owner), Hotel Kashish Plaza, 12A/8, WEA, Karol Bagh, New Delhi-110005. (Re. No. Nil dated 23.03.2013) Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

	IN:	SPECTI	ON REPORT					
	2. Type of Occupancy	ding:	itel Kashish	Plaza, 12A/8, V	VEA. Karol Bagh No			
	 Name & address of the build Type of Occupancy Type of Case 	K	esidential ((nuest House)				
	4. Details of Previous NOC	. 13	LEW CASE KEDEL	val				
	5. Fire Safety directives letter N	: L	etter No. <u>F6/D</u>	ES/MS/GH/2009/29	13 Date 30.09.2009			
	6. Date of inspection	AO : _	THE COURSE STATE AND ADDRESS OF THE PARTY OF	MA				
	Name of Inspecting Officer	03.04.2013						
	Name and designation of off	on of officers						
	From the building side							
	9. Year of Construction	Sh. Narender Singh Before 2006						
	10. Applicant's letter No.	50	52978-79/Addl. CP/LIC. CH) dated 10.09.12. No-Nil dated					
5	Minimum Standards on fire		NBC/BBL	Provided at	Remarks 23.03			
No.	prevention and fire safety U/R 33	3		site	MR/NMR			
l.	Access to building	the state of the s		3100	I AILLY LAIGHT			
	 Road width 		Accessible	07 mts.	MR			
	 Gate width 			180cm				
	 Width of internal road 			Toochip	MR			
2.	Number, Width, Type & Arrange	ment o	f Fyite	The second secon	Phone:			
	a. Number of staircases	TICHE O	LAIG					
	 Upper Floors 		<u> </u>					
	 Basements 		One	One	MR, Being old Co			
	b. Width of staircases		- do -	-do-	- do -			
	Upper Floor							
	Basements		-	130cms	MR, Being a Old Ca			
	c. Protection of exits			120 cm 8	-do-			
	Fire check door							
	• pressurization			-				
	d. No. of continuous staircases t		-					
	terrace	O						
	e. Width of Corridor		•	Ohe				
	f. Door Size		_	142 cms				
			•	80cms x 198 cms				
3.	Compartmentation			The second state of the se				
	 Fire check door 							
	 Sealing of electrical shafts 	,	•					
	 Fire Rating of shaft door 	6		Sealed				
	Water Curtain			No.				
	 Fire Dampers 							
4.	Smoke Management System			_	-			
	* Basements							
	 Upper flcors 		30 a/c per	exhaust fons are Provided	MR			
	apper mons		hour	Matural Ventila				

12 a/c per hour

		hour	-	
5.	Fire Extinguishers			
	 Total numbers 	Three at each Floor	Provided	Nag
	 Types 	Co, WCo, ABC	- do-	MR
	 IS marking 	ISI marked	151 Marked	MR
6.	First-Aid Hose Reels		15/ Marked)*//
	 Total numbers on each floor 	One	Provided	MR
	 Length of hose reel hose 	30 m	-do-	MR
	 Nozzle diameter 	5 mm	- do' -	MR
7.	Automatic fire detection and alarming	system		
	 Type of detectors 	-	•	
	 Location of Main Panel 		-	
	 Location of Repeater Panel 			
	 Alternate source of power 		DG Set of 15 KVA	
	 Hooters' Location 	_		-
8.	MOEFA	Required	Provided	MIR
9.	Public Address System	- do -	- do -	MIR
10.	Automatic Sprinkler System			
	• Basement	Required	Provided	MR
	 Upper Floor 			4
	 Sprinkler above false ceiling 			
11.	Internal Hydrants	1		
	 Size of riser/down-comer 	-	_	+
	 Number of hydrants per floor 		-	
	 Hose Box 	-	=	
12.	Yard Hydrants		1.	
	 Total number of hydrants 			
	 Hose Box 	-	· Same	
13.	Pumping Arrangements			* * * * * * * * * * * * * * * * * * * *
	Ground Level			5 S
	Discharge of main Pump	•		-
	> Head of Main pump	-	p—	-
	Number of main pumps			
	Jockey Pump out putJockey pump head		_	
	> Standby Pump out put		-	
	> Standby Pump Head			
	> Auto Starting/Manual	1-1	i i	_
	stopping		- 1	

N/13 12A/8, WEA, Sarascocki Marg, Karol Bagh, New Delli-110005.

	a and a final fina			~				
	Batter backupBuilding Floor Plans	Required	Provided	MR				
	 PA System Panel 							
	• Flow Switch Panel	•	ş=					
13,	Detector System Panel							
19.	Fire Central D-							
	Location		~					
	Total AreaLocation	•	Ç					
18.	Refuge Area.							
17.	Standby power supply	Required	Provided	MR				
		- do -	-do-	MR				
	 Communication In lift Car Fireman's Grounding Switch Lift Signage 	Required - do -	-do-	MR				
		00000	Provided	MR				
		•	0					
	 Pressurization of Lift lobby 			•				
16.	Provision of Lifts. Pressurization of Lift Shaft							
			1 2001414	1-11				
15.	Exit Signage.	Required	Provided	MR, Being a Old				
	Overhead Tank capacity		5000 (Ar	me Red - a Old				
	Access to tank		Provided	MTR				
	Fire service inlet	-	0					
	 Underground tank capacity Draw-off connection 	-	P.					
14.	Captive Water Storage for fire fighting							
	Auto Starting of pump	-						
	 Power Supply Auto Starting of nump 	Required	Provided	MR, Being a old				
	Head of the pump	450 LPM	4SOLPM 22M	MR				
	Discharge of pump	110010	1.0					
	Pump House AccessTerrace level	•	*	_				

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Note: The management has rectified all the previous short Coming. Comminicated vide letter No. Fel Drs/ms/2012/3161 dt. 36/8/12.

Name H.L. Aneja Designation Divisional Officer

Name P.S. Dahiya

Designation Apath. Divisional Officer.