GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI-110001

No.F6/DFS/MS/EH/2013/ / 52

Dated: 58/04/13

FIRE SAFETY CERTIFICATE

Certified that the Keya-Kainoosh (A Unit of Magique Hospitality Pvt. Ltd.) located at 122-124,DLF Promenade Mall,Plot No.3, Vasant Kunj, New Delhi.comprised of Basement, Ground + 2 Upper Floor but the restaurant is running on ground floor of building. was granted NOC by this department vide F6/MS/DFS/EH/09/3686 dated 04/12/09 The premises was re-inspected by the officer concerned of this department on 29/03/13 in the presence of Mr. Deepak Nautiyal and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group - D Assembly Building with effect from---for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010 subject to conditions printed below.

Issued -08/07/13---at New Delhi by.

Chief Fire Officer Delhi Fire Service

Copy to:- (1) Dy. Health Officer, South Zone, MCD, Green Park, New Delhi.

orca

(2) Keya-Kainoosh (A Unit of Magique Hospitality Pvt. Ltd.), 122-124,DLF Promenade Mall,Plot No.3,Vasant Kunj,New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. The basement shall be used as per the provisions of BBL.

6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- Keya-Kainoosh (A Unit of Magique Hospitality Pvt. Ltd.),122-124,DLF Promenade Mall,Plot No.3,Vasant Kunj,New Delhi.

2. Type of occupancy:- Group - D Assembly Building

3. Type of case:- Renewal

4. Details of previous NOC:-No. F6/MS/DFS/EH/09/3686 dated 04/12/09

5. Fire safety directives No.- No

6. Date of inspection: 29/03/13

7. Name of the inspecting officer:-A.D.O. S.S. Kaushik

8. Name & designation of officer From the building side:- Mr. Deepak Nautiyal

9. Year of construction:- Not known

10.Applicant's letter No:-Nil dated 05/02/13 Basement, Ground + 2 upper Floor(restaurant is on ground floor only)

S.No.	M: · · · ·		• /	Old Case
5.110.	Minimum Standards on fire	Requirement	Provided at	Remarks
1	Prevention and fire safety U/R 33	NBC	site	MR/NMR
1.	Access to Building			IVIIOTVIVII
	1) Road width	14 mtr.	Provided	MR
	2) Gate width	N/A	N/A	N/A
	3)Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrange		IVA	
	A. Number of staircases			
	1. Upper floors	N/A.	N/A	N/A
	2. Basements	N/A	N/A	N/A N/A
	B. Width of staircase		IVA	IN/A
	1. Upper floors	N/A	N/A	NT/A
	2. Basements	N/A	N/A	N/A
	C. Protection of exits	1071	IN/A	N/A
	1. Fire check door	N/A	N/A	27/4
	2. Pressurization	N/A		N/A
	D. No. of continuous staircase	N/A	N/A	N/A
	to terrace	IN/A	N/A	N/A
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	N/A	5 Nos exit	
			provided	MR
			provided	
	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
	Smoke Management System	- 1/11	IVA	N/A
	1) Basements	30 a/c per hour	N/A	NT/A
	2) Upper floors	12 a/c per hour	Exhaust fan	N/A
	Fire Extinguishers	I	DAHaust Iall	N/A
	1) Total numbers		10 Nos.	MR
	2) Types		ABC, Co2 &	MR

		N4-			
		ISI Marked	W.Co2		
	3) ISI marking		Yes	MR	
6.	First-Aid Hose Reel				
	1) Total number of each floor	Yes	2 Nos.Near Restaurant	MR	
	2) Length of hose reel hose	30 m	Yes	MR	
	3) Nozzle diameter	5 mm	Yes	MR	
7.	Automatic Fire Detection & Alarming System:- Provided & maintained by mall management				
	1) Type of detectors	do	do	do	
	2) Location of main panel	do	do	do	
	3) Location of repeater panel	do	do	do	
	4) Alternate source of power	do	do	do	
	5) Hooter's Location	do	do	do	
8.	MOEFA	Yes	Provided	MR	
9.	Public Address System	N/A	Provided	MR	
10.	Automatic Sprinkler System	Provided & maintained by mall management			
9. 7	1) Basement	do	do	do	
	2) Upper floors	do	do	do	
	3) Sprinkler above false ceiling	do	do	do	
11.	Internal Hydrants	:- Provided &			
	n				
	management 1) Size of riser/down-comer	1.	1		
	2) Number of hydrants per floor	do	do	do	
	3) Hose box	do	do	do	
12.	Yard Hydrants :- Provided & mainta		do	do	
12.	1) Total number of hydrants	1			
	2) Hose box	do	do	do	
	2) 11030 00%	do	do	do	
13.	Pumping Arrangement	Provided & maintained by mall management			
	1) Ground level	do	do	do	
13.	a) Discharge of main pump	do	do	do	
	b) Head of main pump	do	do	do	
	c) Number of main pump	do	do	do	
	d) Jockey pump out put	do	do	do	
	e) Jockey pump head	do	do	do	
	f) Stand by pump output	do	do	do	
	g) Stand by pump head	do	do	do	
	h) Auto starting/Manual stopping	do	do	do	
	2) Terrace level	do	do	do	
	a) Discharge of pump	do	do	do	
	b) Head of pump	do	do	do	
	c) Power supply	do	do	do	
v	d) Auto starting of pump	do	do	do	



V	5

b) Fire service inlet	do	do	
To make the particular and the same that the	do		do
d) Over head tank capacity	1	do	do
Exit Signage.	do	do	do
Provision of Lifts		Provided	MR
	maintained by mall		
b) Pressurization of lift lobby	do	do	do
d) Fireman's switch	do	do	do
	c) Access to tank d) Over head tank capacity Exit Signage. Provision of Lifts. a) Pressurization of lift shaft	c) Access to tank d) Over head tank capacity Exit Signage. Provision of Lifts. Provided & maintained by mall a) Pressurization of lift shaft b) Pressurization of lift lobby c) Communication in 150	c) Access to tankdo d) Over head tank capacitydo Exit Signage. Yes Provided Provision of Lifts. Provided & maintained by mall a) Pressurization of lift shaftdo b) Pressurization of lift lobbydo c) Communication in lift core

		ao	do	do
	e) Lift signage	1		
17.	Stand by Power Supply	do	do	do
18.	Refuge Area	Yes	Provided	MR
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
		Provided & maintained by mall	N/A	N/A
	a) Detector system panelb) Flow switch panel	do	do	do
· · · · · ·	c) PA system panel	do	do	do
	d) Battery backup	do	do	do
	e) Building floor plan	do	do	do
0.	Special Fire Protection System for	Protection of services	do	do
	, seem tot	or special R	isk, if any:	N/A

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire

Accordingly DFA is put up please.

Signature of the inspecting officer

Signature of the inspecting officer

Name: - D.P. Bharadwaj.

Designation: Divisional Officer

Designation:- Assistant Divisional Officer.