GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE, CONNAUGHT PLACE NEW DELHI- 110001

Fax:23412593, E-mail: cfohq.dlfire@nic.in

NO. F6/DFS/MS/HTL/2013/188

DATED: 18.04.2013

FIRE SAFETY CERTIFICATE

Issued on 18.04. 2013 at New Delhi by

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service Ph. 23414333

12 y 13

To,

M/s Oriole Dr.Fresh Hotels Pvt.Ltd. B-6/17 Safdarjung Enclave, New Delhi -110029.

Copy to:-

The Addl. Commissioner of Police (Lic.) 1st Floor, Police Station, Defence Colony, New Delhi.

CONDITIONS:

1. All the means of escape shall be kept free of all type of obstruction all the time.

2. All the employees shall be acquainted with the use and maintenance of all fire equipments and method of smooth and speedy safe evacuation of occupants in case of emergency.

3. All the fire fighting equipments shall be maintained in perfect working condition all the time and any lapse rendering non-functional of fire safety measures, management shall be

4. The clarification with regards electrical installation, ventilation, structure stability set back areas, occupancy and constructional deviation in building etc .may be got verified from the authorities

5. This Fire Safety Certificate can not be treated in any case for regularizations of unauthorized construction/ unauthorized use of land if any.

7. All comments/ directions of the Licensing Department shall always be permitted and followed.

8. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rule 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building :Red Fox Hotel at Plot No.6, Community Center, Sec-A, Kondli, Delhi

2. Type of Occupancy

: Residential

3. Type of Case

: Renewal

4. Details of Previous NOC

: F6/DFS/MS/Hotel/2010/570 Dated 25.02.10

5. Fire Safety directives No

: F6/DFS/MS/BP/2008/149 Dated 21.01.2008

6. Date of Inspection

: 06.03.13

7. Name of the Inspecting Officer: DO Virendra Singh & ADO Gurmukh Singh

8. Name of the designation of Officer

From the building side

: Sh.N.C.Malhotra(Vice President) & Sh.Mahesh Kumar(AGM)

9. Year of Construction

: 2009

10.Applicant's letter No

:68356/Addl.C.P./Lic.(H) dated 03.12.12 & 15.02.13

S.NO.	Minimum Standards on fire prevention	NBC	Provided at Site	Remarks MR/NMR			
	and fire safety U/R33	Requirement					
1	Access to building						
	Road width	12 Mtrs.	24 Mtrs.	MR			
	Gate width	4.5 Mtrs.	6.0 Mtrs.	MR			
	 Width of internal road 	6 Mtrs.	6.0 Mtr.	MR			
2	Number, Width, Type and Arrangement of Exits						
	a. Number of Staircases						
	Upper Floor	2 nos.	2 nos.	MR			
	Basement	2 nos.	2 nos+1 Ramp	MR			
	B. Width of Staircases						
	Upper Floor	1.25 Mtrs.	1.5 Mtrs.	MR			
	 Basement 	1.25 Mtrs.	1.5 Mtrs.	MR			
	c. Protection of exits						
	Fire check door	Required	Provided	MR			
	 Pressurization 	Required	Provided	MR			
	e. No. of continuous staircases to terrace	1no.	2 nos.	MR			
	g. Width of Corridor	1.25 Mtrs.	1.4 Mtrs.	MR			
	h. Door Size	1.0 Mtr.	1.0 Mtr.	MR			
3	Compartmentation.	Required Provided					
	Fire check door	Required	Provided	MR			
	 Sealing of electrical shafts 	Required	Sealed	MR			
	 Fire rating of shaft door 	2 hrs.	2 hrs.	MR			
	 Water curtain 	Required	Provided	MR			
	 Fire Dampers 	Required	Provided	MR			
4	Smoke Management System.						
	Basement	30a/c per hour	Provided	MR			
	 Upper floor 	12 a/c per hour	do	MR			
5.	Fire Extinguisher						
	Total numbers	60 nos.	60 Nos.	MR			
	types	ABC & Co2	ABC & Co2	MR			
	IS marking	ISI marked	ISI marked	MR			
6	First-aid-Hose Reels.		1				

71/112

8 M 9 Pu 10 Au	utomat utomat I I I I I I I I I I I I I	Total numbers of each floor Length of hose reel hose Nozzle diameter Lic fire detection and alarming syste Type of detectors Location of main panel Location of repeater panel Alternate source of power Hooters's location ddress System. Lic Sprinkler System. basements	Heat & smoke 1 st basement Security Room Battery & DG Set Staircase Required Required	2 nos. Provided Provided Provided Provided Provided Provided Provided Provided	MR
8 M 9 Pu 10 Au	o I utomat	Nozzle diameter cic fire detection and alarming system Type of detectors Location of main panel Location of repeater panel Alternate source of power Hooters's location ddress System. tic Sprinkler System.	5 mm em. Heat & smoke 1 st basement Security Room Battery & DG Set Staircase Required Required	Provided Provided Provided Provided Provided Provided Provided	MR MR MR MR MR MR
8 M 9 Pu 10 Au	o location at the state of the	tic fire detection and alarming system Type of detectors Location of main panel Location of repeater panel Alternate source of power Hooters's location ddress System. tic Sprinkler System.	Heat & smoke 1st basement Security Room Battery & DG Set Staircase Required Required	Provided Provided Provided Provided Provided Provided	MR MR MR MR
8 M 9 Pu 10 Au	• I • I • I • I • I • I • I • I • I • I	Type of detectors Location of main panel Location of repeater panel Alternate source of power Hooters's location ddress System. tic Sprinkler System.	Heat & smoke 1 st basement Security Room Battery & DG Set Staircase Required Required	Provided Provided Provided Provided Provided	MR MR MR
9 Pu 10 Au	• I • I • I • I • I • I • I • I • I • I	Location of main panel Location of repeater panel Alternate source of power Hooters's location ddress System. tic Sprinkler System.	1st basement Security Room Battery & DG Set Staircase Required Required	Provided Provided Provided Provided Provided	MR MR MR
9 Pu 10 Au	• MOEFA ublic acutomat	Location of repeater panel Alternate source of power Hooters's location ddress System. tic Sprinkler System.	Security Room Battery & DG Set Staircase Required Required	Provided Provided Provided Provided	MR MR MR
9 Pu 10 Au	• MOEFA ublic ac	Alternate source of power Hooters's location ddress System. tic Sprinkler System.	Battery & DG Set Staircase Required Required	Provided Provided Provided	MR
9 Pu 10 Au	● MOEFA ublic ad utoma	Hooters's location ddress System. tic Sprinkler System.	Staircase Required Required	Provided Provided	MR
9 Pu 10 Au	MOEFA ublic ac utoma	ddress System. tic Sprinkler System.	Required Required	Provided	
9 Pu 10 Au	MOEFA ublic ac utoma	ddress System. tic Sprinkler System.	Required		MR
9 Pu 10 Au	ublic ad utoma	tic Sprinkler System.	Required		14113
10 Au	• •	tic Sprinkler System.		Provided	MR
	•		Required	Provided	MR
11 In			Required	Provided	MR
11 In	•	upper floors	Required	Provided	MR
11 In	•	sprinkler above false ceiling	Required	Provided	MR
	nternal	Hydrants			
	•	size of riser/down-comer	150 mm	150 mm	MR
	•	Number of hydrants per floor	Two	Two	MR
		Hose Box	Two	Two	MR
12 Ya	Yard Hydrants.		18		
		Total number of hydrants	Four	Four	MR
		Hose Box	Four	Four	MR
13 Pi	Pumping Arrangements.				
	Ground Level		N. S.	e ,	4
	>	Discharge of main Pump	2280 LPM	Provided	MR
	>	Head of Main Pump	75 Mtrs.	75 mtrs	MR
	>	Number of main pumps	Two	2 No.	MR
	>	Jockey pump out put	One 180 LPM	One180 lpm	MR
	>	Jockey pump head	70 Mtrs.	80 mtrs.	MR
	>	Standby pump out put	2280 LPM	2280 LPM	MR
	>	Standby pump Head	70Mtrs	80 Mtrs.	MR
	. >	Auto Starting /Manual stopping	Auto	Provided	MR
	>	Pump House Access	Required	Provided	MR
	Terrace Level				
	>	Discharge of pump	Not Required	Provided	MR
	<u> </u>	Head of the Pump	do	39 Mtrs.	MR
	<u> </u>	Power supply	do	Provided	MR
	>	Auto Starting of pump	Required	Auto	MR
14 C	Captive	Water Storage for Fire Fighting.			
	•	Underground tank capacity	2,00,000 Ltrs.	2,00,000 Ltrs.	MR

Red Fox Hotel at Plot No.6, Community Center, Sec-A, Kondli, Delhi

*	> Draw-off connection	Required	Provided	MR
	Fire service inlet	Required	Provided	MR
	Access to tank	Required	Provided	MR
	Overhead Tank capacity	20,000 Ltrs.	20,000 Ltrs.	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.			
	 Pressurization of Lift Shaft 	Required	Provided	MR
	 Pressurization of Lift lobby 	Required	Provided	MR
	Communication in lift car	Required	Provided	MR
	 Firemen's grounding switch 	Required	Provided	MR
	Lift Signage	Required	Provided	MR
17	Standby power supply	Required	1000 KVA	MR
18	Refuge Area.		Provided	MR
	Total area	19.650 Mtrs	Provided	MR
	• Location	required	Provided	MR
19	Fire Control Room			
	 Detector system panel 	Required	Provided	MR
	Flow switch panel	Required	Provided	MR
	PA system panel	Required	Provided	MR
	Batter backup	Required	Provided	MR
	 Building Floor Plans 	Required	Provided	MR
20	Special Fire Protection systems for protection of special Risks, if any:	Required for HT/LT panels	Provided	MR

The fire protection systems provided in the building were test checked and found functional at the of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to Fire Safety Certificate under rule 35 of the Delhi Fire Service Rule 2010.

Signature of the Inspecting Officer

Designation DO CE

Signature of the Inspecting Officer

Name Gurmwkh Singh

Designation ADO (LN)