GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUATERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

NO.F6/DFS/MS/GH/2013/ 120

Dated: 26/03/12

FIRE SAFETY CERTIFICATE

Issued on $\frac{26/03//3}{}$ at New Delhi by.

Chief Fire Officer Delhi Fire Service

Copy to: -

1. The Addl.C.P (Lic.), Police Station, Defence Colony, 1st floor, New Delhiw.r.t. your letter No. 2319/Addl.C.P./Lic(H) dated 14-01-13.

2. The Manager, Sweet Home Dx Guest House, 5228, Shora Kothi, Paharganj, New Delhi.

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building :Sweet Home Dx, guest house, 5228, Shora Kothi, Paharganj,

New Delhi

2. Type of Occupancy

: Lodging House

3. Type of Case

: Renewal

4. Details of previous NOC

: Letter No. F.6/DFS/MS/GH/2010/2990 Dated: 20.10.2010.

5. Fire Safety directives letter No : N/A

6. Date of inspection

: 16.02.2013

7. Name of the Inspecting Officers : M.K.Chattopadhyay, ADO(HQ)

8. Name and designation of officers

from the building side

: Mr. Pramod Gupta, Manager

9. Year of Construction

: 2000

10. Applicant's letter No. : 2319/Addl.C.P/Lic(H) dated 14/01/2013

S. No	prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR
1	Access to building			
	Road widthGate widthWidth of internal road	PSS Area	04 mts. Directly accessible from the road	MR MR
	Th.T	N/A	N/A	N/A
	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	01	01	MR
	• Basements	N/A	N/A	N/A
	b. Width of staircases			IN/A
	• Upper Floors	0.80 mts	1.26 mts	MR
	Basementsc. Protection of exitsFire check door	N/A	N/A	N/A
		N/A	N/A	
		N/A	N/A	
	 Pressurization 	N/A	N/A	
	e. No. of continuous staircases to terrace	01	01	MR
3	g. Width of Corridor	N/A	N/A	1711/
	h. Door Size	N/A	N/A	
		N/A	N/A	

3	Compartmentation.			
	Fire check door	N/A	N/A	
	 Sealing of electrical shafts 	N/A	N/A	
	 Fire Rating of shaft door 	N/A	N/A	
	 Water Curtain 	N/A	N/A	
	• Fire Dampers	N/A	N/A	
4	Smoke Management System.			
	• Basements	30 a/c per hour	N/A	N/A
	• Upper floors	12 a/c per hour		v .
			N/A	N/A
5	Fire Extinguishers			
	Total numbers	08	Provided	MR
	• Types	WCO_2, CO_2	Provided	MR
	IS marking	ISI marked	Provided	MR
6	First-Aid Hose Reels.			
	Total numbers on each floor	01	Provided	MR
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	Provided	MR
7	Automatic fire detection and alarmin	g system.		
	Type of detectors	N/A	N/A	
	Location of Main Panel	N/A	N/A	
	Location of Repeater Panel	N/A	N/A	
	Alternate source of power	N/A	N/A	
	Hooters' Location	N/A	N/A	
8	MOEFA	Required	Provided	MR
9	Public Address System.	Required	Provided	MR
10	Automatic Sprinkler System.			
	Basement	N/A	N/A	
	• Upper Floor	N/A	N/A	
	Sprinkler above false ceiling	N/A	N/A	
11	Internal Hydrants			
	Size of riser/down-comer	N/A	N/A	



•	Number of hydrants per floor	N/A	N/A	/
•	II D	N/A	N/A	1
2 Yaro	d Hydrants.			
	Total number of hydrants	N/A	N/A	
	II D	N/A	N/A	
3 Pun	nping Arrangements.			
	• Ground Level	N/A	N/A	
	Discharge of main Pump	N/A	N/A	20 40 40 40 40 40 40 40 40 40 40 40 40 40
	> Head of Main pump	N/A	N/A	
	Number of main pumps	N/A	N/A	
	Jockey Pump out put	N/A	N/A	
	Jockey pump head	N/A	N/A	NAME AND ADDRESS A
	Standby Pump out put	N/A	N/A	
	Standby Pump Head	N/A	N/A	
	> Auto Starting/ Manual	N/A	N/A	
	stopping	N/A	N/A	
	Pump House Access	N/A	N/A	
	• Terrace level	225 LPM	Provided	MR
	Discharge of pump		Provided	MR
	Head of the pumpPower Supply	30 mts	Provided	MR
	Auto Starting of pump	Required	Provided near	MR
			ground floor	2
14 C	aptive Water Storage for fire fight			5
	 Underground tank capacity 	N/A	N/A	
	Draw-off connection	N/A	N/A	
	Fire service inlet	N/A	N/A	
	Access to tank	N/A	N/A	
	 Overhead Tank capacity 	2500 liters	Provided	MR
15 F	Exit Signage.	Required	Provided	MR
	Provision of Lifts.			
	Pressurization of Lift Shaft	N/A	N/A	

R.



	 Pressurization of Lift lobby 	N/A	N/A	
	Communication In lift CarFireman's Grounding SwitchLift Signage	N/A	N/A	
		N/A	N/A	
17		N/A	N/A	
18	Refuge Area.	Required	Provided	MR
	Total AreaLocation	N/A	N/A	
19	Fire Control Room	N/A	N/A	
	Detector System Panel	N/A	N/A	
	Flow Switch Panel PA System Page 1	N/A	N/A	
	The System Panel	N/A	N/A	
	Batter backupBuilding Floor Plans	N/A	N/A	
0	Special Fire Protection Systems for	N/A Required	N/A	
	Protection of special Risks, if any:	Required	01 CO ₂ type fire extinguisher	MR
			provided near elect. panel	

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Note:- Previously, this department was issued NOC (**26 guest rooms**) from fire safety and means of escape point of view for ground floor (02 guest rooms +reception+01 store), Mezzanine floor (store), 1st floor (08 guest rooms), 2nd floor (08 guest rooms) & 3rd floor (08 guest rooms). Few rooms altered at 1st, 2nd and 3rd floor of the guest house. Now, the details of rooms /occupancy floorwise at ground floor (02 guest rooms) +reception+01 store), Mezzanine floor (store), 1st floor (07 guest rooms), 2nd floor(07 guest rooms). i.e. total **23 guest rooms** is recommended for renewal.

Forwarded plane 313.

Signature of the Inspecting Officer Name M.K.CHATTOPADHYAY Designation: - Asstt. Div. Officer (CC)