## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No.F.6/DFS/MS/School/2013/ 2 2

Dated: 26/04/2013

## FIRE SAFETY CERTIFICATE

Certified that the building of Daisy Dale Convent School located at 183-B, A-Block, Shyam Vihar, Phase-I, Najafgarh, New Delhi-110043 comprised of ground floor plus one upper floor, having total 17 rooms (Including Class Rooms, Office, Comp. Lab, Library, & Store etc.) owned/occupied by Mata Kalawati Charitable Trust was inspected by the officer concerned of this department on 16.04.2013 in the presence of Sh. Rahul Chaudhary and found that the school management have complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on 26/4/13 at New Delhi.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Men

Copy to:-

- 1. The Manager, Daisy Dale Convent School, 183-B, A-Block, Shyam Vihar, Ph-I, Najafgarh, New Delhi-110043.
- 2. Director of Education. Govt. of NCT of Delhi, Old Secretariat, New Delhi – 110054.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

ADO (SRd)

## N/1. Ground floor plus one upper floor.

INSPECT	TION REPORT				
Name & address of the building:	Daisy Dale Co.	nvent School, 18	3-B, A-Block Sh		
	Daisy Noile Convent School, 183-B. A-Block SI Educational (School) Vihar, Ph-I, Najat Gash, N.				
7 Type of Case	: New Case/Renewal				
<ol> <li>Details of Previous NOC</li> </ol>	: Letter No	and the second	Dated		
5. Fire Safety directives letter No :		NA			
<ol> <li>Date of inspection</li> </ol>	16.04.2013				
<ol><li>Name of Inspecting Officer</li></ol>	: A.D.O P.S. Dahiya				
<ol> <li>Mame and designation of office</li> </ol>	ers	0			
From the building side	Sh. Rahal Choudhasy				
rear of Construction	2005				
O. Applicant's letter No.	Nil dad	ed MiL			
Minimum Standards on fire prevention	Dir. Of Edu.	Provided at site	Remarks		
and fire safety U/R 33	Circular dt.		MR/NMR		
	01.03.2011				
Access to building					
<ul> <li>Road width</li> </ul>	Acressible	07.50 mtr	MR		
<ul> <li>Gate width</li> </ul>	•	430 cms, 245 cms	MR		
<ul> <li>Width of internal road</li> </ul>		_	~		
Number, Width, Type & Arrangement of	Exits				
Number of staircases					
<ul> <li>Upper Floors</li> </ul>	7000	Two	MR		
<ul> <li>Basements</li> </ul>	1 .	100	The state of the s		
			No Basement		
Width of staircases					
<ul> <li>Upper Floor</li> </ul>	150cms	239cms, 121cms	MR		
<ul> <li>Basements</li> </ul>			No Basement		
Protection of exits	*				
<ul> <li>Fire check door</li> </ul>	•	<b>y</b> -	*		
<ul> <li>bressurization</li> </ul>					
	3				
No of continuous staircases to		A			
ferrace	*	One			
e Width of Corridor		240 cms	_		
f Door Size					
ya		103 cms x 202 cm			
Compartmentation					
<ul> <li>Fire check door</li> </ul>					
<ul> <li>Sealing of electrical shafts</li> </ul>					
<ul> <li>Fire Rating of shaft door</li> </ul>	<b>C</b>	<u> </u>			
<ul> <li>Water Surfain</li> </ul>					
<ul> <li>Fire Dampers</li> </ul>					
	•				
Smoke Management System					
• Basements	30 a/c per hour		A STATE OF THE STA		
		_	No Basement		
<ul> <li>oper floors</li> </ul>			INO DEPONICIO		
		the facility of the facility o			
	T.	Natural Ventilation MR			

## N/3- 183-B, A-Block Shyam Vihar, Ph-I, Majatgarh, New Delki-43.

	<ul><li>Pump House Access</li><li>Terrace level</li></ul>	V	<b>V</b>	~		
	<ul> <li>Discharge of pump</li> <li>Head of the pump</li> <li>Power Supply</li> <li>Auto Starting of pump</li> </ul>		6			
		•	~	7		
		-				
	- Barrip			~		
14.	Captive Water Storage for fire fighting					
	<ul> <li>Underground tank capacity</li> </ul>					
	P Draw-off connection		· ·			
Fire service inlet						
	Access to tank		-	_		
<ul> <li>Overhead</li> </ul>	<ul> <li>Overhead Tank capacity</li> </ul>		THE STATE OF THE S			
15.	Exit Signage.	Required	Provided	MR		
16.	Provision of Lifts.					
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> </ul>		<b></b>	No Ciff		
			7	-do-		
			<u></u>	-do-		
	• Fireman's Grounding Switch		Page .	-do-		
<ul> <li>Lift Signage</li> </ul>		and the second s	-do-			
17.	Standby power supply			**************************************		
18.	Refuge Area.					
ole kor s	> Total Area					
	> Location	•	* * * * * * * * * * * * * * * * * * * *	-		
	1		_			
19.	Fire Control Room					
	<ul> <li>Detector System Panel</li> </ul>					
	<ul> <li>Flow Switch Panel</li> </ul>			The second secon		
	<ul> <li>PA System Panel</li> </ul>		Section 1	Read of the second seco		
	<ul> <li>Batter backup</li> </ul>	0				
	<ul> <li>Building Floor Plans</li> </ul>	Kegluired	Provided	MR		
20.	Special Fire Protection System for Protection of special Risks, if any:		-			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety ertificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Note: The school building is comprised of Ground floor plus one cepper floor. The cepper floor is served by two staircases having width 239 cms & 121 cms respectively. There are total 17 hooms including class rooms, office, comp. Lab, Library & Store etc. In each class students less than 45.

Signature of Inspecting Officer

Designation ASSH. Divisional Officer.

Signature of Inspecting Officer

Name

Designation