## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

No. F.6/DFS/MS/GH/2013/ 2 . 7

Dated: 25/04/13

## **FIRE SAFETY CERTIFICATE**

Certified that the **Hotel City Castle** located at 1100/12-13, Hari Singh Nalwa Street, Naiwalan, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus four upper floors, using basement as Storage purposes, ground floor as reception, office and lobby, first & second floor each having eight guest rooms respectively, third & forth floor each having nine guest rooms respectively (Total Thirty Four guest rooms), Terrace floor sealed with bricks wall was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/1402 dated 12.05.2010 owned/occupied by Sh. Dharam Prakash Sharma. The guest house building was re inspected by the officers concerned of this department on 11.04.2013 in the presence of Sh. D.P. Sharma (owner) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule \$7 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on 25/04/2013 at New Delhi.

CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to:-

- 1. The Addl. Commissioner of Police (Lic.) 1<sup>st</sup> floor, P.S., Defence Colony, New Delhi. (Re. No.12291/Addl. C.P./Lic.(H), Dated 12.03.2013)
- 2. Sh. Dharam Prakash Sharma (Owner), City Castle, 1100/12-13, Hari Singh Nalwa Street, Naiwalan, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

## N/23. Basement, Ground Floor plup four upper Floors.

	INSP	ECTION REPORT			
	1. Name & address of the buildin	g: Hotel City Ca	1410 114-115 15	110 100	
	2. Type of Occupancy	Residential 1	plies + Univers	Maissingh A	19/100 street
	3. Type of Case	: New Case/Rene	wal	, Kan	or Bogh N.
	4. Details of Previous NOC	letter No CCIA	FC/MC/CHIZOMI	lan Data 10	
	<ol><li>Fire Safety directives letter No</li></ol>	:	MA	402 Date 12.1	5.2010
	6. Date of inspection	11.00	4.2012	1.00	
	7. Name of Inspecting Officer	N.A 4.1. A.	reja & A.D.C	P.C hal	1. 0
	8. Name and designation of office	ers	Ta P. N. S.C	1 3, Dar	nya
	From the building side	Sh. D.P.	Sharma (owner),	Sh. Airy C	ral Co. m
	9. Year of Construction	DETORE	1991	V	0
S.	10. Applicant's letter No.	12291/Add1. C.P	./LIC. (H) dated	12.03.201	13
No.	Minimum Standards on fire	NBC/BBL	Provided at	Remarks	
1.	prevention and fire safety U/R 33	Requirement	site	MR/NMR	approximate the
4.	Access to building			1	
	Road width	Accessible	09mts	MR	
	Gate width		120 cmp	MR	
7	Width of internal road	_	_	, ,,,	2
2.	Number, Width, Type & Arrangeme	ent of Exits			
	a. Number of staircases				-
	• Upper Floors	Two	Two	Me	
	Basements	One	One	MR	
	b. Width of staircases		Une	MR	
	Upper Floor	<b></b>	121cms, 90cms	Me Dai	01/0-
	Basements	No.	130 cms	-dol-	Ula Case
	c. Protection of exits		130 cmp	- 400-	
	<ul> <li>Fire check door</li> </ul>				
	* pressurization				
	To or continuous staircases to	The second secon			
	terrace e. Width of Corridor	the second of th	One		
	e. Width of Corridor f. Door Size				
	1. Door Size		260 Cms, 170cms	-	
3.	Compartmentation		79 Cms x 203 cms	-	
	The state of the s	2 2			
	Fire check door	-			
	<ul> <li>Sealing of electrical shafts</li> </ul>		Sealed		
	<ul> <li>Fire Rating of shaft door</li> </ul>		Seared	MR	
	Water Curtain				
	<ul> <li>Fire Dampers</li> </ul>		-		
4.	Smoke Management System			And the second s	
	A STELL				
		120 /	Exposit Para	-	
		30 a/c per	Exhaust fans are Provided	MR	

Auto Starting/Manual

stopping

Maissala, Karol Bagh, New Delli-

_		, , , , , , ,	1				
	Pump House Access		5 A 2 A A A				
	<ul> <li>Terrace level</li> </ul>		•				
	Discharge of pump	110010	1.0.				
	Head of the pump	450 LPM	450 LPM	MR			
	Power Supply	30 M Required	30 M Provided	MR			
	Auto Starting of pump	required	Provided	MR			
14.	Captive Water Storage for fire fighting	g					
	<ul> <li>Underground tank capacity</li> </ul>						
	Draw-off connection			<u> </u>			
	Fire service inlet		^	-			
	Access to tank		Provided	MR			
	<ul> <li>Overhead Tank capacity</li> </ul>		****				
	and capacity	-	Soooltr	MR, Being a old			
15.	Exit Signage.	Required	Provided	MR			
	zxit oightige.	1/10/10/10	1 80 VICICA	IVIK			
16.	Provision of Lifts.						
	• Pressurization of Lift Shaft						
	The state of the s			-			
	• Pressurization of Lift lobby	~					
	Communication In lift Car		P				
	<ul> <li>Fireman's Grounding Switch</li> </ul>	0	Provided	MR			
	<ul> <li>Lift Signage</li> </ul>	required	- do -	MR			
		-do-	-do-	MR			
17.	Standby power supply	Required -do- Required	Provided	mR			
18.	Refuge Area.			5			
	Total Area						
	Location		**************************************				
	1	_	·	-			
19.	Fire Control Room						
	<ul> <li>Detector System Panel</li> </ul>						
	Flow Switch Panel		-	10			
	PA System Panel		. d=				
	Batter backup	t <sub>person</sub>					
	<ul><li>Building Floor Plans</li></ul>	Required	Provided	1000			
	Sanding Floor Plans	1 - paroey	i sovided	MR			
				•			
0.	Special Fire Protection System for						
	Protection of special Risks, if any:	•					
	The state of special Kisks, it and	1	1	L.			

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Name H.L. Aneja Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya

Designation Asstl. Divisional Officer.