

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: NEW DELHI-110001

NO. f6/DFS/MS/School/2013/217

Dated: 26/04/2013

FIRE SAFETY CERTIFICATE

Certified that the Meer Public School, located at Meer Vihar, Madan Pur Dabas Delhi-110081 comprised of a Single block with G + One upper floor was issued Fire Safety Certificate Vide letter No F-6/DFS/MS/2006/819 Dated 04/04/2006. The new block comprised of Ground + two upper floors with second floor used as residence has now been constructed and occupied by Meer Public School was inspected by the officer concerned of this department on 07/03/2013 in the presence of Sh. Dharamvir Singh Dabas and has deemed complied with fire prevention & fire safety requirement in accordance with the Circular No. 262-362 at 17/01/05 issued by Director of Education. Both the blocks of the premise is fit for renewal of occupancy of Group Class B (Educational) with effect from 26/04/2013 for a period of three years, with the conditions mentioned below.

Conditions for the validity of Fire Safety Certificate:

1. All the fire safety arrangement provided there-in shall be maintained in good working conditions at all times.
2. Loss of life or property due to non functional fire safety measure shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation with regard to the construction etc shall be verified by the concerned building sanctioning agency.
5. The basement shall be used strictly as per the provision of building bye laws.
6. This certificate cannot be treated in any case for regularizations of unauthorized construction if any.
7. The second floor shall not be used for school purposes as furnished in affidavit by school.
8. The owner / occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on WWW.dfs.Delhigovt.nic.in

Issued on 26.04.13 at New Delhi by


(SANTOKH SINGH)
Chief Fire Officer
Delhi Fire Service
Ph: 011-23414250
cfowz.dlfire@nic.in

Copy to:

1. The Principal, Meer Public School, located at Meer Vihar, Madan Pur Dabas Delhi-110081.
2. The Director of Education, Old Secretariat, Delhi

S/N

INSPECTION REPORT

1. Name & address of the building: Meer Public School, Meer Vihar, Delhi-81
2. Type of Occupancy: Educational
3. Type of Case: New Case/ Renewal
4. Details of previous NOC: Letter No. F-6/DFS/MS/2006/819 Dated: 4-4-2006
5. Fire Safety directives letter No: Circular, Director of edun. 17-1/05 & 1-3/11
6. Date of inspection: 07-3-2013
7. Name of the Inspecting Officers: ADO - SHYAM LAL
8. Name and designation of officers from the building side: Sh. Dharamvir Singh Dabas
9. Year of Construction: 2000, & 2010, (G+1) & G+2 but second floor - vacant, A.P.P. floor enclosed, C-17. (3C - G+1 only)
10. Applicant's letter No. AA/012/2013 dated 2-2-2013

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement <i>Circular Dir. of edun. 17-1-2005</i>	Provided at site	Remarks MR/NMR
1	Access to building			
	• Road width	Accessible	9 m	MIR
	• Gate width	-n-	3 m x 3	MIR
	• Width of internal road	-n-	open ground	MIR
2	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases	Block-I = 2 Block-II = 2	Block-I = 2 Block-II = 2	MIR
	• Upper Floors	-do-	-do-	MIR
	• Basements	NIL	NIL	NIL
	b. Width of staircases			
	• Upper Floors	1.5 m	Block-I = 1.10 m each Block-II = 1.24 m each	MIR
	• Basements	NIL	NIL	NIL
	c. Protection of exits			
	• Fire check door		NIR	
	• Pressurization			
	e. No. of continuous staircases to terrace			
	g. Width of Corridor	R	2.46 m	MIR
	h. Door Size	1 m	1 m. with door fitting	MIR
3	Compartmentation.			
	• Fire check door			
	• Sealing of electrical shafts		NIR	
	• Fire Rating of shaft door			
	• Water Curtain			
	• Fire Dampers			
4	Smoke Management System.			
	• Basements	30 a/c per hour	NIR	
	• Upper floors	12 a/c per hour		

*[15 class room = 1 door
12 class room = 2 door] Less than 15 student.*

Captive Water Storage for fire fighting.			
<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 		NIR	
	10000 Lts.	Provided	MIR
15	Exit Signage.	R	Provided MIR
16 Provision of Lifts.			
<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 		NIA	
17	Standby power supply		NIR
18 Refuge Area.			
<ul style="list-style-type: none"> ➤ Total Area ➤ Location 		NIA	
19 Fire Control Room			
<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 		NIR	
20	Special Fire Protection Systems for Protection of special Risks, if any:	-	NIL -

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial numbers.....

Signature of the Inspecting Officer
 Name: *[Signature]*
 Designation: *D.O. (NW)*
20/5/13
DCFO (4)

Signature of the Inspecting Officer
[Signature]
 Name: (SHYAM LAL)
 Designation: Assitt. Divn. officer
 9/3/2013