GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001.

Fax: 011-23412593 E-mail: cfohq.dlfire@nic.in
No.F6/DFS/MS/EH/2013/ 212

Dated: 25/4//3

FIRE SAFETY CERTIFICATE

Certified that the Harry's (Karaoke Lounge Bar), A Unit of Harry's Kitchen Pvt. Ltd. located at C-306-307, IIIrd Floor Ansal Plaza, Khel Gaon, New Delhi-110049. comprised of 2 Basement, Ground + 3 Upper Floors but the Restaurant is running on 3rd floor only was granted NOC by this department vide letter No.F6/MS/DFS/EH/2010/469 dated 16/02/10 The premises was re-inspected by the officer concerned of this department on 13/04/13 in the presence of Mr. Peter Paul and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group – D Assembly Building with effect from—25/14/1/3——for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010 subject to conditions printed below.

Issued - <u>2514113</u> --- at New Delhi by.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

- Copy to:- (1) Dy. Health Officer, Municipal Corporation of Delhi, Health Department, Central Zone, Lajpat Nagar, New Delhi.
- (2) Harry's (Karaoke Lounge Bar), A Unit of Harry's Kitchen Pvt. Ltd., C-306-307, IIIrd Floor Ansal Plaza, Khel Gaon, New Delhi-110049. Following fire safety directives must be adhered to:-
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 5. The basement shall be used as per the provisions of BBL.
 - 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1. Name & address of the building:- Harry's (Karaoke Lounge Bar), A Unit of Harry's Kitchen Pvt. Ltd., C-306-307, IIIrd Floor Ansal Plaza, Khel Gaon, New Delhi-110049.
- 2. Type of occupancy:- Group D Assembly Building (Eating House)
- 3. Type of case:- Renewal.
- 4. Details of previous NOC:-No.F6/MS/DFS/EH/2010/469 dated 16/02/10
- 5. Fire safety directives No.- No
- 6. Date of inspection: 13/04/13
- 7. Name of the inspecting officer:- A.D.O. S.S. Kaushik
- 8. Name & designation of officer From the building side:- Mr. Peter Paul.
- 9. Year of construction: 2008.
- 10. Applicant's letter No:-Nil. dated 11/03/13 2 Basement, Ground + 3 Upper Floors. **The Restaurant is running on 3rd floor only**

					Old case
S.No.	displaying to the second	Minimum Standards on fire	Requirement	Provided at	Remarks
		Prevention and fire safety U/R 33		site	M/R/NMR
1.		Access to Building			
		1) Road width	Existing in mall	Provided	M/R
		2) Gate width	N/A	N/A	N/A
		3)Width of internal road	N/A	N/A	N/A
2.		Number, Width Type & Arrange	1.0		
		A. Number of staircases	Provided & maintained by mall	Provided maintained by mall management	3
		1. Upper floors	2 Nos.	2 Nos.	M/R
	outp-state	2. Basements	N/A	N/A	N/A
	and the same of th	B. Width of staircase			
	CP Comments	1. Upper floors	Required	1.5mtrs	M/R
	AND DESCRIPTION OF THE PERSON	2. Basements	N/A	N/A	N/A
	and representation of the second	C. Protection of exits			
		1. Fire check door	Yes	Provided	M/R
		2. Pressurization	Yes	Provided	M/R
	8	D. No. of continuous staircase to terrace	2 Nos.	two	M/R
	-	E. Width of corridor	1.5 mtr.	Yes	M/R
2 25 2 2	ondradica null a poste vid	F. Door size	Required two	2 Nos. Provided	M/R
3.	ALL DESCRIPTION OF THE PERSON	Compartmentation			
		1) Fire check door	N/A	N/A	N/A
	-	2) Sealing of electrical shafts	N/A	N/A	N/A
	- Contract of the Contract of	3) Fire rating of shaft door	N/A	N/A	N/A
		4) Water curtain	N/A	N/A	N/A

	5) Fire Dampers	N/A	N/A	N/A
•	Smoke Management System		DT/A	N/A
,	1) Basements	30 a/c per hour	N/A	M/R
	2) Upper floors	12 a/c per hour	Exhaust fan provided	M/R
	Fire Extinguishers		O Mas	M/R
	1) Total numbers		8 Nos. ABC, Co2 &	M/R
	2) Types	ISI Marked	W.Co2	M/R
	3) ISI marking	1	Yes	M/K
ó.	First-Aid Hose Reel			M/R
	1) Total number of each floor	Maintained by mall	2 Nos. near to restaurant	
	2) Length of hose reel hose	30 m	Yes	M/R
	3) Nozzle diameter	5 mm	Yes	M/R
7.	Automatic Fire Detection & Alarmi	ing System		1 - 6/2
1.	1) Type of detectors	Provided & maintained by mall Management	Provided & maintained by mall Management	M/R
	2) Location of main panel	do	do	do
	3) Location of repeater panel	do	do	do
	4) Alternate source of power	do	do	do
	5) Hooter's Location	do	do	do
0	MOEFA	Required	Provided	M/R
9.	Public Address System	Provided & maintained by mall	Provided	M/R
10.	Automatic Sprinkler System	Provided & maintained by mall	Provided & maintained by mall	
	1) Basement	do	do	
	2) Upper floors	do	do	
	3) Sprinkler above false ceiling	do	do	do
11.	Internal Hydrants			
	1) Size of riser/down-comer	Provided & maintained by mall	Provided & maintained by mall	M/R
	2) Number of hydrants per floor	do	do	
	3) Hose box	do	do	- do
12.	Yard Hydrants			
12.	1) Total number of hydrants	Provided & maintained by mall	Provided & maintained by mall	M/R
	2) Hose box	do	do	do
12	Pumping Arrangement			
13.	rumping Arrangement			

X	1) Ground level	ALL AND THE STREET		
X .	1) Ground level	Provided &	Provided &	MR
		maintained by	maintained	
	a) Discharge of main pump	mall	by mall	-, ,
	b) Head of main pump	do	do	do
	punip	do	do	
	, and of main pump	do	do	
	, pamp out put	do	do	do
	e) Jockey pump head f) Stand by pump output	do	do	4.0
	, pamp output	do	do	
	g) Stand by pump head h) Auto starting/Manual stanning	do	do	
	- Triandal Stoppii	ngdo	do	40
	2) Terrace level	-		40
	a) Discharge of pump	do	do	do
	b) Head of pump	do	do	
	c) Power supply	do	do	do
14.	d) Auto starting of pump	do	1	
14.	Captive Water Storage for Fire Figh	iting :- Provided & m	aintained by mal	do
	1) Under ground tank capacity	Provided &	Provided &	MR
1,		maintained by	maintained by	
	a) Draw-off connection	mall	mall	-
	b) Fire service inlet	do	do	do
	c) Access to tank	do	do	do
	d) Over head tank capacity	do	do	do
15.	Exit Signage.	do Required	do	do
16.	Provision of Lifts.	Required	Provided	MR
	a) Pressurization of lift shaft		×	
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	, and a switch	Yes	Provided	MR
	e) Lift signage	Yes		
17.	Stand by Power Supply	Yes	Provided	MR
18.	Refuge Area	N/A	Provided	MR
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	Ground floor	N/A	N/A
	b) Flow switch panel	N/A	Ground floor	MR
and an order	c) PA system panel	N/A	N/A	N/A
and the same of th	d) Battery backup	Yes Yes	N/A	N/A
	e) Building floor plan	Yes	Provided	MR
20.	Special Fire Protection System for Pro	testion of	Provided	MR
	Joseph Ioi Filo	oi special Ris	k, if any:	N/A
		1		

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/-----

Accordingly DFA is put up please.

Signature of the inspecting officer

Signature of the inspecting officer

Name:- Dharampal Bharadwaj

Designation:- Divisional Officer

Name: S.S.Kaushik.

Designation: - Assistant Divisional Officer.