GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 23412593, E-mail: cfohq. dlfire@nic.in Tel: 011-23414333

No.F6/DFS/MS/EH/2013/ 269

Dated: (26/05) 20/3

FIRE SAFETY CERTIFICATE

Certified that the Restaurant in the name and style of Mc Donald,s Restaurant located at ground floor of property No. 4964-64/1, plot No. E-25, Netaji Subhash Marg, Darya Ganj, New Delhi-110002 owned / occupied by M/s. Mc Donald,s Restaurant (Connaught Plaza Restaurant Pvt. Ltd.) the building comprised of basement (storage), ground floor (restaurant), first to third floor (residence) have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi fire service rules, 2010 and verified by the officer concerned of fire service on 26-04-2013 in the presence of Mr. D.N. Thakur manager of Restaurant and building is fit for occupancy for restaurant with effect from. S. J. S. ... for a period of three years in accordance with rule 36 unless renewed under rule 37 of sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules, 2010.

Issued at New Delhi.

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service Tel:- 011-23414333

E-Mail:- cfohq.dlfire@nic.on

Copy to:

- 1. M/s Mc Donalds Family Restaurant, (Connaught Plaza Restaurant Pvt. Ltd.) property No. 4964-64/1, plot No. E-25, Netaji Subhash Marg, Darya Ganj, New Delhi-110002
- 2. Dy. Health Officer, Central Zone, South Delhi Municipal Corporation, Health Department, Jal Vihar, Lajpat Nagar, New Delhi

Condition for the validity of fire safety certificate

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.

3. The trained fire fighting staff should be available round the clock.

4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.

5. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.

Antil Bhardway.

Mc Donald,s Restaurant, No. 4964-64/1, plot No. E-25, Netaji Subhash Marg, Daryaganj, New Delhi-110002

INSPECTION REPORT

1. Name & address of the building : Mc Donald,s Restaurant, 4964-64/1, plot No. E-25, Netaji Subhash

Marg, Daryaganj, New Delhi-110002

2. Type of Occupancy : Eating House

3. Type of Case : New Case

4. Details of previous NOC : Letter No. N/A dated N/A

5. Fire Safety directives Letter No. : N/A

6. Date of inspection : 26-04-2013

7. Name of the Inspecting Officer : Sh. D.S. Yadav (D.O.)

8. Name and designation of Officer

from the building side : Mr. D.N. Thakur (manager)

9. Year of Construction : N/A

10. Applicant's letter No. : Nil dated 25-02 2013

S No	Minimum standards on fire prevention	BBL	Provided at site (PSS Area)	Remarks MR/NMR
	and fire safety U/R 33	Requirements	(PSS Alea)	
1.	Access of building	accessible	18 mtrs. Approx	MR
	Road width	N/A	2 mtrs.	. N/A
	• Gate width	N/A N/A	Three side open	
	 Width of internal road 		Timee side open	
2.	Number, width, Type & Arrangements of exits			
	a. Number of staircases	N. I. / A	N/A	N/A
	 Upper floors 	N/A		N/A
,	 Basements 	N/A	N/A	IN/A
	b. Width of staircases			N/A
	 Upper floors 	N/A	N/A	N/A N/A
	 Basements 	N/A -	N/A	N/A
	c. Protection of exits			NI/A
	 Fire check door 	N/A	N/A	N/A
	 Pressurization 	N/A	N/A	N/A
	d. No of continuous staircase to terrace	N/A	N/A	N/A
	e. Width Of Corridor	N/A	N/A	N/A
	f. Door Size	N/A	N/A	N/A
3.	Compartmentation			NI/A
	Fire check doorSealing of electrical shaftsFire Rating of shaft door	N/A	N/A	N/A N/A
		N/A	N/A	N/A N/A
		N/A	N/A	N/A N/A
	Water Curtain	N/A	N/A	N/A N/A
	Fire Dampers	N/A	N/A	IV/A
4.	Smoke managements System			MD
	Basements	30 a/c per hour		MR
ý l	Upper floors	12 a/c per hour	Natural ventilation	MR
5.	Fire Extinguishers			

Mc Donald, Restaurant, No. 4964-64/1, plot No. E-25, Netaji Subhash Marg, Daryaganj, New Delhi-1100 MR Total numbers Co2 & A.B.C. MR Types type. MR IS marking ISI marked Provided First – Aid Hose Reels 6. 01 01 MR Total numbers on each floor 30 M Provided MR Length of hose reel hose Provided 5 mm MR Nozzle diameter 7. Automatic fire detection and alarming system N/A Smoke/heat MR Type of detectors N/A Ground floor MR Location of Main Panel N/A N/A N/A Location of Repeater Panel U.P.S. (15KVA) MR Alternate source of power yes Hooters' Location Near gate Near gate MR Yes Provided 8. **MOEFA** MR Public Address System/Intercom 9. N/A N/A N/A 10. Automatic Sprinkler System N/A Separate entry/exit MR Basements Provided at ground Upper Floor N/A MR floor N/A N/A N/A Sprinkler above false ceiling Internal Hydrants 11. N/A 100 mm N/A Size of riser/down-comer Yes 01 at ground floor Number of hydrants per floor MR Provided MR Yes Hose Box 12. Yard Hydrants Total number of hydrants N/A N/A N/A N/A N/A N/A Hose Box Pumping Arrangements 13. Ground Level N/A N/A N/A Discharge of main pump N/A N/A Head of main pump N/A Number of main pumps N/A N/A N/A Jockey pump out put N/A N/A N/A Jockey pump head N/A N/A N/A Standby Pump out put N/A N/A N/A Standby Pump Head N/A N/A N/A auto Staring/Manual stopping N/A N/A N/A Pump House Access N/A N/A N/A Terrace level Discharge of pump 450 LPM & Provided MR 180 LPM Head of the pump -> 35 Mtrs. Each Provided MR Power supply Electric Electric MR Auto starting of pump Yes Provided MR 14. Captive water Storage for fire fighting N/A Under ground tank capacity N/A N/A Draw of connection N/A N/A N/A Fire service inlet N/A N/A N/A Access to tank N/A N/A N/A Overhead Tank capacity 10000 ltrs. 10000 ltrs MR 15 Exit Signage Yes Provided MR

16.

Provision of Lifts

Donald,s Restaurant, No. 4964-64/1, plot No. E-25, Netaji Subhash Marg, Daryaganj, New Delhi-110002 N/A N/A N/A Pressurization of Lift Shaft N/A N/A N/A Pressurization of lift lobby N/A N/A N/A Communication in lift Car N/A N/A Fireman's Grounding Switch N/A N/A N/A N/A Lift Signage MR D.G. Set (160 YES Standby power supply 17. KVA) Refuge Area 18. N/A N/A N/A > Total area N/A N/A > Location N/A Fire control room 19. N/A N/A N/A Detector system panel N/A N/A N/A Flow Switch Panel N/A N/A N/A PA System Panel N/A N/A N/A Batter backup N/A N/A **Building Floor Plans** N/A N/A N/A N/A Special Fire Protection Systems for 20. Protection of special Risks, if any;

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Signature of the Inspecting Officer

Name

Designation pero on leave

Signature of the Inspecting Officer

Name Thatm vis singh yelde.

Designation Divisional Offices (6:3)