GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE,NEW DELHI-110001

Fax: 011-23412593 E-mail:cfohq.dlfire@nic.in Ph. 011-23414333.

No.F6/DFS/MS/EH/2013/ 278

Dated: 08/05/13

FIRE SAFETY CERTIFICATE

Certified that the M/s Setz DLF Emporio Restaurant located at Shop No. 405,2nd Floor,Plot No.4, DLF Emporio,Vasant Kunj,New Delhi.comprised of 3 Basement, Ground,Upper Ground + 2 Upper Floors but the Restaurant is running on 2nd floor only was granted NOC (old Name Zest) by this department vide letter No.F6/MS/DFS/EH/2010/1789 dated 18/06/10 The premises was re-inspected by the officer concerned of this department on 26/04/13 in the presence of Mr. Tusar and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class Group – D Assembly Building with effect from—Only of a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010 subject to conditions printed below.

Issued -08/05/13 --- at New Delhi by.

(Dr. G. C. Misra) Chief Fire Officer Delhi Fire Service

ore

- Copy to:- (1) Dy. Health Officer,
 South Zone, South Delhi Municipal Corporation,
 Office of Dy. Health Officer/South Zone,
 Aurbindo Marg, Green Park, New Delhi.
 - (2) M/s Setz DLF Emporio Restaurant, Shop No. 405,2nd Floor,Plot No.4, DLF Emporio,Vasant Kun,New Delhi.

Following fire safety directives must be adhered to:-

- 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
- 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
- 3. The trained fire fighting staff should be available round the clock.
- 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
- 5. The basement shall be used as per the provisions of BBL.
- 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

Mha

INSPECTION REPORT

- 1. Name & address of the building:- M/s Setz DLF Emporio Restaurant, Shop No. 405,2nd Floor,Plot No.4, DLF Emporio,Vasant KunjNew Delhi.
- 2. Type of occupancy:- Group D Assembly Building (Eating House)
- 3. Type of case:- Renewal
- 4. Details of previous NOC:-No.F6/MS/DFS/EH/2010/1789 dated 18/06/10 in the name of Zest
- 5. Fire safety directives No.- No
- 6. Date of inspection: 26/04/13
- 7. Name of the inspecting officer:- A.D.O. S.S. Kaushik
- 8. Name & designation of officer From the building side:- Mr. Tusar.
- 9. Year of construction: 2007
- 10. Applicant's letter No:-Nil. dated 30/03/13 3 Basement, Ground, Upper Ground + 2 Upper Floors. The Restaurant is running on 2nd floor only

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement	Provided at	Remarks		
1.	Access to Building		site	MR/NMR		
	1) Road width	Existing in mall	Provided	MR		
	2) Gate width	N/A	N/A	N/A		
	3)Width of internal road					
2.		N/A	N/A	N/A		
	Number, Width Type & Arrangement of Exits A. Number of staircases					
	1. Upper floors	A '1 11 '				
		Available in mall	Maintained by mall	MR		
	2. Basements	do	do	do		
	B. Width of staircase					
	1. Upper floors	do	do	do		
-	2. Basements	do	do	do		
1	C. Protection of exits					
	1. Fire check door	Yes	Provided	MR		
	2. Pressurization	Yes	Provided	MR		
	D. No. of continuous staircase	2 Nos.	two	MR		
	to terrace					
	E. Width of corridor	1.5 mtr.	Yes	MR		
	F. Door size	Required	2 mtr.	MR		
•	Compartmentation					
	1) Fire check door	Yes	Provided	MR		
	2) Sealing of electrical shafts	Yes	Provided	MR		
	3) Fire rating of shaft door	Yes	Provided	MR		
	4) Water curtain	N/A	N/A	N/A		
	5) Fire Dampers	N/A	N/A	N/A		
	Smoke Management System					
	1) Basements	30 a/c per hour	N/A	N/A		
Talan and a second	2) Upper floors	12 a/c per hour	Exhaust fan	MR		
			provided			
×	Fire Extinguishers					
	1) Total numbers	ISI Marked	10 Nos.	MR		
	2) Types		ABC, Co2 & W.Co2	MR		
	3) ISI marking			MR		



6.	First-Aid Hose Reel	,		
3	1) Total number of each floor	Maintained by	2 Nos. near to	MR
		mall	restaurant	
	2) Length of hose reel hose	30 m	Yes	MR
	3) Nozzle diameter	5 mm	Yes	MR
7.	Automatic Fire Detection & Alarming			3.00
	1) Type of detectors	Provided &	Provided &	MR
		maintained by	maintained	
	0) Y	mall	by mall	
	2) Location of main panel	do	do	do
	3) Location of repeater panel	do	do	do
	4) Alternate source of power	do	do	do
	5) Hooter's Location	do	do	do
8.	MOEFA	Required	Provided	MR
9,	Public Address System	Provided & maintained by	Provided	MR
		mall		
10.	Automatic Sprinkler System			
	1) Basement	Yes	Provided	MR
	2) Upper floors	Yes	Provided	MR
	3) Sprinkler above false ceiling	Yes	Provided	MR
11.	Internal Hydrants			2.
	1) Size of riser/down-comer	Provided &	Provided &	MR
		maintained by	maintained	
	* *	mall	by mall	No.
	2) Number of hydrants per floor	do	do	do
	3) Hose box	do	do	do
12.	Yard Hydrants		2	
	1) Total number of hydrants	Provided &	Provided &	MR
		maintained by	maintained	
		mall	by mall	
	2) Hose box	do	do	do
13				
13.	Pumping Arrangement			
	1) Ground level	Provided &	Provided &	MR
		maintained by	maintained	
	a) Discharge of main numer	mall	by mall	1
	a) Discharge of main pump	4550 LPM	do	do
	b) Head of main pump	40 mtr.	do	do
	c) Number of main pump	Two	do	do
	d) Jockey pump out put	180 LPM	do	do
	e) Jockey pump head	40 mtr.	do	do
	f) Stand by pump output	4550 LPM	do	do
	g) Stand by pump head	40 mtr.	do	do
	h) Auto starting/Manual stopping	Yes	do	do
	2) Terrace level		. *	
	a) Discharge of pump	450 LPM	do	do
	b) Head of pump	40 mtr.	do	do
	c) Power supply	Yes	do	do
	d) Auto starting of pump	Yes	do	
	The state of the s		intained by mall	



	Under ground tank capacity	5,00,000 ltrs.	Provided & maintained by mall	MR
	a) Draw-off connection	Yes	do	do
	b) Fire service inlet	Yes	do	do
	c) Access to tank	Yes	do	do
	d) Over head tank capacity	50,000 ltrs.	do	do
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	Yes	Provided	MR
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Yes	Provided	MR
	d) Fireman's switch	Yes	Provided	MR

- 4	e) Lift signage	Yes	Provided	MR
17.	Stand by Power Supply	Yes	Provided	MR
18.	Refuge Area	Yes	Provided	MR
	Total area location	2 nd floor	Provided	MR
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	Ground floor	Ground floor	MR
	b) Flow switch panel	Ground floor	Ground floor	MR
	c) PA system panel	Basement floor	Basement floor	MR
	d) Battery backup	Yes	Provided	MR
	e) Building floor plan	Yes	Provided	MR
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010/-----

Accordingly DFA is put up please.

Signature of the inspecting officer

Signature of the inspecting officer

Name:- Dharampal Bharadwaj

Designation: - Divisional Officer

Name: S.S.Kaushik. 26

Designation: - Assistant Divisional Officer.