GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE **NEW DLEHI-110 001**

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2013/

Dated: 17/05/2017

FIRE SAFETY CERTIFICATE

Certified that the Hotel Mid Town located at 17A/7, WEA, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus four upper floors, using basement as Storage, ground floor as reception, hall and shops, first, second & third floor each having seven guest rooms respectively (Total Twenty One guest rooms), A staff room with pantry for staff on forth floor was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/819 dated 18.03.2010 owned/occupied by Sh. Surinder Singh Bakshi. The guest house building was re inspected by the officers concerned of this department on 08.05.2013 in the presence of Sh. M. Purohit (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on at New Delhi.

(DR. G.C. MÍSRA) CHIEF FIRE OFFICER **DELHI FIRE SERVICE** Ph:- 011-23414333

Ma

Copy to:-

- The Addl. Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.17817/Addl. C.P./Lic.(H), Dated 16.04.2013)
- 2. Sh. Surinder Singh Bakshi (Owner), Hotel Mid Town, 17A/7, WEA, Karol Bagh, New Delhi-110005.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

NIS. Basement, Ground Floor plus Four cepper Floors.

	INSPECT	ION REPORT					
	 Name & address of the building: / Type of Occupancy 	Hotel Mid Tou	on, 17A/7, WE	A. Karol Bach, MD-05			
	 Type of Occupancy Type of Case 	: New Case/Renewal					
	4. Details of Previous NOC						
	5. Fire Safety directives letter No :	: Letter No. F.6/DFS/MS/G.H/2010/819 Date 18.03.2010					
	6. Date of inspection	API	A STATE OF THE PARTY OF THE PAR				
	7. Name of Inspecting Officer :	08.05.20/3					
	8. Name and designation of officers	O P.S. Dahiya					
	From the building side :	01 - 0	1.1.6				
	9. Year of Construction	Sh.M.F	usohit (Mana	ger)			
	10. Applicant's letter No.	Before 1701712001	C.0/1 10 (4)	(4.6. / 2.4. 4/ 4			
S.	Minimum Standards on fire	NBC/BBL	Provided at	ated 16.04.2013			
No.	prevention and fire safety U/R 33	Requirement	site	Remarks			
I.	Access to building	nequirement	site	MR/NMR			
	 Road width 	Accessible	09mtr	MR			
	 Gate width 	770000000	118 cm 8	MR			
	• Width of internal road		11001115	/ V / A			
2.	Number, Width, Type & Arrangement	of Evite					
	a. Number of staircases	OI EXILS		Management of the second secon			
	• Upper Floors	M .					
	* Basements	One	One	MR, Being a old Cop.			
	b. Width of staircases	Two	760	MRU			
	 Upper Floor 		1.00	and the same of th			
	 Basements 		127cm8	MR, Being old Os			
	c. Protection of exits	-	175cmp, 80cmp	MR			
	 Fire check door 						
	pressurization						
	d. No. of continuous staircases to						
	terrace	,					
	e. Width of Corridor	Section 1	Ohe				
	f. Door Size	**************************************	250cms, 130cms	game.			
		•	8. Scmp x204cms				
7.	Compartmentation						
	 Fire check door 						
	 Sealing of electrical shafts 		Sealed				
	 Fire Rating of shaft door 		Seurea				
	 Water Curtain 	The second secon		-			
	 Fire Dampers 						
4.	Smoke Management System	<u> </u>					
	• Basements	20 - /	Exhaust Fans				
	* Upper floors	30 a/c per hour	are Provided				
			Natural Ventila	hos MR			

Standby Pump Head

stopping

Auto Starting/Manual

-

-

-

N/7 17A/7, WEA, Kosol Bagh, New Delli-110005.

	Pump House Access	•		_		
	 Terrace level 					
	Discharge of pump	450 LPM	456 LPM	MR		
	Head of the pump		30 M Provioled	MR		
	Power Supply	30 M Required	Provided	MR		
	Auto Starting of pump					
4. (Captive Water Storage for fire fighting					
	 Underground tank capacity 	*		_		
	Draw-off connection		4-			
	Fire service inlet					
	Access to tank		-	_		
And the second s	 Overhead Tank capacity 		Socolta	MR, Beingaol		
15.	Exit Signage.	Required	Socoltr Provided	MR, Beligaoli MR		
16.	Provision of Lifts.					
	Pressurization of Lift Shaft		~	6		
	Pressurization of Lift lobby		-			
	Communication In lift Car		Provioled	MR		
40	• * Fireman's Grounding Switch	0				
And the second second	• Lift Signage	Keglired	- do -	MR		
	- Lift Signage	-do-	-do-	MR		
17.	Standby power supply	Required -do- Required	Provided	MR		
18.	> Total Area					
	> Location		/ .			
	1					
19.	Fire Control Room					
	Detector System Panel	•	been constitution of the c			
	Flow Switch Panel	Name of the last o				
and the passenger	PA System Panel					
	Batter backup	Required	Provided	mr		
MANAGEMENT TO THE	Building Floor Plans			·-		
	Special Fire Protection System for					
20.				L .		

The fire protection systems provided in the building were test checked and found functional at 🦤 the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention Fire Safety measures required under the rules it is recommended to grant Fire Safety

Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial IRES

numbers

Name H. L. Aneja

Designation Divisional Officer

Signature of Inspecting Officer

Name P.S. Dahiya
Designation AS\$H. Divisional Officer