GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001

Fax: 011-23412593 E-mail: <u>cfohq.dlfire@nic.in</u> Ph. 011-23414333.

No.F6/DFS/MS/EH/2013/3 > Dated: 17/12/13

FIRE SAFETY CERTIFICATE

Issued 17/55/13 --- at New Delhi by.

20

(Dr. G.C. Misra) Chief Fire Officer Delhi Fire Service

orch

- Copy to:- (1) The DEO (Restt.)
 Office of Commissioner of Ex. & Ent.,
 L& J Block, Vikas Bhawan, I.P. Estate, New Delhi.
- (2) Oh Calcutta Restaurant (Unit of Speciality Restaurant Ltd.), GF,26-38,International Trade Tower,Nehru Place,New Delhi. Following fire safety directives must be adhered to:-
 - 1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
 - 2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
 - 3. The trained fire fighting staff should be available round the clock.
 - 4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
 - 5. The basement shall be used as per the provisions of BBL.
 - 6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
 - 7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

- 1. Name & address of the building:- Oh Calcutta Restaurant (A Unit of Speciality Restaurant Ltd.), GF, 26-38, International Trade Tower, Nehru Place, New Delhi.
- 2. Type of occupancy:- Group D Assembly Building (Eating House)
- 3. Type of case:- Renewal
- 4. Details of previous NOC:-No.F6/MS/DFS/EH/2010/1476 dated 19/05/10.
- 5. Fire safety directives No.- No
- 6. Date of inspection: 01/05/13.
- 7. Name of the inspecting officer:- A.D.O. S.S. Kaushik
- 8. Name & designation of officer
 - From the building side:- Mr. Deepak Sharma
- 9. Year of construction:- Not known
- 10. Applicant's letter No:-Nil. dated 22/03/13 basement ,ground + 19 upper foors. The

Restaurant is running on ground floor only

				Old Case
S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement	Provided at site	Remarks MR/NMR
1.	Access to Building			1 12
	1) Road width	Existing in Tower	Provided	MR
	2) Gate width	5 mtr.	5 mtr.	MR
	3)Width of internal road	6 mtr.	6 mtr.	MR
2.	Number, Width Type & Arrange			
	A. Number of staircases		~	
-	1. Upper floors	Provided & maintained by management of International Trade Tower	Provided & maintained by management of International Trade Tower	MR
0	2. Basements	do	do	do
	B. Width of staircase	40	do	do
go, o comanda e	1. Upper floors	do	do	do
	2. Basements	do	do	do
	C. Protection of exits		40	
	1. Fire check door	do	do	do
	2. Pressurization	do	do	do
8	D. No. of continuous staircase to terrace	Required	Provided	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	Two door	2 Nos.	MR
3.	Compartmentation			
2	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
-	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 a/c per hour	N/A	N/A
	2) Upper floors	12 a/c per hour	Exhaust fan provided	MR
5.	Fire Extinguishers		· ·	



- Y	1) Total numbers		12 Nos.	MR
<i>y</i>	2) Types	ISI Marked	ABC, Co2 & W.Co2	MR
	3) ISI marking		Yes	MR
6.	First-Aid Hose Reel			
	1) Total number of each floor	Provided & maintained by management of International Trade Tower	2 Nos. near to restaurant	MR
	2) Length of hose reel hose	30 m	Yes	MR
. *	3) Nozzle diameter	5 mm	Yes	MR
7.	Automatic Fire Detection & Aları		103	IVIK
	1) Type of detectors	Provided & maintained by management of International Trade Tower	Provided & maintained by management of International Trade Tower	MR
	2) Location of main panel	do	do	do
	3) Location of repeater panel	do	do	do
	4) Alternate source of power	do	do	do
	5) Hooter's Location	do	do	do
9.	MOEFA Public Address System	Required	Provided	MR
10		Provided & maintained by management of International Trade Tower	Provided	MR
10.	Automatic Sprinkler System	0		
	1) Basement	do	do	do
	2) Upper floors	do	do	
	3) Sprinkler above false ceiling	do	do	do
11.	Internal Hydrants		40	4
	Size of riser/down-comer Number of hydrouts and face.	Provided & maintained by management of International Trade Tower	Provided & maintained by management of International Trade Tower	MR
*	2) Number of hydrants per floor	do	do	do
2.	3) Hose box	do	do	do
2.	Yard Hydrants			
	1) Total number of hydrants	management of	Provided & maintained by management	MR
		Trade Tower	of International Trade Tower	
	2) Hose box	Trade Tower	of International	do



1-	1	1 1		-	
	emperature acuta a since acutation and acutation and acutation and acutation acutation and acutation acuta	1) Ground level	Provided & maintained by management of International Trade Tower	management of	MR
			. *	International Trade Tower	
		a) Discharge of main pump	do	do	do
		b) Head of main pump	do	do	do
		c) Number of main pump	do	do	do
	e la company de	d) Jockey pump out put	do	do	do
		e) Jockey pump head	do	do	do
	in a distance of the second	f) Stand by pump output	do	do	do
1		g) Stand by pump head	do	do	do
		h) Auto starting/Manual stoppin	gdo	do	do
		2) Terrace level			
		a) Discharge of pump	do	do	do
		b) Head of pump	do	do	do
		c) Power supply	do	do	do
		d) Auto starting of pump	do	do	do
14.		Captive Water Storage for Fire Figh	ting :- Provided & m	aintained by mall	
		7 V V			
		 Under ground tank capacity 	Provided &	Provided &	MR
	-		maintained by	maintained by	
			management of	management	
			International	of	NS
	-		Trade Tower	International	
		a) Draw-off connection	do	Trade Tower	1
	Times 4,700 III	b) Fire service inlet	do	do	do
	Description of the last	c) Access to tank	do		do
-	- Charles	d) Over head tank capacity	do	do	do
15.		Exit Signage.	Required	Provided	do
16.		Provision of Lifts.	required	riovided	MR
		a) Pressurization of lift shaft	N/A	N/A	N/A
	and a second	b) Pressurization of lift lobby	N/A	N/A	N/A
	0	c) Communication in lift car	N/A	N/A	N/A
		d) Fireman's switch	N/A	N/A	N/A
		0) 1:0.			
17.		e) Lift signage	N/A	N/A	N/A
18.		Stand by Power Supply	Yes	Provided	MR
10.		Refuge Area Total area location		10	
19.		Fire Control Room	N/A	N/A	N/A
13.		The Control Room	Provided & maintained by management of International Trade Tower		
	A CONTRACTOR OF THE PARTY OF TH	a) Detector system panel	Yes	Provided	MR
		b) Flow switch panel	Yes	Provided	MR
		c) PA system panel	Yes	Provided	MR
		d) Battery backup	Yes	Provided	
			100	Tiovided	MR



20.	Special Fire Protection System for	Protection of special Risk, if any:	N/A
The fire pr	rotection system provided in the building	were checked and found functional at the	time of inspection.
required un	n view of the substantial compliance of the nder the rules it is recommended to grant lales 2010/Accordingly DFA is put up	Fire Safety Certificate under rules 35 of th	
Signature	of the inspecting officer	Signature of the inspecting officer	
Name:- Dh	narampal Bharadwaj	Name: S.S.Kaushik 13	
Designatio	n:- Divisional Officer	Designation: - Assistant l	

Yes

Provided

MR

Building floor plan