

**GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE
NEW DELHI-110001.**

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/EH/2013/356

Dated: 24/05/13

FIRE SAFETY CERTIFICATE

Certified that the **Cross Roads Bar & Restaurant (A unit of Atul Constructions Pvt. Ltd.)** located at 17A/1, WEA, Main Gurudwara Road, Karol Bagh, New Delhi-110005. The building is comprised of basement, ground floor plus four upper floors. The restaurant is running at Ground floor only of above said Hotel Arpit Palace's building. The restaurant having two exits was issued NOC by this department vide letter No.F.6/DFS/MS/EH/10/730 dated 10.03.2010 owned/occupied by Atul Constructions Pvt. Ltd. The Restaurant was re-inspected by the officers concerned of this department on 15.05.2013 in the presence of Sh. Bal Krishan Butani (Manager) and found that the Atul Constructions Pvt. Ltd. have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises (ground floor only) is fit for occupancy class Group D assembly building Sub- Division D-6 w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules, 2010 printed overleaf.

Issued on.....24/05/13.....at New Delhi.


(DR. G.C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE
Ph:- 011-23414333

Copy to:-

- 1 The Director,
Cross Road Bar Restaurant,
17A/1, WEA, Main Gurudwara Road,
Karol Bagh, New Delhi-110005.
2. The Dy.Health Officer,
North Delhi Municipal Corporation,
Karol Bagh Zone, New Delhi-110005.
(Ref. No. DHO/KBZ/2013/1161 dated 06.05.2013)

ok
Guj

The restaurant is established at Ground floor of a five storeyed building (Hotel Arpit Palace) having separate exits.

N/S

INSPECTION REPORT

1. Name & address of the building : Cross Road Bar Restaurant, 17A/1, WEA, Main Gurudwara Rd, Karol Bagh, N.D.-05.
2. Type of Occupancy : Assembly Building
3. Type of Case : New Case/ Renewal
4. Details of Previous NOC : Letter No. F.6/AES/MS/EH/10/730 Date 10.03.2010
5. Fire Safety directives letter No : N/A
6. Date of inspection : 15.05.2013
7. Name of Inspecting Officer : D.O H.L. Aneja & A.D.O P.S. Dahiya
8. Name and designation of officers : Sh. Bal Krishan Butani (Manager)
From the building side
9. Year of Construction : Before 2005
10. Applicant's letter No. : NIL dated 07.05.2013

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC/BBL Requirement	Provided at site	Remarks
1.	Access to building			MR/NMR
	• Road width	<u>Accessible</u>	<u>09 mtr</u>	<u>MR</u>
	• Gate width	<u>-</u>	<u>240 cms</u>	<u>MR</u>
	• Width of internal road	<u>-</u>	<u>-</u>	<u>-</u>
2.	Number, Width, Type & Arrangement of Exits			
	a. Number of staircases			
	• Upper Floors	<u>-</u>	<u>-</u>	<u>Rest. running at G.F only</u>
	• Basements	<u>-</u>	<u>-</u>	<u>- do -</u>
	b. Width of staircases			
	• Upper Floor	<u>-</u>	<u>-</u>	<u>Rest. running at G.F only</u>
	• Basements	<u>-</u>	<u>-</u>	<u>- do -</u>
	c. Protection of exits			
	• Fire check door	<u>-</u>	<u>-</u>	<u>-</u>
	• pressurization	<u>-</u>	<u>-</u>	<u>-</u>
	d. No. of continuous staircases to terrace	<u>-</u>	<u>-</u>	<u>-</u>
	e. Width of Corridor	<u>-</u>	<u>-</u>	<u>-</u>
	f. Door Size	<u>-</u>	<u>-</u>	<u>Ground Floor only</u>
		<u>-</u>	<u>100cms x 230cms</u>	<u>-</u>
3.	Compartmentation			
	• Fire check door	<u>-</u>	<u>-</u>	<u>-</u>
	• Sealing of electrical shafts	<u>-</u>	<u>-</u>	<u>-</u>
	• Fire Rating of shaft door	<u>-</u>	<u>-</u>	<u>-</u>
	• Water Curtain	<u>-</u>	<u>-</u>	<u>-</u>
	• Fire Dampers	<u>-</u>	<u>-</u>	<u>-</u>
4.	Smoke Management System			
	• Basements	<u>30 a/c per hour</u>	<u>Exhaust Fans are provided</u>	<u>MR</u>
	• Upper floors	<u>-</u>	<u>Natural Ventilation</u>	<u>MR</u>

M/6-

12 a/c per hour

5.	Fire Extinguishers			
	• Total numbers	10 Nos	Provided	MR
	• Types	CO ₂ , WCO ₂ , ABC	- do -	MR
	• IS marking	ISI marked	ISI Marked	MR
6.	First-Aid Hose Reels			
	• Total numbers on each floor	Two	Provided	MR
	• Length of hose reel hose	30 m	- do -	MR
	• Nozzle diameter	5 mm	- do -	MR
7.	Automatic fire detection and alarming system			
	• Type of detectors	-	-	-
	• Location of Main Panel	-	-	-
	• Location of Repeater Panel	-	-	-
	• Alternate source of power	-	-	-
	• Hooters' Location	-	-	-
8.	MOEFA	Required	Provided	MR
9.	Public Address System	- do -	- do -	MR
10.	Automatic Sprinkler System			
	• Basement	Required	Provided	MR
	• Upper Floor (Rest. Area)	- do -	- do -	MR
	• Sprinkler above false ceiling	-	-	-
11.	Internal Hydrants			
	• Size of riser/down-comer	100mm	100mm	MR
	• Number of hydrants per floor	One	One	MR
	• Hose Box	- do -	- do -	MR
12.	Yard Hydrants			
	• Total number of hydrants	-	-	-
	• Hose Box	-	-	-
13.	Pumping Arrangements			
	• Ground Level			
	➤ Discharge of main Pump	-	-	-
	➤ Head of Main pump	-	-	-
	➤ Number of main pumps	-	-	-
	➤ Jockey Pump out put	-	-	-
	➤ Jockey pump head	-	-	-
	➤ Standby Pump out put	-	-	-
	➤ Standby Pump Head	-	-	-
	➤ Auto Starting/Manual stopping	-	-	-

17A/1, WEA, Main Gurudwara Road,
Kasol Bagh, New Delhi - 110005.

N/7

	<ul style="list-style-type: none"> ➤ Pump House Access • Terrace level ➤ Discharge of pump ➤ Head of the pump ➤ Power Supply ➤ Auto Starting of pump 	-	-	-
		450 LPM	450 LPM	MR (old case)
		-	24 M	- do -
		Required	Provided	MR
		-	-	-
14.	Captive Water Storage for fire fighting			
	<ul style="list-style-type: none"> • Underground tank capacity ➤ Draw-off connection ➤ Fire service inlet ➤ Access to tank • Overhead Tank capacity 	-	-	-
		-	-	-
		-	-	-
		-	-	-
		-	5000 Ltr	MR (old case)
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	<ul style="list-style-type: none"> • Pressurization of Lift Shaft • Pressurization of Lift lobby • Communication In lift Car • Fireman's Grounding Switch • Lift Signage 	-	-	Rest running at Ground floor only
		-	-	-
		-	-	-
		-	-	-
		-	-	-
17.	Standby power supply	Required	Provided	MR
18.	Refuge Area.			
	<ul style="list-style-type: none"> ➤ Total Area ➤ Location 	-	-	-
		-	-	-
19.	Fire Control Room			
	<ul style="list-style-type: none"> • Detector System Panel • Flow Switch Panel • PA System Panel • Batter backup • Building Floor Plans 	-	-	-
		-	-	-
		-	-	-
		Required	Provided	MR
		-	-	-
20.	Special Fire Protection System for Protection of special Risks, if any:	-	-	-

N/8.

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to ^{Renewal} grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ ~~issue shortcomings as noted at serial numbers.....~~

Note:- The Restaurant is established at Ground floor of a five storeyed building (Hotel Arpit Palace) having separate exits. The restaurant is not linked with the Arpit Palace. The restaurant having seating capacity 90 persons with two exits i.e. One from front side and the second on the rear side.


Signature of Inspecting Officer

Name H. L. Anuja

Designation Divisional Officer


Signature of Inspecting Officer

Name P. S. Dahiya

Designation Asstt. Divisional Officer.