#### GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No: F.6/DFS/MS/School/2013/ 379

1

Dated: 24/5/13

### **FIRE SAFETY CERTIFICATE**

Certified that the building of **M. C. Primary Boys School,** Mitraon, New Delhi - 110043 comprised of ground floor plus one upper floor, having total 12 rooms (Including Class Rooms, Office & Store etc.) owned/occupied by MCD was inspected by the officer concerned of this department on 08.05.2013 in the presence of Sh. Jagdish Prasad Yadav (Principal) and found that the M.C.D have complied with the fire prevention and fire safety requirements in accordance with the Circular No- F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on ...24 /5/17 ......at New Delhi

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

olc

#### Copy to: -

- The Principal,
   M. C. Primary Boys School,
   Mitraon, New Delhi-110043.
- Director of Education, South Delhi Municipal Corporation 23<sup>rd</sup> floor, Dr. S.P.M Civic Centre, Minto Road, New Delhi-110002.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

# Ground Floor plus one upper floor.

	Upper floors		Matural Ventilation	Mo Basement	
	<ul> <li>Basements</li> </ul>	30 a/c per hour			
	Smoke Management System				
1.	Smoke Management S	_	Rem.	4.00	
	<ul> <li>Fire Dampers</li> </ul>		_	_	
	<ul> <li>Water Curtain</li> </ul>	-	_		
	<ul> <li>Fire Rating of shaft door</li> </ul>	-		-	
	<ul> <li>Sealing of electrical shafts</li> </ul>			-	
	Fire check door				
3.	Compartmentation		110 cms x 200 cms	-	
	terrace e Width of Corridor f Door Size				
			210 cms		
		,			
	<ol> <li>No. of continuous staircases to</li> </ol>				
		0-			
	* pressurization	-	V-maries.		
	<ul><li>Protection of exits</li><li>Fire check door</li></ul>		y' .		
	Basements  Protection of a difference in the second control of the second control o	•		No Basement	
	<ul> <li>Upper Floor</li> </ul>		136cms, 133cm	MR	
	b. Width of staircases			,	
			•	No Basemen	
	• Basements	760	Two	MR	
	• Upper Floors	17.			
	a. Number of staircases	EXIIS			
2.	Number, Width, Type & Arrangement of	Evite		-	
	<ul> <li>Width of internal road</li> </ul>	-	300 cm3	MR	
	<ul><li>Road width</li><li>Gate width</li></ul>	Accessible	09mtr	MR	
1	Access to building	2000-121-			
10.	and fire safety U/R 33	Circular dt. 01.03.2011		MR/NMR	
5	Minimum Standards on fire prevention	Dir. Of Edu.	Provided at site	Remarks	
	10. Applicant's letter No.	Nic dated Nic			
	9. Year of Construction	Sh. Jagdish Parpad Yadar (Princi) 2007-08			
	From the building side	ers CL Tag	dul Paradi	an do 10.	
	<ul><li>7. Name of Inspecting Officer</li><li>8. Name and designation of office</li></ul>	: A.D.O	P.S. Dahiya		
	<ol> <li>Date of inspection</li> <li>Name of Inspecting Officer</li> </ol>	. 08	.05.2013		
	5. Fire Safety directives letter No		NIA		
	4. Details of Previous NOC	: Letter No		Dated	
	3. Type of Case	: New Case/Re	enewal		
	- Type of ecopulicy.	Educationa	1 CSChool	117 8 (10h) 1(10h)	
	<ol> <li>Name &amp; address of the building</li> </ol>	TION REPORT : M. C. Primar	y Boys School, N	Titraon, NA.A.	

## N/9. Mitraion, Mew Delli-43.

	Pump House Access					
	Terrace level	-	Para	-		
	Discharge of pump					
	Head of the pump		_	_		
	Power Supply	-	-	- 1		
	> Auto Starting of pump			-		
	7 Auto Starting of pump			~		
14.	Captive Water Storage for fire fighting					
	• Underground tank capacity					
	Draw-off connection			-		
	<ul><li>Fire service inlet</li><li>Access to tank</li></ul>	-		-		
	<ul> <li>Overhead Tank capacity</li> </ul>	***************************************				
15.	Exit Signage.	_	Provided	-		
16.	Provision of Lifts.		-			
	Pressurization of Lift Shaft					
	<ul> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> </ul>	*	/	Nociff		
		-	None.	-do-		
		•	•	-do-		
		•		-do-		
	<ul> <li>Lift Signage</li> </ul>			-do -		
17.	Standby power supply	-	•	- ,		
18.	Potus Aug					
J.O.	Refuge Area.  > Total Area	T				
	20° - 20° -	•	<b>~</b>	Draw.		
	Location	Electric		_		
			1 7 7 -			
10	Fire Control Poom					
19.	Fire Control Room					
19.	Detector System Panel	Lym.		<i>F</i>		
19.	<ul><li>Detector System Panel</li><li>Flow Switch Panel</li></ul>		~	~		
19.	<ul><li>Detector System Panel</li><li>Flow Switch Panel</li><li>PA System Panel</li></ul>			-		
19.	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> </ul>					
19.	<ul><li>Detector System Panel</li><li>Flow Switch Panel</li><li>PA System Panel</li></ul>					
	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> <li>Building Floor Plans</li> </ul>					
20.	<ul> <li>Detector System Panel</li> <li>Flow Switch Panel</li> <li>PA System Panel</li> <li>Batter backup</li> </ul>					

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Mote: The school building is comprised of Ground Floor plus one cepper floor. The lepper floor is served by two staircases having width 136 cmp, 133 cmp respectively. The building is directly approchable to the fire Vechiles. All Class Rooms facilated with Double doors. There are total 12 Rooms including class Rooms, Office, Store etc. The MCD rectify the Cill shortcomings which is recised viole letter No. F.6 | DFS | MS | 2012 | 4523 dated 07.12.2012.

Name P.S. Dahiya
Designation ASSH. Divisional Officer

Signature of Inspecting Officer

Name

Designation