## GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No: F.6/DFS/MS/School/2013/ 777

Dated: 24/5/13

## FIRE SAFETY CERTIFICATE

Certified that the building of **M. C. Primary School,** Nawada Main (1<sup>st</sup> & 2<sup>nd</sup> Shift), New Delhi -110059 comprised of ground floor plus one upper floor, having total 19 rooms (Including Class Rooms, Office, Sci. Room & Store etc.) owned/occupied by MCD was inspected by the officer concerned of this department on 08.05.2013 in the presence of Sh. J.K. Bansal (Principal) and found that the M.C.D have complied with the fire prevention and fire safety requirements in accordance with the Circular No-F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.11 issued by the Director of Education and that the school building is fit for occupancy class "Educational" with effect from the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on 24 15 113 at New Delhi

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

of c

Copy to: -

- The Principal,
   M. C. Primary School,
   Nawada Main (1<sup>st</sup> & 2<sup>nd</sup> Shift), N.D-59.
- Director of Education, South Delhi Municipal Corporation 23<sup>rd</sup> floor, Dr. S.P.M Civic Centre, Minto Road, New Delhi-110002.

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on <a href="https://www.dfs.delhigovt.nic.in">www.dfs.delhigovt.nic.in</a>

## Goodend Floor plus one cepper Floor.

	INSPECT  Name & address of the building:	TON REPORT	Calcul Alatrada	Mad Ten		
	1. The second of					
	3. Type of Case :	: Educational (School) 14.5-59, : New Case/Renewal				
	4. Delails of Previous NOC :			Darkani		
	5. Fire Safety directives letter No :	Letter No	The state of the s	Dated*		
	<ul><li>b. The sorety directives letter No.</li><li>b. Date of inspection : : : : : : : : : : : : : : : : : : :</li></ul>	N/A 08.05.20/3				
	7. Mame of Inspecting Officer: A.S.O. P.S. Sahiya. 8. Mame and designation of officers					
	From the building side :	K. Bansal (P. 95-96	200100			
	* Sear of Construction :	Jn. J.	major s			
		17	75-76	the state of the s		
	10. Applicant's letter No.		d 15.03.2013			
١.,	Minimum Standards on fire prevention and fire safety U/R 33	Dir. 0f Edu. Circular dt.	Provided at site	Remarks MR/NMR		
	Access to building	01.03.2011				
	Road width	Accessible	00.	mo		
	Gate width	MUCCOSIDIE	09mtr	MR		
	<ul> <li>Width of internal road</li> </ul>	*	330 cm8	MR		
		F :4				
	Number, Width, Type & Arrangement of a Number of staircases	EXITS				
	Upper Floors					
	Basements	100	7600	MR		
	• sosements			No Basement		
	5 Width of staircases		15000 11000	h		
	<ul> <li>Upper Floor</li> </ul>		150cms, 140cms			
	* Basements	+		No Basement		
	Protection of exits					
	<ul> <li>Fire check door</li> </ul>		-	<u> </u>		
	<ul> <li>pressurization</li> </ul>					
	A. No. of continuous staircases to					
	terrace					
	e. Width of Corridor	-	100			
	f Door Size	-	155 cms, 135 cms	-		
		•	112 cm \$ x 210 cms	-		
	Compartmentation					
	<ul> <li>Fire check door</li> </ul>	-	-	-		
	<ul> <li>Sealing of electrical shafts</li> </ul>	4				
	<ul> <li>Fire Rating of shaft door</li> </ul>					
	<ul> <li>Water Curtain</li> </ul>					
	<ul> <li>Fire Dampers</li> </ul>					
	Smoke Management System			- 1 8 ·		
	<ul> <li>Basements</li> </ul>	30 a/c per hour				
	<ul> <li>Upper floors</li> </ul>	30 a/c per nour		No Basement		
			Matural Ventile	Happy MR		

## N/7 Nawada Moein - I & II, New Delli - 110059.

	Pump House Access			7			
	Terrace level	•	<u> </u>	•			
	Discharge of pump						
	<ul><li>Head of the pump</li><li>Power Supply</li></ul>		-	<b>1</b>			
			•	-			
	Auto Starting of pump			-			
				_			
14.	Captive Water Storage for fire fighting			4.1			
	<ul> <li>Underground tank capacity</li> <li>Draw-off connection</li> <li>Fire service inlet</li> <li>Access to tank</li> <li>Overhead Tank capacity</li> </ul>		-				
		•					
		•					
			0 11	10			
15.	Exit Signage.		Provided	-			
4.6							
16.	Provision of Lifts.						
	<ul> <li>Pressurization of Lift Shaft</li> <li>Pressurization of Lift lobby</li> <li>Communication In lift Car</li> <li>Fireman's Grounding Switch</li> <li>Lift Signage</li> </ul>		,	No Crft			
			-	-do-			
				-do-			
		Approximate 2		-do-			
				-do-			
				- 00			
17.	Standby power supply			_			
18.	Refuge Area.						
	<ul><li>Total Area</li><li>Location</li></ul>						
		-		-			
19.	Fire Control Room						
	Detector System Panel						
	<ul><li>Flow Switch Panel</li><li>PA System Panel</li></ul>	-	-	-			
		-		V=-			
		•	-	_			
	Ratter backup						
	Batter backup     Building Floor Plans	_	_				
	<ul><li>Batter backup</li><li>Building Floor Plans</li></ul>						
	Building Floor Plans	_					
20.							

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial pumbers

Note: The school building is comprised of Ground Floor plus one upper floor.

The cepper floor is served by two sterircases having width 140cms

& 150 cms respectively. The building is approchable to the fire vechiles.

There are fotal 19 Rooms (Including class Rooms Office, Sci. Rooms Storeeta).

Double Doors are provided. The Med D rectified all the short comings which is raised vide (efter No. F.6/DFS) ms/2012/4521 dated 07.12.2012.

Name P.S. Dahiya Designation ABSH. Divisional Officer.

Signature of Inspecting Officer

Name

Designation

