GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DLEHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/School/2013/ 3 95

Dated: 30/05/13

FIRE SAFETY CERTIFICATE

Certified that the **Shiksha Gyan Vidyalaya** located at A-7, Nishant Park, Kakrola More, New Delhi-110078 comprised of ground floor only, having total 07 rooms (Including Class Rooms & Office etc.) was issued NOC by this department vide letter No.F.6/MS/DFS/2006/2384 dated 08.09.2006. The School building was re inspected by the officer concerned of this department on 23.05.2013 in the presence of Sh. Virender Ghalot (Manager) and found that the school management have deemed complied with the fire prevention and fire safety requirements in accordance with the Circular No. F.16/Estate/CC/Fire Safety/2011/3298 to 3398 dated 01.03.2011 issued by the Director of Education and that the building/ premises is fit for occupancy class "Educational" w.e.f. the date of issue of this certificate for a period of three years, subject to compliance of the conditions printed overleaf.

Issued on 30/55/13 at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

OL

Copy to:-

- 1. The Manager, Shiksha Gyan Vidyalaya, A-7, Nishant Park, Kakrola More, N. D-78.
- Director of Education, South Delhi Municipal Corporation 23rd floor, Dr. S.P.M Civic Centre, Minto Road, New Delhi-110002

Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 6. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

INSPECT	TON REPORT				
1. Name & address of the building:	Shiksha Gyan	Vidyalaya, A-	7, Nishant Park,		
z. Type of Occupancy ;	Educational (School) Kakrola More, N.D.				
3. Type of Case :	: New Case/Renewal				
4. Details of Previous NOC :	: Letter No. <u>F.6/ms/SFS/2006/2384</u> Dated <u>68.09</u> .				
5. Fire Safety directives letter No :	:NIA				
6. Date of inspection :	23.05.2013				
7. Name of Inspecting Officer :	: A.D.O P.S. Dahiya				
Name and designation of officer					
From the building side :	Sh. Virender Ghalot				
9. Year of Construction :	Before 2006				
10. Applicant's letter No. :	: SGV/01/2012-2013 dated 20.03.2013				
Minimum Standards on fire prevention	Dir. Of Edu.	Provided at site	Remarks		
and fire safety U/R 33	Circular dt.	1 to raca at one	MR/NMR		
	01.03.2011		11.44.71.11.44.		
Access to building .	0.110012011				
 Road width 	Accessible	Obmtr	MR		
Gate width	1766693101-				
 Width of internal road 	•	220 cmp	MR		
Number, Width, Type & Arrangement of 1	Evite		-		
a. Number of staircases	LANS		<u> </u>		
 Upper Floors 			4		
	•	<u></u>	Ground Floor		
 Basements 			Ground Floor C No Bosement		
h. Width of staircases					
Upper Floor			Capital Class		
* Basements			Goound Floore No Basemen		
Protection of exits			No Basemen		
		2			
Fire check door		_			
 pressurization 		_ `.	_		
d. No. of continuous staircases to					
			The state of the s		
terrace e. Width of Corridor					
e. Width of Corridor f Door Size	Paurin		Ground Floor		
0001 Size	_	90 cm 8 x 19 5 cms	Ground Floor Gold Case		
Compartmentation		70 11 p p 1 7 3 cmp	(VICE COPE		
Fire check door					
 Fire check abor Sealing of electrical shafts Fire Rating of shaft door 	-	*			
Water Curtain	·	_	-		
 Fire Dampers 		_			
C., . l M		_	Name:		
Smoke Management System					
Basement System Basements	30 a/c per hour		F.(2)		
	30 a/c per hour		No Basement		
	30 a/c per hour		No Basement		
 Basements 	30 a/c per hour	-	No Basement Ground Flooron		

12 a/c per hour Fire Extinguishers Total numbers 03 NOS Provided MR Co, ABC -da-MR IS marking ISI marked 151 Marked MR First-Aid Hose Reels Total numbers on each floor Length of hose reel hose 30 m Nozzle diameter 5 mm Automatic fire detection and alarming system Type of detectors Location of Main Panel Location of Repeater Panel Alternate source of power D.G. Set of 62.5 KVA Hooters' Location Mear office MOEFA Public Address System Provided Automatic Sprinkler System Basement NO Basement Upper Floor Sprinkler above false ceiling Internal Hydrants Size of riser/down-comer Number of hydrants per floor Hose Box Yard Hydrants Total number of hydrants Hose Box Pumping Arrangements Ground Level Discharge of main Pump Head of Main pump Number of main pumps Jockey Pump out put Jockey pump head Standby Pump out put Standby Pump Head Auto Starting/Manual stopping

N/5 A-7, Mishant Park, Kakrola More, New Delli - 110078.

	Pump House Access					
	 Terrace level 					
	Discharge of pump			_		
	Head of the pump	_	~	~		
	Power Supply	-	~	•		
	Auto Starting of pump	-	x	•		
14.	Captive Water Storage for fire fighting					
	 Underground tank capacity 	1	~			
	Draw-off connection		_			
	Fire service inlet	_				
	Access to tank) Description of the control of the	Final Control of the			
	 Overhead Tank capacity 					
BITATION OF THE PARTY OF THE PA			0 .4 1			
15.	Exit Signage.	•	Poorided	~		
16.	Provision of Lifts.					
	 Pressurization of Lift Shaft 	•		No Ciff		
	 Pressurization of Lift lobby 			-do -		
	 Communication In lift Car 			-do-		
	Fireman's Grounding Switch					
	 Lift Signage 			-do-		
		-	-	-do-		
17.	Standby power supply	-	Provided	-		
18.	Refuge Area.					
	Total Area					
	> Location					
			•	_		
19.	Fire Control Room					
	 Detector System Panel 	_	_	_		
	Flow Switch Panel	-	_	-		
	 PA System Panel 			-		
	 Batter backup 					
	 Building Floor Plans 			-		
20.	Special Fire Protection System for Protection of special Risks, if any:	-	_	-		

The fire protection systems provided in the building were test checked and found functional at $\mathring{\mathbb{T}}$ the time of inspection.

Keeping in view the above substantial compliance of the minimum standards on fire prevention and Fire Safety measures required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Note: - The school building is comprised of Ground Floor only.

Signature of Inspecting

Name P.S. Dahiya
Designation AppH. Divisional Officer

Signature of Inspecting Officer

Name

Designation