GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEAD QUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110001

Fax: 23412593, E-mail: cfohq.dlfire@nic.in, Tel:- 011-23414333

No. F.6/DFS/MS/2013/9H/4/3

Dated: 03/06/13

Certified that Maratha Mitra Mandal located at D-4, Faiz road, Karolbagh, New Delhi comprised of basement floor, ground floor & first floor have complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules 2010 and verified by the officer concerned of Delhi Fire Service on 29-04-2013 in presence of Shri Prabhakar Gwande, General Administrator of the building and that the building/premises is fit for occupancy class Assembly(Gymnasium Hall) with effect from _______ for a period of 3(three) years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules,2010.

(Dr. G.C. Misra) CHIEF FIRE OFFICER DELHI FIRE SERVICE

Copy to :-

- 1. The General Administrator, Maratha Mitra mandal, D-4, Faiz road, Karol bagh, New Delhi.
- 2. The Executive Engineer(Bldg.), NDMC, Sadar Pahargani Zone, Delhi

Conditions for the validity of fire safety certificate

- a. All the fire safety and means of escape facilities shall be maintained in good working conditions at all time. Any lapse rendering fire safety or means of evacuation facilities rendering non-functional shall be the responsibility of the management.
- b. Building Sanctioning authority may verify any deviation with regard to the construction / occupancy in the building. In case of any deviation, the fire safety certificate stands null and void.
- c. The staffs shall be trained for operating fire fighting system and mock evacuation drills be conducted at regular intervals and record be maintained.
- d. The owner/occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on website www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building: Maratha Mitra Mandal, D-4, Faiz Road, Karol Bagh, New Delhi

2. Type of Occupancy

: Assembly

3. Type of Case

: New case

4. Details of previous NOC

: N/A

5. Fire Safety directives letter No : NBC-IV

6. Date of inspection

: 29.04.2013

7. Name of the Inspecting Officers: M.K.Chattopadhyay, ADO(CC)

8. Name and designation of officers

from the building side

: Mr. Prabhakar Gawande, General Administrator

9. Year of Construction

: 2012

10. Applicant's letter No.

: nil dated 25/01/2013

S. No.	Minimum Standards on fire prevention and fire safety U/R 33	NBC Requirement	Provided at site	Remarks MR/NMR		
1	Access to building					
	Road width	06 mts	12 mts	MR		
	Gate width	4.5 mts	05 mts	MR		
12	Width of internal road	N/A	N/A	N/A		
2	Number, Width, Type & Arrangement of Exits					
	a. Number of staircases			-		
	• Upper Floors	02	02	MR		
	• Basements	02	02	MR		
	b. Width of staircases	-	_	-		
	 Upper Floors 	2.0 mts, 1.20 mts	2.0, 1.20 mts	MR		
	• Basements	2.0 mts, 1.20 mts	2.0, 1.20 mts	MR		
	c. Protection of exits	-	-	- *		
	 Fire check door 	Required	Provided	MR		
	 Pressurization 	N/A	N/A	N/A		
	e. No. of continuous staircases to terrace	02	02	MR		
	g. Width of Corridor	N/A	N/A	N/A		
	h. Door Size	N/A	N/A	N/A		
3	Compartmentation.					
	• Fire check door	N/A	N/A	N/A		
	Sealing of electrical shafts	N/A	N/A	N/A		

	71			1	
	• Fire Rating of shaft door	N/A	N/A	N/A	
	Water Curtain	N/A	N/A	N/A	
1	Fire Dampers	N/A	N/A	N/A	
4	Smoke Management System.			1771	
286	BasementsUpper floors	30 a/c per hour 12 a/c per hour	Exhaust fan provided	MR	
5	Fire Extinguishers		Exhaust fan provided	MR	
	Total numbersTypes	9	Provided	MR	
		ABC, WCO ₂ , CO ₂	Provided	MR	
6	IS marking First-Aid Hose Reels.	ISI marked	Provided	MR	
	• Total numbers on each floor	01	Provided	MR	
	• Length of hose reel hose	30 m	Provided	MR	
7	Nozzle diameter	5 mm	Provided	MR	
7	Automatic fire detection and alarming system.				
	 Type of detectors 	N/A	N/A	N/A	
	• Location of Main Panel	N/A	N/A	N/A	
	 Location of Repeater Panel Alternate source of 	N/A	N/A	N/A	
	Alternate source of powerHooters' Location	N/A	N/A	N/A	
		N/A	N/A	N/A	
	MOEFA	Required	Provided	MR	
	ublic Address System.	N/A	N/A	N/A	
A	Automatic Sprinkler System.				
	BasementUpper Floor	Required	Provided	MR	
	 Sprinkler above false ceiling 	N/A	N/A	N/A	
In		N/A	N/A	N/A	
111	ternal Hydrants				
	Size of riser/down-comerNumber of hydrants per floor	100 mm	Provided	MR	
	Hose Box	01	Provided	MR	
-		01	Provided	MR	



	 Total number of hydrants 	N/A	N/A	N/A
	Hose Box	N/A	N/A	N/A
13	Pumping Arrangements.			
	Ground Level	N/A	N/A	N/A
	Discharge of main Pump	N/A	N/A	N/A
	Head of Main pump	N/A	N/A	N/A
	Number of main pumps	N/A	N/A	N/A
	Jockey Pump out put	N/A	N/A	N/A
	Jockey pump head	N/A	N/A	N/A
	Standby Pump out put	N/A	N/A	N/A
	Standby Pump Head	N/A	N/A	N/A
	Auto Starting/ Manual	N/A	N/A	N/A
	stopping	N/A	N/A	N/A
	Pump House Access	N/A	N/A	N/A
	Terrace levelDischarge of pump	900 LPM	Provided	
	Head of the pump	40 mts		MR
	Power Supply		Provided	MR
	Auto Starting of pump	Required Required	Provided	MR
14	Captive Water Storage for fire fighting		Provided	MR
	Underground tank capacity	N/A	N/A	N/A
	Draw-off connection	N/A	N/A	N/A
	Fire service inlet	N/A	N/A	N/A
	> Access to tank	N/A	N/A	N/A
	 Overhead Tank capacity 	15000 lts	Provided	MR
15	Exit Signage.	Required	Provided	MR
16	Provision of Lifts.		Tiovided	IVIIX
	Pressurization of Lift Shaft	N/A	N/A	N/A
	Pressurization of Lift lobby	N/A	N/A	N/A
	Communication In lift Car	N/A	N/A	N/A
	• Fireman's Grounding Switch	N/A		V
	• Lift Signage		N/A	N/A
		N/A	N/A	N/A



17	C4 II			
	Standby power supply	Required	Provided	MR
18	Refuge Area.			14114
	> Total Area	N/A	N/A	N/A
	> Location	N/A	N/A	N/A
19	Fire Control Room			1
	Detector System Panel	N/A	N/A	N/A
	Flow Switch Panel	N/A	N/A	N/A
	PA System Panel	N/A	N/A	N/A
	Batter backup	N/A	N/A	N/A
	Building Floor Plans	N/A	N/A	N/A
20	Special Fire Protection Systems for Protection of special Risks, if any:	Required	One CO ₂ type fire extinguisher found provided near elect. panel	MR

The fire protection systems provided in the building were test checked and found functional at the time of inspection.

Keeping in view the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rule 35 of the Delhi Fire Service Rules 2010.

Do (CD) Submitted pl.

Submitted pl.

Submitted pl.

23.513.

Signature of the Inspecting Officer
Name M.K.CHATTOPADHYAY
Designation: - Asstt. Div. Officer (CC)