

GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI
HEADQUARTERS, DELHI FIRE SERVICE, NEW DELHI-110001
Fax : 011-23412593 E-mail : cfohq.dfire@nic.in Ph. 011-23414333.

No.F6/DFS/MS/Hotel/2013/ 52/471

Dated : 24/06/13

FIRE SAFETY CERTIFICATE

Certified that **Hotel Vivanta by Taj Ambassador** located at **Subramaniam Bharti Marg, Sujan Singh Park, New Delhi-110003**..comprised of **Basement, Ground + 4 Upper Floors** was granted NOC by this department vide letter No.F6/DFS/MS/Hotel/2010/3319 dated **08/12/10** The premises was re-inspected by the officer concerned of this department on **20/05/13** in the presence of **Mr. Amit Singh (Security Manager)** and found that the said hotel have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the premises fit for occupancy class **Hotel Residential, Group A** with effect from ~~-----~~ 24/06/13 ----- for period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules,2010 subject to conditions printed below.

Issued ~~-----~~ 24/06/13 -----at New Delhi by.


(Dr.G.C.Misra)
Chief Fire Officer
Delhi Fire Service

Copy to:- (1) The Addl. Commissioner of Police, (Lic.),
First Floor, PS Defence Colony, New Delhi

(2) Hotel Vivanta by Taj Ambassador,
Subramaniam Bharti Marg, Sujan Singh Park, New Delhi-110003

Following fire safety directives must be adhered to:-

1. All the fire safety arrangements provided therein shall be maintained in good working conditions at all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t. construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of BBL.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner / occupier shall submit a declaration every year in form 'K' provided in the first schedule of Delhi Fire Service Rules 2010. The form is available on www.dfs.delhigovt.nic.in

INSPECTION REPORT

1. Name & address of the building:- Hotel Vivanta by Taj Ambassador Subramaniam Bharti Marg, Sujan Singh Park, New Delhi-110003.
2. Type of occupancy:- Residential, Group A
3. Type of case:- Renewal
4. Details of previous NOC:- F6/DFS/MS/Hotel/2010/1399 dated 08/12/10
5. Fire safety directives No.- N/A
6. Date of inspection:- 20/05/13
7. Name of the inspecting officer:-D.O. Dharampal & A.D.O. S.S. Kaushik
8. Name & designation of officer
From the building side:- Mr. Amit Singh (Security Manager)
9. Year of construction:- 1945.
10. Applicant's letter No:-18630/Addl. C.P. /Lic. (H) dated 22/04/13 Basement, ground + 4 upper Floors Old Case

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	12 basic fire safety standard/NBC Requirement	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	Required	Provided	MR
	2) Gate width	4.5 mtr.	Provided	MR
	3) Width of internal road	Required	Provided	MR
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors	4 Nos.	3 Nos. ground floor to terrace & 1 Nos. 1 st floor to terrace	MR
	2. Basements	2 Nos.	Provided	MR
	B. Width of staircase			
	1. Upper floors	Required	1.26 mtr., 1.20 mtr., 1.40 mtr. & 1.45 mtr.	MR old case
	2. Basements	Required	1.07 mtr. & 1.10 mtr.	MR old case
	C. Protection of exits			
	1. Fire check door	Yes	Provided	MR
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	3 Nos.	3 Nos.	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	1 mtr.	1 mtr.	MR
3.	Compartmentation			
	1) Fire check door	Yes	Provided	MR

Amit Singh

	2) Sealing of electrical shafts	Yes	Provided	MR
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 a/c per hour	Exhaust fan provided	MR
	2) Upper floors	12 a/c per hour	Exhaust fan provided	MR
5.	Fire Extinguishers			
	1) Total numbers	ISI Marked	130 Nos.	MR
	2) Types		ABC, Co2, W.Co2 & Foam.	MR
	3) ISI marking		Yes	MR
6.	First-Aid Hose Reel			
	1) Total number of each floor	4 Nos.	4 Nos.	MR
	2) Length of hose reel hose	30 m	Yes	MR
	3) Nozzle diameter	5 mm	Yes	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	Smoke & heat	Provided	MR
	2) Location of main panel	Yes	Engineering control	MR
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	Yes	Provided	MR
	5) Hooter's Location	Yes	At every floor	MR
8.	MOEFA	Yes	Provided	MR
9.	Public Address System	Yes	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	Yes	Provided	MR
	2) Upper floors	Yes	Yes in the guest area & restaurant	MR
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	Yes	100 mm.	MR
	2) Number of hydrants per floor	4 Nos.	4 Nos.	MR
	3) Hose box	4 Nos.	4 Nos.	MR
12.	Yard Hydrants			
	1) Total number of hydrants	Required	07 Nos. provided	MR
	2) Hose box	Required	07 Nos. provided	MR
13.	Pumping Arrangement			
	1) Ground level			
	a) Discharge of main pump	1620 LPM	1620 LPM	MR
	b) Head of main pump	45 mtr.	45 mtr.	MR
	c) Number of main pump	2 Nos.	2 Nos.	MR

Audrey

	d) Jockey pump out put	180 LPM	180 LPM	MR
	e) Jockey pump head	45 mtr.	45 mtr.	MR
	f) Stand by pump output	1620 LPM	1620 LPM	MR
	g) Stand by pump head	45 mtr.	45 mtr.	MR
	h) Auto starting/Manual stopping	Yes	Provided	MR
	2) Terrace level			
	a) Discharge of pump	N/A	N/A	N/A
	b) Head of pump	N/A	N/A	N/A
	c) Power supply	N/A	N/A	N/A
	d) Auto starting of pump	N/A	N/A	N/A
14.	Captive Water Storage for Fire Fighting			
	1) Under ground tank capacity	1,00,000 ltrs	1,00,000 ltr.	MR
	a) Draw-off connection	Yes	Provided	MR
	b) Fire service inlet	Yes	Provided	MR
	c) Access to tank	Yes	Provided	MR
	d) Over head tank capacity	10,000 ltrs.	10,000 Ltrs.	MR
15.	Exit Signage.	Yes	Provided	MR
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	Yes	Provided	MR
	d) Fireman's switch	Yes	Provided	MR
	e) Lift signage	Yes	Provided	MR
17.	Stand by Power Supply	Yes	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room			
	a) Detector system panel	Yes	Provided	MR
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	Yes	Provided	MR
	d) Battery backup	Yes	Provided	MR
	e) Building floor plan	Yes	Provided	MR
20.	Special Fire Protection System for Protection of special Risk, if any:			N/A


Mansel

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to grant Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010-----

Accordingly DFA is put up please

Signature of the inspecting officer



18/6/13

Name:- Dharampal Bharadwaj

Designation:- Divisional Officer

Signature of the inspecting officer



19/6/13

Name:-S.S. Kaushik.

Designation:- Assistant Divisional Officer.