


NO. FG1DPS/MS/82/2013/501

Dated: 11/7/13

FIRE SAFETY CERTIFICATE

Certified that the **Kylin Restaurant** located at **24, Basant Lok, Vasant Vihar, New Delhi** comprised of Ground + 2 Upper floors and the Restaurant is running on 1st & 2nd floor only, was granted NOC by this department vice letter No. F6/DFS/MS/EH/2010/1773 dated 16/06/10. The premises was re-inspected by the officer concerned of this department on 26/06/13 in the presence of Mr. Sohan, manager and found that the said premises have deemed complied with the fire prevention and fire safety requirements in accordance Assembly Building with effect from 11/7/13 for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule 38 of the Delhi Fire Service Rules 2010.

Issued 11/7/13 at New Delhi by


(DR. G. C. MISRA)
CHIEF FIRE OFFICER
DELHI FIRE SERVICE

Dr. G. C. Misra

Copy to:-

1. Mr. Saurabh Khanijo, Kylin Restaurant, 24, Basant Lok, Vasant Vihar, New Delhi
2. The D.E.O. (Restt.), Govt. of NCT of Delhi, Office of the Commissioner of Excise, Entt. & Tax department, L & N Block, I. P. Estate, Vikas Bhawan, New Delhi-2

1. All the fire safety arrangements provided there in shall be maintained in good working conditions t all times.
2. Any loss of life or property due to non functional fire safety measures shall be at the responsibility of the management.
3. The trained fire fighting staff should be available round the clock.
4. Any deviation w.r.t construction etc. shall be verified by the concerned building sanctioning authority.
5. The basement shall be used as per the provisions of BBL.
6. This fire safety certificate may not be treated in any case for regularization of unauthorized construction, if any.
7. The owner/ occupier shall submit a declaration every year in form "K" provided in the first schedule of Delhi Fire Service Rules 2010. The form is available of www.dfs.delhigovt.nic.in

Old case

INSPECTION REPORT

1. Name & address of the building:- Kylin Restaurent, 24, Basant Lok, Vasant Vihar, New Delhi
 2. Type of occupancy:- Group - D Assembly Building
 3. Type of case:- Renewal
 4. Details of previous NOC:-No. F6/MS/DFS/EH/2010/1773 dated 16/06/10
 5. Fire safety directives No.- N/A
 6. Date of inspection:-26 /06/13
 7. Name of the inspecting officer:-D.B.Mukherjee, ADO (BCP)
 8. Name & designation of officer From the building side:- Mr.Sohan
 9. Year of construction:- 2005 (Starting Year)
 10. Applicant's letter No:-Nil. dated 15/05/13
- Building comprised of Ground + 2 Upper Floors. Restaurant is running on 1st & 2nd floor only.

S.No.	Minimum Standards on fire Prevention and fire safety U/R 33	Requirement NBC/BBL	Provided at site	Remarks MR/NMR
1.	Access to Building			
	1) Road width	4.5 mts	Provided	MR
	2) Gate width	N/A	N/A	N/A
	3) Width of internal road	N/A	N/A	N/A
2.	Number, Width Type & Arrangement of Exits			
	A. Number of staircases			
	1. Upper floors	01	01	MR
	2. Basements	N/A	N/A	N/A
	B. Width of staircase			
	1. Upper floors	Required	1.30 mtr..	MR
	2. Basements	N/A	N/A	N/A
	C. Protection of exits			
	1. Fire check door	N/A	N/A	N/A
	2. Pressurization	N/A	N/A	N/A
	D. No. of continuous staircase to terrace	N/A	One	MR
	E. Width of corridor	N/A	N/A	N/A
	F. Door size	N/A	N/A	N/A
3.	Compartmentation			
	1) Fire check door	N/A	N/A	N/A
	2) Sealing of electrical shafts	N/A	N/A	N/A
	3) Fire rating of shaft door	N/A	N/A	N/A
	4) Water curtain	N/A	N/A	N/A
	5) Fire Dampers	N/A	N/A	N/A
4.	Smoke Management System			
	1) Basements	30 a/c per hour	N/A	N/A
	2) Upper floors	12 a/c per hour	Exhaust fan	MR
5.	Fire Extinguishers			
	1) Total numbers	ISI Marked	13	MR
	2) Types		ABC & CO ₂	MR
	3) ISI marking		Yes	MR
6.	First-Aid Hose Reel			
	1) Total number of each floor	One at each floor	provided	MR
	2) Length of hose reel hose	30 m	Yes	MR

	3) Nozzle diameter	5 mm	Yes	MR
7.	Automatic Fire Detection & Alarming System			
	1) Type of detectors	N/A	N/A	N/A
	2) Location of main panel	N/A	N/A	N/A
	3) Location of repeater panel	N/A	N/A	N/A
	4) Alternate source of power	N/A	N/A	N/A
	5) Hooter's Location	N/A	N/A	N/A
8.	MOEFA	Required	Provided	MR
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System			
	1) Basement	N/A	N/A	N/A
	2) Upper floors	YES	Provided	MR
	3) Sprinkler above false ceiling	N/A	N/A	N/A
11.	Internal Hydrants			
	1) Size of riser/down-comer	100 mm.	100 mm.	MR
	2) Number of hydrants per floor	One	provided	MR
	3) Hose box	Required	Provided	MR
12.	Yard Hydrants			
	1) Total number of hydrants	N/A	N/A	N/A
	2) Hose box	N/A	N/A	N/A
13.	Pumping Arrangement			
	1) Ground level	----	-----	-----
	a) Discharge of main pump	N/A	N/A	N/A
	b) Head of main pump	N/A	N/A	N/A
	c) Number of main pump	N/A	N/A	N/A
	d) Jockey pump out put	N/A	N/A	N/A
	e) Jockey pump head	N/A	N/A	N/A
	f) Stand by pump output	N/A	N/A	N/A
	g) Stand by pump head	N/A	N/A	N/A
	h) Auto starting/Manual stopping	N/A	N/A	N/A
	2) Terrace level	----	-----	-----
	a) Discharge of pump	450 & 225LPM	Provided	MR
	b) Head of pump	35 mtr.	Provided	MR
	c) Power supply	Yes	Provided	MR
	d) Auto starting of pump	Yes	Provided	MR
14.	Captive Water Storage for Fire Fighting			
	1) Under ground tank capacity	N/A	N/A	N/A
	a) Draw-off connection	N/A	N/A	N/A
	b) Fire service inlet	Yes	Provided	MR
	c) Access to tank	N/A	N/A	N/A
	d) Over head tank capacity	5,000 Ltrs.	provided	MR
15.	Exit Signage.	required	Provided ✓	MR ✓
16.	Provision of Lifts.			
	a) Pressurization of lift shaft	N/A	N/A	N/A
	b) Pressurization of lift lobby	N/A	N/A	N/A
	c) Communication in lift car	N/A	N/A	N/A
	d) Fireman's switch	N/A	N/A	N/A
	e) Lift signage	N/A	N/A	N/A

A

17.	Stand by Power Supply	Yes	Provided	MR
18.	Refuge Area	N/A	N/A	N/A
	Total area location	N/A	N/A	N/A
19.	Fire Control Room	N/A	N/A	N/A
	a) Detector system panel	N/A	N/A	N/A
	b) Flow switch panel	N/A	N/A	N/A
	c) PA system panel	N/A	N/A	N/A
	d) Battery backup	N/A	N/A	N/A
	e) Building floor plan	N/A	N/A	N/A
20.	Special Fire Protection System for Protection of special Risk, if any:	Required	One ABC type fire extinguisher provided near elect. panel	MR

The fire protection system provided in the building were checked and found functional at the time of inspection.

Keeping in view of the substantial compliance of the minimum standards on fire prevention and fire safety required under the rules it is recommended to renew Fire Safety Certificate under rules 35 of the Delhi Fire Service Rules 2010

Accordingly DFA is put up please.

Signature of the inspecting officer

Name:- D.B. Mukherjee.

Designation:- Assistant Divisional Officer (BCP).

