GOVERNMENT OF NATIONAL CAPITAL TERRITORY OF DELHI HEADQUARTERS: DELHI FIRE SERVICE: CONNAUGHT PLACE NEW DELHI-110 001.

E-mail:- cfohq.dlfire@nic.in

Fax:- 011-23412593

No. F.6/DFS/MS/GH/2013/ 53 0

Dated: 08/07/13

FIRE SAFETY CERTIFICATE

Certified that the Guest House **Sheesh Mahal** located at 2121, Bank Street, Karol Bagh, New Delhi-110005 comprised of Basement, ground floor plus four upper floors, using basement as Storage, ground floor as reception, shops, lobby and office, first floor having 07 guest rooms, second floor having 11 guest rooms, third floor having 10 guest rooms (Total 28 guest rooms), forth floor having 04 rooms for personnel use, A D.G set on terrace was issued NOC by this department vide letter No.F.6/DFS/MS/GH/2010/2255 dated 30.07.2010 owned/occupied by Sh. Satnam Singh. The guest house building was re-inspected by the officer concerned of this department on 15.06.2013 in the presence of Sh. Pillai (Manager) and found that the owner have deemed complied with the fire prevention and fire safety requirements in accordance with rule 33 of the Delhi Fire Service Rules, 2010 and that the building/ premises is fit for occupancy class residential w.e.f. the date of issue of this certificate for a period of three years in accordance with rule 36 unless renewed under rule 37 or sooner cancelled under Rule 40 and subject to compliance of the conditions under rule-38 of the Delhi Fire Service Rules. 2010 printed overleaf.

Issued on....at New Delhi.

(DR. G.C. MISRA) CHIEF FIRE OFFICER DELHI FIRE SERVICE Ph:- 011-23414333

Copy to:-

1. The Addl. Commissioner of Police (Lic.) 1st floor, P.S., Defence Colony, New Delhi. (Re. No.25778/Addl. C.P./Lic.(H), Dated 31.05.2013)

On

2. Sh. Satnam Singh (Owner), Guest House Sheesh Mahal, 2121, Bank Street, Karol Bagh, N. D-05. Following fire safety directives must be adhered to –

- 1. All the fire safety arrangements provided therein shall be maintained in good working condition at all times.
- 2. Any loss of life or property due to non-functional fire safety measures shall be at the risk & responsibility of the management.
- 3. The trained staff should be available round the clock.
- 4. Any deviation w.r.t. construction shall be verified by the concerned building sanctioning agency.
- 5. The basement shall be used strictly as per the provisions of the Building Bye Laws, 1983.
- 6. The certificate may not be treated in any case for regularization of unauthorized construction, if any.
- 7. The owner/occupier shall submit a declaration every year in form 'K' Provided in the first schedule of Delhi Fire Service Rules 2010, form is available on www.dfs.delhigovt.nic.in

Basement, Ground Floor plus Four Lepper Floors.

	Name & address (1)	INSPECT	ION REPORT				
	 Name & address of the Type of Occupancy 	e building : (n.H Sheesh M.	ahal 2121 Bank	Street Konal	1 Rout	
	3. Type of Case	/	Maruencia,	Suest House	N.D.	.05.	
	4. Details of Previous NO		New Case/Repe	wal			
	5. Fire Safety directions 1		Letter No. F.6/Dr	ES/MS/GH/2010/22	SS Date 20.03	. 2010	
	5. Fire Safety directives In6. Date of inspection	etter No :			30.07	2010	
	7. Name of Inspection	Officer A.D.O P.S. Dahiya					
	and of mapper and of						
	From the building side 9. Year of Construction	- Milliam (Monager)					
			Detore 2001				
5	10. Applicant's letter No.	: 6	25778 [Add1. C.P. Lic. CH) dated 31.05.2013				
No.	Minimum Standards on fire		NBC BBL	Provided at	Remarks	13	
1	prevention and fire safety L	J/R 33	Requirement	site	MR/NMR	4	
1.	Access to building	The second Constitution of the second of the		Site	INIK/INIK		
	 Road width 		Accessible	09mts	had	-	
	 Gate width 			105cms, 240cms	MR		
	 Width of internal roa 	ad		100 - 17 100 000	MR		
2.	Number, Width, Type & Arr	Ongomont a	-f C. U		~		
	a. Number of staircases	angement (JI EXITS				
	• Upper Floors						
	• Basements		One	One	MR COLA	1000)	
	b. Width of staircases		One	One	MR, Cola MR, Colo	JA A	
	• Upper Floor				177,010	(ase)	
		f.	4	117 to 125cms	the Pai	2110	
	Basements			136cm8	MR, Being a	Old Case	
	c. Protection of exits			13001118	- do =		
	 Fire check door 	The state of the s	4		The state of the s	_	
	* pressurization	The second state of the se			-		
	d. No. of continuous stairca	ses to			6.		
	terrace						
	e. Width of Corridor		Gine.		- Property and the second seco		
	f. Door Size			240 cms, 150 cms	_		
			•	88cms x 20Scms			
3.	Compartmentation			BOCH & XXXXX (M)			
	 Fire check door 				and the same of th		
	 Sealing of electrical s 	hafts	-	•	_		
	 Fire Rating of shaft d 	nai(2		Sealed			
	Water Curtain	oor					
	The state of the s		Company of the Compan				
4	 Fire Dampers 				-		
4.	Smoke Management System	1	1		<u>~</u>		
	 Basements 	,	70 -1	Exhaust fans			
	 Upper flcors 		30 a/c per	are Provided	MR		
		Marie Control of the	hour M	afciral Ventilation	The second section is a second section of the second section of the second section is the second section of the second section of the second section section is a second section of the second section		
			August and a second a second and a second and a second and a second and a second an	yara venniahop	MR	į.	

		Property of the second		
		12 a/c per hour	•	
	Fire Extinguishers			
	* Total numbers	four at each floor		
	• Types	Co, WCo, ABC	Provided	MR
	IS marking	ISI marked	- 00,-	MR
6.	First-Aid Hose Reels	DEMINISTRA	1SI Marked	MR
	 Total numbers on each floor 	One		
	 Length of hose reel hose 	30 m	Provided	MR
	Nozzle diameter	5 mm	-do-	MR
7.	Automatic fire detection and alarming	311111	- clo: -	MR
	Type of detectors	system		
	 Location of Main Panel 		-	+1
	 Location of Repeater Panel 	-	-	~
	 Alternate source of power 	-		+
	Hooters' Location	-	D.G. Set of 62.5 KVA	MR
8.	MOEFA			-
9.	Public Address System	Required	Provided	MR
10.	Automatic Sprinkler System	-do-	-do-	NIR
	Basement			
	Upper Floor	Required.	Provided	MR
11.	 Sprinkler above false ceiling Internal Hydrants 			-
	The second secon		'	
	arec of tiselydown-comer			
	realinger of rigurants per floor			
12.	 Hose Box Yard Hydrants 	•	•	
		Y	j.	
	Total number of hydrantsHose Box	-		
13.	Pumping Arrangements		-	
	Ground Level			
	Discharge of main Pump		-	Name of the last o
	Head of Main pump	•	-	
	Number of main pumpsJockey Pump out put			
	Jockey pump head			
	> Standby Pump out put			
	Standby Pump Head			
	Auto Starting/Manual	-	4 4	-
	stopping			

2121, Bank Street, Karol Bagh, New Delli-05.

	, by,			
	Pump House Access			
	 Terrace level 		-	
	Discharge of pump	450 LPM	1.0	
	Head of the pump	130 LPM	450 LPM	MR
	· ower supply	30 M Required	30M	MR
	Auto Starting of pump	Requirea	Provided	MR
14.	The state of Storage for fire fighting	ng		
	 Underground tank capacity 	B77		
	onnection connection			•
	Fire service inlet			
	Access to tank		57	-
	 Overhead Tank capacity 	Name of the last o		-
			5000 Ctr	MR COIDC
15.	Exit Signage.	Required	Provided	MR
16.	Provision of Lifts.			
	 Pressurization of Lift Shaft 			
	 Pressurization of Lift lobby 		Name of the last o	
	 Communication In lift Car 		-	-
	 Fireman's Grounding Switch 		Provided	MR
	 Lift Signage 	Required	- do -	
		-do -	-do-	MR
17.	Standby power supply	Required -do- Required	Provided	MR
18.	Def		, , , , , ,	MR
10.	Refuge Area.			
	Total Area			
	Location		*	
	(-	_	
			The state of the s	
19.	Fire Control Room			
19.				8
19.	 Detector System Panel 	-		
19.	Detector System PanelFlow Switch Panel	1		
19.	 Detector System Panel Flow Switch Panel PA System Panel 	\(\tag{\frac{1}{2}} \)		
19.	 Detector System Panel Flow Switch Panel PA System Panel Batter backup 	Required	Paristad	
19.	 Detector System Panel Flow Switch Panel PA System Panel Batter backup 	Required	Provided	- MR
0.	 Detector System Panel Flow Switch Panel PA System Panel Batter backup Building Floor Plans 	Required	Provided	- MR
0.	 Detector System Panel Flow Switch Panel PA System Panel Batter backup 	Required	Provided	MR -

The fire protection systems provided in the building were test checked and found functional at he time of inspection.

ceping in view the above substantial compliance of the minimum standards on fire prevention Fire Safety measures required under the rules it is recommended to grant Fire Safety ertificate under rule 35 of Delhi Fire Service Rules 2010/ issue shortcomings as noted at serial

Note: - The forth floor is used by the owner for personeluse (04 Rooms), hence only 28 Guest rooms are recommended i.e. 07 Guest rooms at first floor, Elven (11) Guest rooms for second floor and 10 Guest rooms at third floor as per MCD letter dated 30:05.2009 and D.C.P letter dated 25:06:12 are placed in the file. One alternate staircase also provided from first floor to ferrace having width 68 cmp.

Signature of insplants Mills

Designation ABBH. Divisional Officer

Signature of Inspecting Officer

Name

Designation

